



Home and Stucco Inspection

for

Lisa Miller

585 Croydon Lane
Alpharetta, GA 30022



Inspected By:

John Miller

Home and Stucco Inspections, Inc.

HOME AND STUCCO INSPECTION REPORT

HOME AND STUCCO INSPECTIONS, INC.

Peachtree Corners, Georgia 30092
Phone:(770)246-9448 Fax:(770)242-5979

Brief Description of the Subject Structure

This two-story wood framed structure is a single-family residence, constructed in the year circa 1994. It has a two-car attached garage; an asphalt shingle and metal roof; hardcoat stucco cladding w/EIFS trim accents and a poured concrete foundation enclosing the unfinished basement. The front of the home faces Southwest.

Address of Subject Property:

585 Croydon Lane
Alpharetta, GA 30022

Copy to:

Andrea Cueny

Inspected for:

Lisa Miller

Inspected by:

John Miller
Home and Stucco Inspections, Inc.

Fee \$700.00 (home/stucco) + \$175.00 (radon) =
\$875.00

Paid **\$875.00**

AMEX **Paid in full**
(xxxx1007)

Dated 08/07/2020

Billed Date N/A

Inspection Date 08/07/2020

Time Started 9:00 AM

Weather Partly Cloudy

Temperature 78 degrees

Recent Weather Rain in the last week

Scope of Inspection: Per your request, the subject property; i.e., the grounds, exterior surfaces visible from ground, garage, carport, structure, attic, basement, crawl space, electrical system, heating system, air conditioning system, plumbing, fireplace, built-in appliances have been visually inspected if present, and major installed systems and components are described. This report, intended to provide you with a better understanding of the condition of the property, reflects our observations and opinions at the time of the inspection and no warranty is expressed or implied. **If this inspection report is received and/or used by the Client, the conditions of this Scope of Inspection are agreed to by the Client.** This inspection and resultant report is conducted and prepared in accordance with the applicable laws of the State of Georgia and the Inspection Standards of the American Society of Home Inspectors. The inspector is not required to: walk on roof; activate utilities; activate systems or equipment that are shut down; report on or evaluate systems or components life expectancy, adequacy, efficiency, or cause of the need to repair; observe items or areas if concealed or not readily accessible; evaluate suitability for any specialized use or conformance to any previous or present regulatory requirements or building codes; or evaluate the present or future market value or marketability of the property. Unless specifically agreed upon and reported on, no inspection or evaluation was made concerning any environmental conditions, soil or geological conditions, recreational facilities, outbuildings, alarms, communication systems, pools, spas, irrigation systems, sewage disposal systems; the presence or absence of pests, wood destroying organisms, mold, fungi, or possible hazardous materials or conditions. **In the event that Home and Stucco Inspections, Inc. or its inspectors are found liable for any errors or omissions, the total value of all claims per subject property are limited to the amount of the inspection fee paid.**

Notice to Client: Those items marked in the "See Summary" column of this report may be acceptable to you when considering the intended use and / or value of the property. This report generally excludes those items which are considered purely cosmetic in nature, but in some instances may be mentioned in the "Summary" section for clarification or maintenance purposes. If references are made to building codes or other standards, these are made in an effort to clarify the issue, and are not intended to infer a building code violation, since Home and Stucco Inspections, Inc. is a private corporation, not a regulatory or policing agency. If any estimates of repair costs or methods of repair were provided, these are only to be considered as rough "ballpark" estimates or methods, not quotations, since Home and Stucco Inspections, Inc., does not perform repairs. Prices and methods of repair may vary depending upon the contractor, engineer, or architect selected.

LEGEND:

"X" IN THE "**Satisfactory**" COLUMN INDICATES THE ITEM APPEARS INSTALLED ACCEPTABLY AND IS FUNCTIONING.

"X" IN THE "**See Summary**" COLUMN INDICATES THE ITEM APPEARS INSTALLED UNACCEPTABLY, BROKEN OR NOT FUNCTIONING AND NEEDS CORRECTION, FURTHER ACTION, OR CLARIFICATION.

ALSO:
THE CONVENTION USED TO IDENTIFY LOCATIONS, BOTH INSIDE AND OUTSIDE, IS TO ASSUME YOU ARE STANDING IN THE FRONT YARD LOOKING AT THE FRONT OF THE STRUCTURE; RELATIVE LOCATIONS WILL BE FRONT, REAR, LEFT AND RIGHT.

Section A

OUTSIDE GROUNDS

Item #	Satisfactory	See Summary	ITEM <<----- COMMENTS ----->>
A01	_____	X	Drainage & Grading (as affect building) NOTE: Soil grading is to be installed and maintained sloping downward from the foundation such that water will flow away from the building. In addition, since soil and mulch contain moisture, it needs to be eight (8) inches minimum below the bottom sill or wood framing members or at least six (6) inches below the siding.
A02	_____	X	Trees, Shrubs, and other Vegetation (as affect building) NOTE: Trees or bushes growing too close or hanging over the house can cause damage to the foundation, siding or roof. Large trees within ten (10) feet of the house should be considered for removal; others need to be trimmed away from contact with the house, and should be clear for at least 18 inches around and four (4) feet above the exterior air conditioning equipment.
A03	X	_____	<u>Retaining Walls</u> <input type="checkbox"/> none (as affect building) <input checked="" type="checkbox"/> concrete <input type="checkbox"/> treated timber
A04	_____	X	Driveway <input type="checkbox"/> concrete <input type="checkbox"/> asphalt <input type="checkbox"/> gravel or dirt <input type="checkbox"/> brick or pavers <input checked="" type="checkbox"/> settling cracks
A05	X	_____	<u>Walks</u> <input checked="" type="checkbox"/> concrete <input type="checkbox"/> brick <input type="checkbox"/> none <input type="checkbox"/> typical cracks <input type="checkbox"/> other: _____
A06	X	X	<u>Patios, Stoops & Steps</u> <input checked="" type="checkbox"/> front <input checked="" type="checkbox"/> right & rear <input checked="" type="checkbox"/> stone/concrete <input checked="" type="checkbox"/> void in soil <input type="checkbox"/> none <input type="checkbox"/> typical cracks
A07	X	_____	<u>Fences</u> <input type="checkbox"/> chain link <input checked="" type="checkbox"/> wood <input type="checkbox"/> none

Section B

STRUCTURE EXTERIOR

Item #	Satisfactory	See Summary	ITEM	COMMENTS
--------	--------------	-------------	------	----------

NOTE: Normal observation of exterior surfaces is from the ground using binoculars, as necessary. Inspector is not required to walk on roof nor to observe surfaces of chimneys, vents, roof or walls not visible from the ground. In addition, accessories, such as antennae, solar systems, lightning arresters, etc., are not included as part of this inspection.

ALSO: Per the scope of this inspection, this is a visual inspection, which may not detect concealed moisture conditions which could cause or be causing damage to the interiors of the walls, floors or ceilings.

			<u>Roof Style</u>	<input checked="" type="checkbox"/> gable	<input checked="" type="checkbox"/> hip	<input type="checkbox"/> shed	<input type="checkbox"/> mansard	<input checked="" type="checkbox"/> other: conical
			<u>Roof Pitch</u>	<input checked="" type="checkbox"/> steep	<input type="checkbox"/> medium	<input type="checkbox"/> low	<input type="checkbox"/> flat	
			<u>Estimated Layers of Roofing Shingles</u>	<input checked="" type="checkbox"/> one	<input type="checkbox"/> two	<input type="checkbox"/> not determined		
			<u>Method of Observation</u>	<input checked="" type="checkbox"/> binoculars from ground – about 80% of the roof surface is visible and observed from the ground				
			<u>Estimated Age:</u>	10 yrs. +/-				
				<input checked="" type="checkbox"/> from ladder	<input type="checkbox"/> walked on roof	<input type="checkbox"/> from interior		
B01	X	X	<u>Roofing Materials</u>	<input checked="" type="checkbox"/> asphalt shingle	<input checked="" type="checkbox"/> metal	<input type="checkbox"/> other:		
B02		X	<u>Visible Flashings</u>					
B03	X	X	<u>Fireplace Chimneys/ Chimney Caps</u>	<input type="checkbox"/> metal vent	<input type="checkbox"/> masonry	<input checked="" type="checkbox"/> framed	<input type="checkbox"/> none	
B04		X	<u>Vents & Skylights</u>					
B05	X	X	<u>Eaves, Soffits, Fascia & Exterior Trim</u>					
B06		X	<u>Moisture/Insect Damage</u>					
B07		X	<u>Gutters & Downspouts</u>	<input type="checkbox"/> none				
B08		X	<u>Splashblocks, Extensions & Drains</u>	<input type="checkbox"/> none				
B09	X	X	<u>Walls (exterior cladding)</u>	<input checked="" type="checkbox"/> stucco (hardcoat)	<input checked="" type="checkbox"/> EIFS (synthetic stucco)	<input type="checkbox"/> brick	<input type="checkbox"/> wood	<input type="checkbox"/> composition
				<input type="checkbox"/> vinyl	<input type="checkbox"/> other:			
B10	X		<u>Door & Window Frames</u>					
B11			<u>Decks, Balconies & Porches</u>	<input checked="" type="checkbox"/> none	<input type="checkbox"/> bolted	<input type="checkbox"/> open deck flashed		
B12	X		<u>Stairs & Railings</u>	<input type="checkbox"/> none				
B13	X	X	<u>Paint/Caulking/Sealants</u>					

Section C

GARAGE & CARPORT

Item #	Satisfactory	See Summary	ITEM	COMMENTS
--------	--------------	-------------	------	----------

C01	X	X	<u>Ceiling & Walls</u>	<input checked="" type="checkbox"/> garage	<input type="checkbox"/> carport	<input type="checkbox"/> outside parking
C02	X		<u>Floor</u>	<input checked="" type="checkbox"/> typical cracks		
C03	X		<u>Door & Frame</u>	<input checked="" type="checkbox"/> car	<input type="checkbox"/> vehicle doors	
C04	X		<u>Opener(s)</u>	<input type="checkbox"/> none		
C05	X		<u>Safety Reverse</u>			

Section D

FOUNDATION & BASEMENT

Item #	Satisfactory	See Summary	ITEM	COMMENTS
--------	--------------	-------------	------	----------

NOTE: Under-floor crawl spaces will be entered except when access is obstructed, property could be damaged by entry, or when dangerous or adverse conditions are suspected.

D01	X		<u>Foundation</u> <input checked="" type="checkbox"/> concrete <input type="checkbox"/> concrete block <input type="checkbox"/> slab <input checked="" type="checkbox"/> typical cracks <input type="checkbox"/> other: _____	
			<u>Basement</u> <input type="checkbox"/> none	Approximately 0% finished, this section of items below addresses only the <u>unfinished</u> areas
D02	X		<u>Walls & Sills</u>	
D03	X		<u>Sub-floor</u> <input type="checkbox"/> not visible	
D04	X		<u>Insulation</u> <input type="checkbox"/> under floor <input checked="" type="checkbox"/> walls <input type="checkbox"/> sills <input type="checkbox"/> none noted	
D05	X		<u>Floor Structure</u> <input checked="" type="checkbox"/> joists & beams <input type="checkbox"/> wood I-joists <input type="checkbox"/> Trusses <input type="checkbox"/> other: _____	
D06		X	<u>Posts & Piers Material</u> <input checked="" type="checkbox"/> 2x6 walls <input type="checkbox"/> metal <input type="checkbox"/> wood posts	
D07	X		<u>Floor</u> <input checked="" type="checkbox"/> concrete <input type="checkbox"/> dirt <input checked="" type="checkbox"/> typical cracks	
D08		X	<u>Evidence of Moisture/Microbial Growth</u> Not active – water-proofing system	
			<u>Crawl Space</u> <input checked="" type="checkbox"/> none	
D09			<u>Entry Location:</u> _____ <input type="checkbox"/> entered <input type="checkbox"/> access limited	
D10			<u>Walls & Sills</u>	
D11			<u>Sub-floor</u> <input type="checkbox"/> not visible	
D12			<u>Insulation</u> <input type="checkbox"/> under floor <input type="checkbox"/> walls <input type="checkbox"/> sills <input type="checkbox"/> none noted	
D13			<u>Floor Structure</u> <input type="checkbox"/> joists & beams <input type="checkbox"/> wood I-joists <input type="checkbox"/> trusses <input type="checkbox"/> other: _____	
D14			<u>Posts & Piers Material</u> <input type="checkbox"/> concrete block <input type="checkbox"/> concrete <input type="checkbox"/> wood posts	
D15			<u>Ventilation</u>	
D16			<u>Vapor Barrier</u> <input type="checkbox"/> none <input type="checkbox"/> poly <input type="checkbox"/> concrete	
D17			<u>Floor</u> <input type="checkbox"/> concrete <input type="checkbox"/> dirt	
D18			<u>Evidence of Moisture/Microbial Growth</u>	

Section E

ATTIC

Item #	Satisfactory	See Summary	ITEM	COMMENTS
--------	--------------	-------------	------	----------

NOTE: Attic spaces will be entered except when access is obstructed, property could be damaged by entry, or when dangerous or adverse conditions are suspected.

E01	X	X	<u>Access Locations:</u> Master Bedroom Closet / Upstairs Hallway <input checked="" type="checkbox"/> entered <input type="checkbox"/> access limited <input type="checkbox"/> none <input checked="" type="checkbox"/> pull-down <input type="checkbox"/> ceiling scuttle <input checked="" type="checkbox"/> wall entry <input type="checkbox"/> walk-up <input type="checkbox"/> walk-in	
E02		X	<u>Insulation Type</u> <input checked="" type="checkbox"/> loose fill <input checked="" type="checkbox"/> batt or roll <input type="checkbox"/> other _____ Flat Ceiling Estimated Average Depth: 8-10 inches Estimated R-value: 19-26	
E03	X		<u>Framing</u> <input type="checkbox"/> trusses <input checked="" type="checkbox"/> rafters & joists	
E04	X		<u>Ventilation</u> <input type="checkbox"/> fan(s) <input checked="" type="checkbox"/> turbine <input type="checkbox"/> gable <input checked="" type="checkbox"/> soffit <input type="checkbox"/> ridge	
E05		X	<u>Evidence of Rodents/Pests</u> <input checked="" type="checkbox"/> carcass <input type="checkbox"/> droppings <input checked="" type="checkbox"/> trampled insulation	
E06		X	<u>Evidence of Moisture/Leaks</u>	

Section F

KITCHEN & APPLIANCES

Item #	Satisfactory	See Summary	ITEM	COMMENTS
F01	X		<u>Cook</u>	<input checked="" type="checkbox"/> top <input type="checkbox"/> stove <input checked="" type="checkbox"/> gas <input type="checkbox"/> electric
F02	X		<u>Oven(s)</u>	<input type="checkbox"/> part of stove <input checked="" type="checkbox"/> built-in
F03	X		<u>Vent</u>	<input type="checkbox"/> recirculating <input checked="" type="checkbox"/> vented <input type="checkbox"/> none
F04			<u>Microwave</u>	<input type="checkbox"/> built-in (tested only to heat water) <input checked="" type="checkbox"/> not installed
F05	X		<u>Refrigerator</u>	<input type="checkbox"/> not installed
F06			<u>Compactor</u> (appears to cycle)	<input checked="" type="checkbox"/> none
F07	X		<u>Sink & Faucet</u>	
F08	X		<u>Sink Sprayer</u>	<input type="checkbox"/> none
F09	X		<u>Disposal</u> (runs & drains)	<input type="checkbox"/> none
F10	X		<u>Dishwasher</u> (cycles)	<input type="checkbox"/> none
F11			<u>Other:</u>	

Section G

GENERAL INTERIOR

Item #	Satisfactory	See Summary	ITEM	COMMENTS
G01		X	<u>Doors</u>	
G02		X	<u>Windows/ Screens</u>	<input type="checkbox"/> single pane <input checked="" type="checkbox"/> thermal pane <input type="checkbox"/> metal <input checked="" type="checkbox"/> wood <input type="checkbox"/> vinyl
G03		X	<u>Floors</u>	
G04	X		<u>Walls</u>	
G05		X	<u>Ceilings</u>	
G06	X	X	<u>Stairs & Railings</u>	<input type="checkbox"/> none
G07		X	<u>Cabinets</u>	
G08	X		<u>Countertops</u>	

NOTE: If this is an occupied home, floors, walls, windows, closets, cabinets, etc. may not be completely visible due to furnishings and other personal items which may not be moved by the inspector. Per the scope of inspection, this inspection is performed on an "as visible" basis.

Section H

ELECTRICAL

Item #	Satisfactory	See Summary	ITEM <<-----	COMMENTS ----->>>
H01	X		<u>Service Location</u>	<input type="checkbox"/> overhead <input checked="" type="checkbox"/> underground <input type="checkbox"/> front <input type="checkbox"/> right side <input type="checkbox"/> rear <input checked="" type="checkbox"/> left side
H02	X		<u>Meter Location</u>	<input type="checkbox"/> front <input type="checkbox"/> right side <input type="checkbox"/> rear <input checked="" type="checkbox"/> left side
H03	X		<u>Main Disconnect Location</u>	<input type="checkbox"/> inside <input type="checkbox"/> front <input type="checkbox"/> right side <input type="checkbox"/> rear <input checked="" type="checkbox"/> left side Service Disconnect Amperage Rating: <input type="checkbox"/> 100 <input type="checkbox"/> 125 <input type="checkbox"/> 150 <input checked="" type="checkbox"/> 200 Service Voltage: 120/240 <input type="checkbox"/> 100 <input type="checkbox"/> 125 <input type="checkbox"/> 150 <input checked="" type="checkbox"/> 200 Service Amperage: Service Conductor Material: <input checked="" type="checkbox"/> aluminum <input type="checkbox"/> copper
H04	X		<u>Grounding Location</u>	<input type="checkbox"/> water line <input type="checkbox"/> front <input type="checkbox"/> right side <input type="checkbox"/> rear <input checked="" type="checkbox"/> left side
H05	X		<u>Distribution Panel Location</u>	<input type="checkbox"/> garage <input checked="" type="checkbox"/> basement <input type="checkbox"/> hall <input type="checkbox"/> other: _____
H06	X		<u>Branch Circuits</u>	<input checked="" type="checkbox"/> 120 volt <input type="checkbox"/> 240 volt
H07	X		<u>Branch Wiring</u>	<input checked="" type="checkbox"/> copper <input type="checkbox"/> aluminum (240 volt only)
H08		X	<u>GFCI/AFCI Protection</u>	<input type="checkbox"/> none, see Note below <input type="checkbox"/> none at kitchen, see Note below

Note: The GFCI reset for the exterior outlet on the left side of the front stoop is at the GFCI receptacle in the main floor bathroom. The GFCI reset for the exterior outlet above the right side of the patio on the back of the home is at the GFCI receptacle below the main electrical panel in the basement. The GFCI reset for the outlet in the rear wall of the garage is at the GFCI receptacle above the right sink in the master bathroom. The GFCI reset for the outlet in the mirror between the sinks in the master bathroom is at the GFCI receptacle in the front, center bedroom bath.

NOTE: Although they may not have been required at the time of construction or renovation and may be acceptable for age, GFCI-protected outlets or circuits are suggested for your safety at wet areas, such as: kitchen and bar counter outlets; bathrooms; hydro-massage tubs, garage, exterior, and unfinished basements and crawl spaces. New construction or renovated areas require GFCI protection at these locations.

Locations where GFCI-protected outlets are controlled

kitchen baths hydro massage tub
 garage exterior basement
 crawl space breaker(s) @ panel

Locations which are GFCI protected (yes/no)

kitchen baths garage exterior
 basement crawl space hydro massage tub

H09	X	X	<u>Receptacles/ Cover-plates:</u>	
H10	X	X	<u>Light Switches/ Fixtures/Ceiling Fans:</u>	
H11		X	<u>Smoke Detector(s)/ Carbon Monoxide</u>	<input type="checkbox"/> none <input checked="" type="checkbox"/> not tested, may be part of alarm
H12	X		<u>Exhaust Fan(s)</u>	<input type="checkbox"/> none
H13			<u>Whole House Fan</u>	<input type="checkbox"/> speed <input type="checkbox"/> timer <input checked="" type="checkbox"/> none
H14	X		<u>Doorbell</u>	<input type="checkbox"/> none

Section I

HEATING & AIR CONDITIONING

Item #	Satisfactory	See Summary	ITEM	COMMENTS
--------	--------------	-------------	------	----------

NOTE: If the exterior temperature is above 85 degrees F. or if the cooling system uses the same distribution system and is operating, the inspector is not required to activate heating, since this could cause damage to the equipment. If the exterior temperature is under 65 degrees F., or has been under 60 deg. F. during the last 24 hours, the inspector is not required to activate cooling, since this could cause damage to the equipment.

			<u>Heating System Installed Location(s)</u>	<input checked="" type="checkbox"/> attic	<input checked="" type="checkbox"/> basement	<input type="checkbox"/> garage
			Manufacturer or Brand:	Lennox (up) Lennox (mn)	Estimated Age:	10 yrs. 10 yrs.
			Model Number:	SL280UH070V36A-01 (up) SL280UH070V36A-01 (mn)	Serial Number:	5910L02231 5910L02220
			Fuel:	<input checked="" type="checkbox"/> gas <input type="checkbox"/> electric	<input type="checkbox"/> other:	
			Distribution Type:	<input checked="" type="checkbox"/> forced air	<input type="checkbox"/> other:	
I01		X	Condition:	<input type="checkbox"/> operated <input checked="" type="checkbox"/> visual inspection only, see Note above		
I02	X		Exhaust:			
I03		X	Operating Controls:	<input checked="" type="checkbox"/> operated only on cool		
I04		X	Distribution Equipment:			
I05		X	Filter(s):	<input checked="" type="checkbox"/> electronic <input type="checkbox"/> re-usable <input type="checkbox"/> disposable: size		

			<u>Air Conditioning Outdoor Locations</u>	<input type="checkbox"/> front	<input type="checkbox"/> right side	<input type="checkbox"/> rear	<input checked="" type="checkbox"/> left side
			Manufacturer or Brand:	Lennox (lft-mn) Lennox (rt-up)	Estimated Age:	10 yrs. 10 yrs.	
			Tonage:	2.5 ton (mn) 2.5 ton (up)	Serial Number:	5810K09819 5810K09138	
			Fuel:	<input checked="" type="checkbox"/> electric <input type="checkbox"/> other:			
I06	X		Condition:	<input checked="" type="checkbox"/> operated <input type="checkbox"/> visual inspection only			
I07	X		Condensate Lines & Pan:				
I08	X		Refrigerant Lines:				
I09	X		Temperature Differential	Unit 1 (mn) 16	Unit 2 (up) 17	Unit 3	
I10	X		Operating Controls:	<input type="checkbox"/> operated only on heat			
I11			Distribution and Filter Equipment (if separate from heating):			SEE "I04" and "I05"	

			<u>Fireplace Locations</u>	<input checked="" type="checkbox"/> family/living room	<input type="checkbox"/> basement	<input type="checkbox"/> bedroom	<input type="checkbox"/> none
			Firebox:	<input type="checkbox"/> not fully visible due to debris, ashes or gas logs			
I12	X		Flue:	<input type="checkbox"/> none needed	<input checked="" type="checkbox"/> not fully visible		
I13	X		Damper:				<input type="checkbox"/> none
I14	X		Gas Starter:	<input type="checkbox"/> none	<input checked="" type="checkbox"/> gas logs installed	<input type="checkbox"/> gas fuel only	
I15		X	Hearth:				
I16	X						

Section J

PLUMBING

Item #	Satisfactory	See Summary	ITEM	COMMENTS
			<u>Water Service</u>	
			Meter Location:	Meter near street
<p>NOTE: Per the scope of inspection, underground or buried systems are not included as part of this inspection. Therefore, the underground water service line from the meter to the building was not observed, and no representation is made as to the material and condition of such piping. You may wish to inquire with the owner about the material or any maintenance or repairs.</p>				
J01	X		Piping Entering House:	<input type="checkbox"/> plastic/polybutylene <input checked="" type="checkbox"/> copper <input type="checkbox"/> galvanized <input type="checkbox"/> not visible
			Cutoff Location:	Meter / Right, front corner of the basement ceiling
J02	X		Piping Visible in House:	<input type="checkbox"/> plastic/polybutylene <input checked="" type="checkbox"/> copper <input type="checkbox"/> galvanized <input type="checkbox"/> other: _____
J03	X	X	Water Pressure/ Water Spigots:	_____
			<u>Sewer Service</u> (see Note below)	
<p>NOTE: Per the scope of inspection, underground or buried systems are <u>not included</u> as part of this report and, therefore, the building sewer and disposal system was not inspected. If there is a possibility that this property has a private septic or cesspool, you may wish to inquire with the local Environmental Health Department to help determine the type of disposal system, location and description. If it is determined to have a private system, you may wish to inquire of the owner as to when the system was last pumped or serviced.</p>				
J04	X		Piping in House:	<input checked="" type="checkbox"/> plastic <input type="checkbox"/> cast iron <input type="checkbox"/> other: _____
J05			Sump or Sewage Pump (presence only – not operated)	<input checked="" type="checkbox"/> none noted
			<u>Gas or Fuel Service Type:</u>	<input checked="" type="checkbox"/> natural gas <input type="checkbox"/> L/P gas <input type="checkbox"/> oil <input type="checkbox"/> none
			<input type="checkbox"/> tank or <input checked="" type="checkbox"/> meter location:	<input type="checkbox"/> front <input type="checkbox"/> right side <input type="checkbox"/> rear <input checked="" type="checkbox"/> left side
J06	X	X	Piping / Sediment Traps	_____
			Water Heater(s)	<input checked="" type="checkbox"/> gas <input type="checkbox"/> electric
			Location:	<input type="checkbox"/> attic <input checked="" type="checkbox"/> basement <input type="checkbox"/> garage
			Manufacturer or Brand:	GE Estimated Age: 7 yrs.
			Size:	50 gallons Serial #: GELNA341306901 Model #: SG50T12AVG00
J07	X		Condition:	_____
J08	X		Exhaust:	_____
J09	X	X	Relief Valve / Thermal Expansion Tank:	_____
J10		X	<u>Laundry Area:</u>	<input checked="" type="checkbox"/> 240 volt (3-prong) <input type="checkbox"/> gas <input checked="" type="checkbox"/> vent available for dryer
J11	X	X	<u>Sinks, Faucets, Showerheads & Valves:</u>	_____
J12		X	<u>Commodes:</u>	_____
J13		X	<u>Tubs/Whirlpool:</u>	_____
J14		X	<u>Caulking/Grouting</u>	_____
J15	X	X	<u>Stall Shower / Shower Door:</u>	<input type="checkbox"/> none <input checked="" type="checkbox"/> tile floor <input type="checkbox"/> fiber-glass or plastic floor

John Miller, Inspector
 Certified ASHI Member #204047
 Registered & Certified by SBCCI, One and Two-Family Dwelling Inspector, #4741
 ICC Residential Combination Inspector #5188792-R5
 EDI Certified EIFS and Stucco Inspector, #GA-17

****SUMMARY // DEFECTS PAGES ****

All references assume you are facing the home from the street.

MAJOR CONCERNS

(ITEMS THAT HAVE FAILED OR HAVE POTENTIAL OF FAILING SOON)

1. Evidence of rodent activity was visible in the attic areas of the home (trampled/damaged insulation and a rodent carcass). Please consult with the homeowner about this issue. A construction gap was present between the fascia board and the roof decking at the bottom of the roof valley located above the garage door and a rodent access hole was present above the gable return in the left, front corner of the upper attic (see photos). A squirrel carcass was also present in the insulation in the left, front corner of the upper attic (see photo). A qualified rodent exclusion contractor should evaluate these areas and seal as needed. The rodent carcass should be removed and the perimeter of the roof evaluated for construction gaps between the fascia boards and the roof decking and sealed with metal flashing to prevent future rodent entry. The rodent issue should then be monitored in the future.
2. The thermo seal appears to have failed inside the glass in the fixed window located above the exterior French doors in the rear wall of the family room (1), in the upper piece of glass in the right window in the front wall of the garage (1), in the lower piece of glass in the right window in the right wall of the master bedroom (1), in the center bay window in the left, front bedroom (1) and in the lower piece of glass in the window located in the front wall of the upper attic (1) - (the glass is fogged). A qualified contractor should evaluate the glass in these windows and replace as needed.
3. A large void was present in the soil below the rear portion of the front stoop (see photo). A qualified foundation repair contractor should evaluate this issue and repair as needed to prevent future settlement of the stoop.
4. There was no water pressure at the showerhead in the master bathroom and the faucet handle inside the shower stall does not adjust properly. A licensed plumber or qualified contractor should evaluate these issues and repair as needed.
5. There was a sign on the commode in the jack and jill bathroom stating "do not use". Please consult with the homeowner about the operation. If needed, a licensed plumber or qualified contractor should evaluate and repair as needed.
6. A qualified contractor should install the missing insulation in the rear wall and replace the rodent damaged batt insulation in the left wall of the knee wall portion of the attic located off the right wall of the master bedroom closet (see photos).
7. The blown-in insulation in the floor of the upper attic has been trampled in various areas from previous rodent activity (see photo for example). A qualified contractor should evaluate and re-insulate as needed to help increase efficiency. Current standards require a minimum R-value of 30 (i.e. 11-12" of blown-in insulation).
8. The shingle is cracked at the gable peak located above the window in the front wall of the foyer (see photo). Moisture stains were present on the roof decking above the chimney chase in the back, left corner of the upper attic and on the roof decking above the bay windows in the rear wall of the master bedroom (see photos). A licensed roofer should replace the cracked shingle and evaluate the shingles above the moisture stains and the flashing around the chimney chase and address as needed.

ITEMS NOT OPERATED/OPERATING

1. Did not test the furnaces due to the outside temperature and the a/c units being in operation before and during the inspection.
2. Did not evaluate the security system in the home or the irrigation system in the yard. Please consult with the homeowner about the operation.
3. The exterior water spigot located below the windows in the right wall of the kitchen was winterized prior to the start of the inspection – did not test. The shut-off valve on the waterline attached to this spigot is located inside the cabinet below the kitchen sink. Please consult with the homeowner about the operation.
4. The bulb(s) appears to be burned-out in the under-cabinet light located above the rear countertop in the kitchen, in the exterior light fixture outside the exterior French doors in the left wall of the basement and in the light fixture on the ceiling of the mechanical room in the basement – ensure these fixtures are operable.
5. The control dial for the gas logs in the fireplace does not adjust properly and as a result the pilot light for the gas logs could not be lit. A qualified contractor should evaluate and repair as needed and ensure the gas logs are operable.
6. Install the missing drain-stop inside the tub in the front, center bedroom bathroom.
7. Adjust the left cabinet door below the front sink in the jack and jill bathroom so that it stays closed.

POTENTIAL SAFETY/HEALTH HAZARDS

1. For added safety, a GFCI receptacle(s) should be installed at the outlet in the front wall of the laundry room and at the (3) outlets located above the countertop on the right side of the range in the kitchen.
2. Approximately (50-60%) of the windows in the home appear to be painted shut which may present a safety hazard in the event of an emergency – ensure all windows are operable.
3. The glass in the left window located above the whirlpool tub in the master bathroom does not appear to be tempered-safety glass (labels are not visible on the glass).
4. Recommend installing a carbon monoxide detector on the main floor and upper level of the home.
5. Replace the batteries in the smoke detectors on a yearly basis and recommend installing a smoke detector in each bedroom.
6. Replace the cracked spindle in the railing on the right side of the stairwell located in the right, front corner of the family room and in the railing at the top of the stairwell in the foyer (see photos).
7. A chain is embedded in the lower portion of the pine tree located on the right side of the backyard and it appears that this tree was struck by lightning in the past (see photo)? Recommend having this tree evaluated by a certified arborist to ensure that's it's healthy.
8. The excessive height between the threshold and the stone step outside the exterior French doors in the rear wall of the family room presents a possible trip hazard (see photo). A qualified contractor should evaluate this issue and address as needed.
9. Secure the loose valance covering the blind above the center bay window in the formal living room.
10. Install the missing globe over the light fixture located above the stairwell to the basement.

11. Install the missing cover-plate over the light switch located at the top and bottom of the stairwell to the basement.
12. The dead-bolt lock in the front door does not latch completely. A qualified contractor should evaluate and adjust as needed.
13. Recommend having the inside of the hvac ductwork cleaned by a licensed hvac contractor.
14. Please consult with the homeowner about the maintenance schedule for the electronic filters on the hvac systems.
15. The insides of the jets/waterlines in the whirlpool tub should be cleaned prior to use and as part of routine maintenance.
16. Cockroach droppings were present on the flooring inside the knee wall portions of the attic located off the right and left walls of the master bedroom closet. Recommend having the home treated for insects by a licensed Exterminator.
17. Tighten the hardware on the pull-down stairs to the attic.
18. A thermal expansion tank is missing on the cold waterline above the water heater (required when the water heater was replaced). A licensed plumber or qualified contractor should evaluate and install as needed.

DEFERRED COST ITEMS

ITEMS THAT HAVE REACHED OR ARE REACHING THEIR NORMAL LIFE EXPECTANCY OR SHOW INDICATIONS THAT THEY MAY REQUIRE REPAIR OR REPLACEMENT ANYTIME **WITHIN THE NEXT FIVE (5) YEARS.**

None

ADDITIONAL COMMENTS

1. Trim the tree limbs away from the window in the front wall of the master bedroom closet as needed and as part of routine maintenance.
2. Negative grading was present in the soil outside the front wall of the formal dining room and a basin was present in the soil on the right side of the stone steps outside the exterior door in the laundry room, which will contribute to water accumulation in these areas during rains (**see photos**). Recommend having these areas evaluated by a qualified landscaping contractor.
3. Recommend sealing the settling cracks in the driveway near the sidewalk at the right, front corner of the home to help prevent future soil erosion below the concrete.
4. The insides of the gutters and downspouts should be cleaned prior to closing as part of routine maintenance (**see photo for example**).
5. Recommend adjusting and installing a longer elbow on the bottom of the downspout located on the left side of the garage door to help divert water away from the foundation and stucco system.
6. Recommend installing a longer extension on the bottom of the downspout located on the right side of the stone steps outside the exterior door in the right wall of the laundry room to help prevent future soil erosion below these steps.
7. The lower portion of the downspout has been taped above retaining wall at the left, front corner of the home due to this section of the downspout being rusted (**see photo**). A qualified contractor should evaluate and replace this section of the downspout.

8. A qualified contractor should secure the downspout to the EIFS system on the right side of the bay windows at the left, front corner of the home and ensure the downspout straps penetrating the EIFS system are sealed with caulking (see photo).
9. Secure the buried extension to the bottom of the downspout located below the right, front corner of the formal living room and at the back, right corner of the home to help divert water away from the foundation walls.
10. Replace the damaged downspout extension at the back, left corner of the home to help prevent water accumulation along the foundation wall (see photo).
11. Ponding water was present inside the rear portion of the gutter located above the garage door due to an inadequate pitch of this gutter towards the downspout. A qualified contractor should adjust this gutter and apply caulking along the top of this gutter to help prevent overflow and moisture damage to the fascia board (see photo).
12. Caulking should be applied along the top of the gutters located below the gable returns on the front of the home to help prevent future moisture damage to the fascia boards (see photo for example).
13. Seal the open joint in the sill below the left window in the front, center bedroom to prevent future moisture entry (see photo).
14. Secure the upper portion of the shutter on the right side of the window in the front wall of the master bedroom closet.
15. The upper sash is displaced in the window located in the front wall of the attic (see photo). A qualified contractor should evaluate and repair as needed to help prevent future moisture/insect entry.
16. The metal furnace flues and the metal chimney cap located on top of the chimney chase should be painted with a rust-inhibiting paint.
17. A qualified contractor should install the missing venthood over the vent for the downdraft exhaust fan located below the rear wall of the kitchen and over the dryer vent located outside the rear wall of the laundry room (see photos).
18. Moisture damage was present at the brick mould above the left side of the left window in the guest bedroom (main floor) and at the bottom of the brick mould on the left side of the left window in the back, left bedroom (see photo). A qualified contractor should evaluate and replace the damaged wood as needed.
19. Minor moisture damage was present on the interior frame below the upper piece of glass in the right window in the formal dining room (see photo). A qualified contractor should evaluate and repair the damaged wood as needed.
20. Screens were not installed on the windows in the home at the time of the inspection.
21. There appears to be inactive moisture stains on the rear portion of the garage ceiling (see photos). Please consult with the homeowner about previous plumbing leaks in these areas.
22. Install the missing strike-plate for the lock located above the left side of the right exterior French door in the rear wall of the family room.
23. Moisture damage was present on the cabinet shelving below the kitchen sink and below the right sink in the master bathroom, which is cosmetic in nature (see photos). Please consult with the homeowner about previous plumbing leak(s) in these areas – replace the damaged shelving as desired.
24. Note: The light fixture was installed at the angle above the sink in the main floor bathroom, above the front sink in the jack and jill bathroom and above each sink in the master bathroom – adjust as needed.

25. The weather-stripping is damaged below the front door and between the exterior French doors in the left wall of the basement. A qualified contractor should evaluate and replace the weather-stripping as needed to help increase efficiency.
26. Inactive moisture stains were present on the ceiling of the rear closet in the back, left bedroom, which may be related to gutter overflow (see photo)? Please consult with the homeowner about these stains – re-paint and monitor in the future during rains.
27. Daylight is visible below the right and left sides of the right window in the back, left bedroom when this window is in the closed position. A qualified contractor should evaluate and seal as needed to help increase efficiency.
28. Re-apply the caulking along the corners of the tile above the tub in the main floor bathroom.
29. The right door to the master bathroom opens by itself and the left door does not stay open – adjust as needed.
30. Install the missing strike-plate on the side of the hallway door to the front, center bedroom.
31. A ridge was present in the center portion of the tiled floor in the master bathroom which has caused a hairline crack in the floor tiles (see photo). This does not appear to be related to a structural issue – monitor in the future.
32. Hairline cracks were present in the tiles around the drain in the floor of the master shower stall, which is mainly cosmetic in nature (see photo).
33. The grouting should be re-glazed between the tiles inside the master shower stall.
34. The cultured marble panel is cracked below the left side of the whirlpool tub in the master bathroom, which is cosmetic in nature.
35. Scratches and grouting was present on the enamel inside the tub in the jack and jill bathroom, which is cosmetic in nature.
36. Secure the raised escutcheon plate around the waterline located below the left side of the commode in the front, center bedroom bathroom.
37. Recommend having the hvac systems serviced by a licensed hvac contractor prior to closing.
38. A sediment trap is missing on the gas line entering the main floor furnace (see photo). A licensed hvac contractor should install the missing trap.
39. A vibration was present from the metal grate attached to the hvac supply vent located above the whirlpool tub in the master bathroom when air was passing through this vent. A licensed hvac contractor should evaluate and repair as needed.
40. Recommend installing an insulated foam panel behind each of the access doors to the knee wall portions of the attic in the master bedroom closet and an insulated boot or cover above the pull-down stairs to the attic to help increase efficiency in the home.
41. A water-proofing system has been installed along some of the foundation walls in the basement. Please consult with the homeowner about previous moisture entry and possible warranty information from the contractor who installed the system (Basement Systems).
42. There appears to be past termite trails on the rigid foam wall sheathing located above the lower step-down in the foundation in the back, left corner of the basement (see photo). Please consult with the homeowner about this issue and previous termite activity.

43. A qualified contractor should re-install the wall studs and sill plate along the lower step-down in the foundation in the back, left corner of the basement and the wall stud and sill plate along the foundation behind the main floor furnace in the basement (see photos). The lower portion of these studs were removed to install the water-proofing system.
44. The light fixture in the front, center room in the basement was turned-on prior to the start of the inspection. However, a switch could not be located for this fixture. Please consult with the homeowner about how you turn-off this light? If needed, a licensed electrician or qualified contractor should evaluate and replace this fixture with a fixture that has a pull-string.

Stucco: A visual inspection was conducted on the stucco system that was applied to the exterior of this home. The system on the home is hardcoat stucco which consists of Portland cement, lime and sand. These ingredients are typically field mixed with water and trowelled onto metal lath. The grey trim accents are made from EIFS (Exterior Insulation Finish System) or more commonly referred to as "synthetic stucco" and have been applied over the hardcoat stucco system. Foam wall sheathing was installed behind the hardcoat stucco system where visible, which should not be confused with EIFS. Header flashing was installed above the windows and doors, Raintek kick-out flashing has been installed in the stucco system at the primary roof termination located above the right side of the bay window cavity in the left, front bedroom (see photo), expansion joints were installed along the floorlines in the stucco system and the windows, doors, utility boxes/penetrations, venthoods, etc... have been sealed with Dow Corning caulking or an equivalent. Hairline cracks are common with hardcoat stucco systems and were present in some areas. These cracks have been sealed and are cosmetic in nature. Overall, the hardcoat stucco system is in good condition. **However, the following items were identified and should be addressed:**

1. Caulking is needed along the bottom of the stucco system on the left side of the garage door, around the exterior light fixtures on the right and left sides of the front door, around the exterior light fixtures located above the patio on the back of the home, around the exterior light fixture on the right side of the exterior door on the right side of the home and along the right side of the stone patio on the back of the home. Caulking such as Dow Corning's 790/795 series or NP-1 is recommended when sealing stucco systems. The caulking will need to be maintained in the future as part of normal homeowner maintenance.
2. Ground contact of the hardcoat stucco system may present an issue with the Pest Control Industry? Please consult with the current Exterminator about this issue. If needed, the stucco system can be raised and sealed above the grade of the soil by a certified stucco contractor.

Items listed in this report may have inadvertently been left off the Summary/Defects Page(s). Client should read the **entire** report.

PICTURES



A construction gap was present between the fascia board and the roof decking at the bottom of the roof valley located above the garage door.



A rodent access hole was present above the gable return in the left, front corner of the upper attic.



A rodent access hole was present above the gable return in the left, front corner of the upper attic.



A squirrel carcass was also present in the insulation in the left, front corner of the upper attic.



A large void was present in the soil below the rear portion of the front stoop.



A qualified contractor should install the missing insulation in the rear wall of the knee wall portion of the attic located off the right wall of the master bedroom closet.



A qualified contractor should replace the rodent damaged batt insulation in the left wall of the knee wall portion of the attic located off the right wall of the master bedroom closet.



The blown-in insulation in the floor of the upper attic has been trampled in various areas from previous rodent activity.



The shingle is cracked at the gable peak located above the window in the front wall of the foyer.



Moisture stains were present on the roof decking above the chimney chase in the back, left corner of the upper attic.



Moisture stains were present on the roof decking above the bay windows in the rear wall of the master bedroom.



Replace the cracked spindle in the railing on the right side of the stairwell located in the right, front corner of the family room.



Replace the cracked spindle in the railing at the top of the stairwell in the foyer.



A chain is embedded in the lower portion of the pine tree located on the right side of the backyard and it appears that this tree was struck by lightning in the past.



The excessive height between the threshold and the stone step outside the exterior French doors in the rear wall of the family room presents a possible trip hazard.




Negative grading was present in the soil outside the front wall of the formal dining room.



A basin was present in the soil on the right side of the stone steps outside the exterior door in the laundry room.



The insides of the gutters and downspouts should be cleaned prior to closing as part of routine maintenance.



The lower portion of the downspout has been taped above retaining wall at the left, front corner of the home due to this section of the downspout being rusted.



A qualified contractor should secure the downspout to the EIFS system on the right side of the bay windows at the left, front corner of the home and ensure the downspout straps penetrating the EIFS system are sealed with caulking.



Replace the damaged downspout extension at the back, left corner of the home to help prevent water accumulation along the foundation wall.



Ponding water was present inside the rear portion of the gutter located above the garage door due to an inadequate pitch of this gutter towards the downspout. A qualified contractor should adjust this gutter and apply caulking along the top of this gutter to help prevent overflow and moisture damage to the fascia board.



Caulking should be applied along the top of the gutters located below the gable returns on the front of the home to help prevent future moisture damage to the fascia boards.



Seal the open joint in the sill below the left window in the front, center bedroom to prevent future moisture entry.



The upper sash is displaced in the window located in the front wall of the attic.



A qualified contractor should install the missing vent hood over the vent for the downdraft exhaust fan located below the rear wall of the kitchen.



A qualified contractor should install the missing vent hood over the dryer vent located outside the rear wall of the laundry room.




Moisture damage was present at the brick mould above the left side of the left window in the guest bedroom (main floor) and at the bottom of the brick mould on the left side of the left window in the back, left bedroom.



Minor moisture damage was present on the interior frame below the upper piece of glass in the right window in the formal dining room.



There appears to be inactive moisture stains on the rear portion of the garage ceiling.



There appears to be inactive moisture stains on the rear portion of the garage ceiling.



Moisture damage was present on the cabinet shelving below the kitchen sink.



Moisture damage was present on the cabinet shelving below the right sink in the master bathroom.



Inactive moisture stains were present on the ceiling of the rear closet in the back, left bedroom, which may be related to gutter overflow.



A ridge was present in the center portion of the tiled floor in the master bathroom which has caused a hairline crack in the floor tiles.



Hairline cracks were present in the tiles around the drain in the floor of the master shower stall, which is mainly cosmetic in nature.



A sediment trap is missing on the gas line entering the main floor furnace.



There appears to be past termite trails on the rigid foam wall sheathing located above the lower step-down in the foundation in the back, left corner of the basement.



A qualified contractor should re-install the wall studs and sill plate along the lower step-down in the foundation in the back, left corner of the basement.



A qualified contractor should re-install the wall stud and sill plate along the foundation behind the main floor furnace in the basement.



Raintek kick-out flashing has been installed in the stucco system at the primary roof termination located above the right side of the bay window cavity in the left, front bedroom.



The shut-off valve on the main waterline is located at the right, front corner of the basement ceiling (below the formal dining room).