www.home-probe.com

KEY FACTOR ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

THERMAL IM NON-SCOPE LIMITATIONS APPENDIX REFERENCE



25. Poor Fit

16. Condition: • Does Not Latch Properly **Location**: Second Floor Hall Bathroom

Task: Adjust

Time: Discretionary

Cost: Minor



26. Does Not Latch Properly

APPLIANCES \ Microwave oven

17. Condition: • Work light Inoperative.

This is most likely blown bulb and recommend confirming operation from the seller.

Location: Kitchen
Task: Correct
Time: Discretionary

Using Experience to Educate Our Client

Page 25 of 53