


P2 LCD Cable Connection Service Advisory	
<b>Ref #:</b> SA1000	
<b>Date:</b> Aug 15, 2014	
<b>Issue:</b> The screen on the P2 control panel remains blank upon power up or is flashing.	
<p><b>Step #1:</b> Check the LCD cable (PT2413) at the back of the display (PT2414). If the connection looks like this picture then the connector is not inserted properly.</p>	
<p><b>Step #2:</b> Insert the connector until the metal housings of the male and female connectors are touching.</p>	