

K3E October Highlight

- Year to Date: (41 K3Es Completed)
 - **Environmental Improvement: 1**
 - **Service Improvement: 3**
 - **Efficiency Improvement: 19**
 - **Quality Improvement: 7**
 - **Inventory Improvement: 4**
 - **Safety Improvement: 20**
 - **5S Improvement: 8**

Pictured to the right:

The plunger assembly and walking beams are difficult to assemble due to alignment issues in differing models of fire pumps. A 3D printed part was made and approved to improve the alignment (without adjustments) of the walking beam and contactor.

