

RE: 313 NIBLEWILL PLACE # Fwd: 313 Niblewill Place FMLS Member Home Matrix

https://mail.google.com/mail/u/2/?tab=wm&ui=2#inbox/WhoX/Agtrwblg/tyl5d9f8b/vsq/MQ6vkgjc/tuqSH6WW5tC00fwgR9JCdyBnc/Hg/projector=1&messagePartId=0.1

Find on page rhodes No results Options

313 Niblewill Place Unit 29, Marietta, GA 30066 Page 26

Interior

Attic/Structure/Assembly/Insulation cont.

Comments cont. Could not thoroughly inspect portions of the attic due to the homeowners belongings

Photos

Recommend metal housing around the vent pipe in the attic

Could not thoroughly inspect portions of the attic due to the homeowners belongings

4:25 PM 4/6/2020

RE: 313 NIBLEWILL PLACE # Fwd: 313 Niblewill Place 313 Niblewill Place Unit 29 FMLS Member Home Matrix

https://mail.google.com/mail/u/2/?tab=wm&ui=2#inbox/WhoX/Agtrwblg/tyl5d9f8b/vsq/MQ6vkgjc/tuqSH6WW5tC00fwgR9JCdyBnc/Hg/projector=1&messagePartId=0.1

Find on page rhodes No results Options

Comments

Hose bib leaks water around the knob recommend repair

Photos

Hose bib leaks water around the knob recommend repair

4:34 PM 4/6/2020

