

- Year to Date: (85 K3Es Completed)
  - **Environmental Improvement: 3**
  - **Service Improvement: 7**
  - **Efficiency Improvement: 34**
  - **Quality Improvement: 10**
  - **Inventory Improvement: 11**
  - **Safety Improvement: 42**
  - **5S Improvement: 32**

## Pictured to the right:

The 3 Phase power wires were wired directly to the test fixture. This would not allow for safe disconnect while transferring to a unit under test. Installed safe disconnects on all 3 wires which allows for a safer transition when detaching wires from test fixture to a unit under test.

