MICHIGAN ECONOMIC DEVELOPMENT CORPORATION

December 3, 2019



SCOTT ERICKSON CITY OF IRONWOOD 213 S MARQUETTE STREET IRONWOOD MI 49938

RE:

ER19-1123

Ironwood City Square Construction and Improvements, Sec. 22, T47N, R47W,

City of Ironwood, Gogebic County (HUD)

Dear Mr. Erickson:

Under the authority of Section 106 of the National Historic Preservation Act of 1966, as amended, we have reviewed the additional information for the above-cited undertaking at the location noted above. Based on the information provided for our review, it is the opinion of the State Historic Preservation Officer (SHPO) that the effects of the proposed undertaking do not meet the criteria of adverse effect [36 CFR § 800.5(a)(1)]. Therefore, the project will have <u>no adverse effect</u> [36 CFR § 800.5(b)] on the Ironwood Commercial Historic District, which appears to meet the criteria for listing in the National Register of Historic Places.

This letter evidences HUD's compliance with 36 CFR § 800.4 "Identification of historic properties" and 36 CFR § 800.5 "Assessment of adverse effects," and the fulfillment of HUD's responsibility to notify the SHPO, as a consulting party in the Section 106 process, under 36 CFR § 800.5(c) "Consulting party review." If the scope of work changes in any way, or if artifacts or bones are discovered, please notify this office immediately.

We remind you that federal agency officials or their delegated authorities are required to involve the public in a manner that reflects the nature and complexity of the undertaking and its effects on historic properties per 36 CFR § 800.2(d). The National Historic Preservation Act also requires that federal agencies consult with any Indian tribe and/or Tribal Historic Preservation Officer (THPO) that attach religious and cultural significance to historic properties that may be affected by the agency's undertakings per 36 CFR § 800.2(c)(2)(ii).

Finally, the State Historic Preservation Office is not the office of record for this undertaking. You are therefore asked to maintain a copy of this letter with your environmental review record for this undertaking. Thank you for this opportunity to review and comment, and for your cooperation.

If you have any questions, please contact Brian Grennell, Cultural Resource Management Coordinator, at 517-335-2721 or by email at GrennellB@michigan.gov. Please reference our project number in all communication with this office regarding this undertaking.

Sincerely,

Martha MacFarlane-Faes

Deputy State Historic Preservation Officer

MMF:SAT:BGG

copy:

Carmen Reveron, HUD

Julie Gardner, MEDC


Jerald Wuorenmaa, WUPPDR

FLOODPLAIN & WETLAND REVIEW FOR THE

8 STEP PROCESS FOR COMPLIANCE WITH FLOODPLAIN MANAGEMENT

[24 CFR 55, Executive Orders 11988 & 11990]

1. Floodplain and Wetland review applies to projects involving ANY of the following-Check all that apply:
Acquisition of land or buildings
New Construction
\square Substantial Rehabilitation (i.e. modifications and improvements to buildings where rehabilitation costs exceed 50% of the pre-rehab value of the building or where residential density increases more than 20%)
Expanding the footprint of buildings or structures
☐ Infrastructure Improvements—Water, Sewer, Drainage, Roads, and Ditches
Other activities affecting land use:
2. Is the project located in a 100-year floodplain, designated floodway, or results in new construction in a wetland?
☐ Yes ☐ No
[Note: Review the FIRM (Flood Insurance Rate Map) for your project area, or when the project area is not mapped, use other best available information]
If YES, skip to #4
If NO, go on to #3
3. You have determined that the project is NOT located in a floodplain or wetland. Document the determination by completing the following:
Source Documentation: Attach a FEMA Flood Insurance Rate Map (FIRM) and identify the site and project location on the map. Community Name/Number: 260081
FIRM Map Panel and Date of Map Panel: 0005 B July 17, 1978
If the area has not been mapped, obtain the best available information from one or more of the following qualified resources: (Check all sources used and attach all documentation received.)
☐ Michigan Department of Environmental Quality (MDEQ)
☐ Natural Resources Conservation Service (NRCS)
☐ Michigan Geographical Information Service (MCGI)
Other
4. You have determined that your project 🗌 is 🛛 is not located in a floodplain/wetland.
The HUD 8 Step Process is is not required.
Please sign and date this form. Return with environmental review record documents to the Project Manager.
Signature: All a Nore Date: 7/22/2019




ELEVATION REFERENCE MARKS

REFERENCE WARK	[FT, NGVD)	BESCRIPTION OF LUCATION
BAN	1433.56	A square pointer Niue on the top of the south railing, on the oust ont of the weakboard State Highway 2 (Covertant Drive) bridge over the Mostreel River.
RMZ	1462,90	A calling of spike in the most westerly 3-inch might tree in a row of 4-inch might trees, approximately 2250 feet west of the contribute of Heinlack Street, on the north-side of Cemetery Road.
RMS	1467,08	A rational spike in a power pole on the earth side of North Street, approximately 50 feet cast of the North Street bridge over the Montreal Biver,
R/44	1475,35	A chieded space in the southwest corner of the southwas wing- wall of the Silver Street bridge over the Montreal River.
RMs	1495.47	A chicked square on the southeast comes of the couthwest footing of a water tank along the extended centeding of Ash Street west, on Ole Mill property.
RM6	1479,73	The top of the west leg braze on the continuent corner of a consmission tower on the west side of Balker Street, reach of the north-cornect Sec, Chicago & North Western Railway marks.
RM7	1463.61	On the south side of the street, the "9" is "1925" as the cost abutment of the dam near the south corporate finite, near the bend in Bulkare Schot.



KEY TO MAP



Floodplain Management (CEST and EA)


General Requirements	Legislation	Regulation
Executive Order 11988,	Executive Order 11988	24 CFR 55
Floodplain Management,		
requires Federal activities to		
avoid impacts to floodplains		
and to avoid direct and		
indirect support of floodplain		
development to the extent		
practicable.		
Reference		
https://www.hudexchange.info	/environmental-review/floodpla	ain-management

	management regulations in Part 55? ☐ Yes Provide the applicable citation at 24 CFR 55.12(c) here. If project is exempt under 55.12(c)(7) or (8), provide supporting documentation.
	→ Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below.
	\boxtimes No \rightarrow Continue to Question 2.
2.	Provide a FEMA/FIRM or ABFE map showing the site. The Federal Emergency Management Agency (FEMA) designates floodplains. The FEMA Map Service Center provides this information in the form of FEMA Flood Insurance Rate Maps (FIRMs) or Advisory Base Flood Elevations (ABFEs). For projects in areas not mapped by FEMA, use the best available information to determine floodplain information. Include documentation, including a discussion of why this is the best available information for the site.
	 Does your project occur in a floodplain? ☑ No → Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below.
	□ Yes

Which of the following mitigation/minimization measures have been identified for this project in the 8-Step or 5-Step Process? Select all that apply.
☐ Permeable surfaces
$\ \square$ Natural landscape enhancements that maintain or restore natural hydrology
☐ Planting or restoring native plant species
☐ Bioswales
☐ Evapotranspiration
☐ Stormwater capture and reuse
Green or vegetative roofs with drainage provisions
\square Natural Resources Conservation Service conservation easements or similar
easements
☐ Floodproofing of structures
☐ Elevating structures including freeboarding above the required base flood
elevations
☐ Other
\rightarrow Based on the response, the review is in compliance with this section. Continue to the
Worksheet Summary below.
, , , , , , , , , , , , , , , , , , ,
Worksheet Summary
Compliance Determination
Provide a clear description of your determination and a synopsis of the information that it was
based on, such as:
Map panel numbers and dates
Names of all consulted parties and relevant consultation dates
Names of plans or reports and relevant page numbers Any additional requirements and efficiency region.
Any additional requirements specific to your region
See attached map.

Are formal compliance steps or mitigation required?	
☐ Yes	
⊠ No	

Ironwood City Square



This map is for general reference only. The US Fish and Wildlife November 7, 2019 Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should Wetlands Freshwater Emergent Wetland Lake be used in accordance with the layer metadata found on the Wetlands Mapper web site. Estuarine and Marine Deepwater Freshwater Forested/Shrub Wetland Other - Streetlights

Main preject This page was produced by the NWI mapper Estuarine and Marine Wetland Freshwater Pond Riverine

screening tool, but observed or known wetlands not indicated on NWI maps must also be processed. Off-site impacts that result in draining, impounding, or destroying wetlands must also be processed.		
References		
https://www.hudexchange.info/environmental-revie	w/wetlands-protection	<u>on</u>
1. Does this project involve new construction expansion of a building's footprint, or groun The term "new construction" shall included diking, impounding, and related activities authorized after the effective date of the Order No → Based on the response, the Continue to the Worksheet Surface	d disturbance? e draining, dredging, and any structures of er. review is in compliar	channelizing, filling, or facilities begun or
\boxtimes Yes \rightarrow Continue to Question 2.		
2. Will the new construction or other groun wetland? The term "wetlands" means those areas that with a fraguency sufficient to support and the support and t	are inundated by sui	face or ground water

The term "wetlands" means those areas that are inundated by surface or ground water with a frequency sufficient to support, and under normal circumstances does or would support, a prevalence of vegetative or aquatic life that requires saturated or seasonally saturated soil conditions for growth and reproduction. Wetlands generally include swamps, marshes, bogs, and similar areas such as sloughs, potholes, wet meadows, river overflows, mud flats, and natural ponds. Wetlands under E.O. 11990 include isolated and non-jurisdictional wetlands.

- No, a wetland will not be impacted in terms of E.O. 11990's definition of new construction.
 - → Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide a map or any other relevant documentation to explain your determination.

Yes, there is a wetland that be impacted in terms	of E.O.	11990's d	definition	of
new construction.				


Any additional requirements specific to your region
See attached map.
Are formal compliance steps or mitigation required?
☐ Yes

Names of plans or reports and relevant page numbers

 \boxtimes No

Gogebic County West Part of Ironwood Township, T48N R48W, T48N R49W, T49N R47W and T49N R48W

The heavy red line is the *Coastal Zone Management Boundary*The red hatched area is the *Coastal Zone Management Area*



Coastal Zone Management Act (CEST and EA)

General requirements	Legislation	Regulation
Federal assistance to applicant	Coastal Zone Management	15 CFR Part 930
agencies for activities affecting	Act (16 USC 1451-1464),	
any coastal use or resource is	particularly section 307(c) and	
granted only when such	(d) (16 USC 1456(c) and (d))	
activities are consistent with		
federally approved State Coastal		
Zone Management Act Plans.		
	References	
https://www.onecpd.info/enviror	mental-review/coastal-zone-ma	nagement

Projects located in the following states must complete this form.

 \square Yes \rightarrow Continue to Question 2.


Alabama	Florida	Louisiana	Mississippi	Ohio	Texas
Alaska	Georgia	Maine	New Hampshire	Oregon	Virgin Islands
American	Guam	Maryland	New Jersey	Pennsylvania	Virginia
Samona					
California	Hawaii	Massachusetts	New York	Puerto Rico	Washington
Connecticut	Illinois	Michigan	North Carolina	Rhode Island	Wisconsin
Delaware	Indiana	Minnesota	Northern	South Carolina	
			Mariana Islands		

1.	Is the project located in, or does it affect, a Coastal Zone as defined in your state Coastal
	Management Plan?

\boxtimes No \rightarrow	Based on the response, the review is in compliance with this section. Continue to the
	Worksheet Summary below. Provide a map showing that the site is not within a Coasta
	Zone.

2.	Does this project include activities that are subject to state review?	
	□Yes →	Continue to Question 3.
	□No →	Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide documentation used to make your determination.
3.	Program?	ch mitigation. → Continue to Question 4.
	section	thout mitigation. Based on the response, the review is in compliance with this Continue to the Worksheet Summary below. Provide documentation used to our determination.

	☐ No, project must be canceled. Project cannot proceed at this location.		
4.	Explain in detail the proposed measures that must be implemented to mitigate for the impact or effect, including the timeline for implementation.		
	Continue to the Worksheet Summary below. Provide documentation of the consultation (including the State Coastal Management Program letter of consistency) and any other documentation used to make your determination.		
Co	mpliance Determination ovide a clear description of your determination and a synopsis of the information that it was sed on, such as: • Map panel numbers and dates • Names of all consulted parties and relevant consultation dates • Names of plans or reports and relevant page numbers • Any additional requirements specific to your region		
Se	ee attached map.		
Are	e formal compliance steps or mitigation required? ☐ Yes ☑ No		



Sole Source Aquifers (CEST and EA)

General requirements	Legislation	Regulation		
The Safe Drinking Water Act of 1974	Safe Drinking Water	40 CFR Part 149		
protects drinking water systems	Act of 1974 (42 U.S.C.			
which are the sole or principal	201, 300f et seq., and			
drinking water source for an area and	21 U.S.C. 349)			
which, if contaminated, would create				
a significant hazard to public health.				
Reference				
https://www.hudexchange.info/environmental-review/sole-source-aquifers				

1. Does your project consist solely of acquisition, leasing, or rehabilitation of an existing building(s)? \square Yes \rightarrow Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. \bowtie No \rightarrow Continue to Question 2. 2. Is the project located on a sole source aguifer (SSA)¹? oxtimes No $oldsymbol{ o}$ Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide documentation used to make your determination, such as a map of your project (or jurisdiction, if appropriate) in relation to the nearest SSA and its source area. \square Yes \rightarrow Continue to Question 3. 3. Does your region have a memorandum of understanding (MOU) or other working agreement with EPA for HUD projects impacting a sole source aquifer? Contact your Field or Regional Environmental Officer or visit the HUD webpage at the link above to determine if an MOU or agreement exists in your area. \square Yes \rightarrow Provide the MOU or agreement as part of your supporting documentation. Continue to Question 4. \square No \rightarrow Continue to Question 5. 4. Does your MOU or working agreement exclude your project from further review? \square Yes \rightarrow Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide documentation used to make your determination and document where your project fits within the MOU or agreement.

¹ A sole source aquifer is defined as an aquifer that supplies at least 50 percent of the drinking water consumed in the area overlying the aquifer. This includes streamflow source areas, which are upstream areas of losing streams that flow into the recharge area.

Worksheet Summary

Compliance Determination

Provide a clear description of your determination and a synopsis of the information that it was based on, such as:

- Map panel numbers and dates
- Names of all consulted parties and relevant consultation dates
- Names of plans or reports and relevant page numbers
- Any additional requirements specific to your region

Project is not located on or near a sole-source aquifer. See attached maps.
re formal compliance steps or mitigation required?
☐ Yes
⊠ No



Conserving the Nature of America

ECOS / Species Reports / Species By County Report

Species By County Report

The following report contains Species that are known to or are believed to occur in this county. Species the state level are now excluded from this report. If you are looking for the Section 7 range (for please visit the IPaC application.

County: Gogebic, Michigan

Need to contact a FWS field office about a species? Follow this link to find your local FWS Office.

Group	Name	Population	Status	Lead Office	Recovery Plan	Re
Birds	Red knot (<u>Calidris</u> <u>canutus rufa</u>)	Wherever found	Threatened	New Jersey Ecological Services Field Office	Recovery Outline for the Rufa Red Knot (Calidris canutus rufa)	in no im inf to

Group	Name	Population	Status	Lead Office	Recovery Plan	Re
Mammals	Gray wolf (<u>Canis lupus</u>)	U.S.A.: All of AL, AR, CA, CO, CT, DE, FL, GA, IA, IN, IL, KS, KY, LA, MA, MD, ME, MI, MO, MS, NC, ND, NE, NH, NJ, NV, NY, OH, OK, PA, RI, SC, SD, TN, TX, VA, VT, WI, and WV; and portions of AZ, NM, OR, UT, and WA. Mexico.	Endangered	Assistant Regional Director- Ecological Services		
<i>M</i> ammals	Canada Lynx (<u>Lynx</u> <u>canadensis</u>)	Wherever Found in Contiguous U.S.	Threatened	Montana Ecological Services Field Office	Recovery Outline for the Contiguous United States Distinct Population Segment of Canada Lynx (Lynx canadensis)	in no im inf

Mammals

Northern Long-

<u>septentrionalis</u>)

Eared Bat

(Myotis

Wherever found

Threatened

Minnesota-

Wisconsin

Ecological

Services Field Office

Endangered Species Act (CEST and EA)

General requirements	ESA Legislation	Regulations		
Section 7 of the Endangered Species Act (ESA)	The Endangered	50 CFR Part		
mandates that federal agencies ensure that	Species Act of 1973 (16	402		
actions that they authorize, fund, or carry out	U.S.C. 1531 et seq.);			
shall not jeopardize the continued existence of	particularly section 7			
federally listed plants and animals or result in	(16 USC 1536).			
the adverse modification or destruction of				
designated critical habitat. Where their actions				
may affect resources protected by the ESA,				
agencies must consult with the Fish and Wildlife				
Service and/or the National Marine Fisheries				
Service ("FWS" and "NMFS" or "the Services").				
References				
https://www.hudexchange.info/environmental-re	view/endangered-species			

L .	Does the project involve any activities that have the potential to affect species or habitats? ☐ No, the project will have No Effect due to the nature of the activities involved in the project. → Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide any documents used to make your determination.		
	□ No, the project will have No Effect based on a letter of understanding, memorandum of agreement, programmatic agreement, or checklist provided by local HUD office. Explain your determination:		

- → Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide any documents used to make your determination.
- 2. Are federally listed species or designated critical habitats present in the action area?

 Obtain a list of protected species from the Services. This information is available on the FWS

 Website or you may contact your Local FWS and/or NMFS offices directly.
 - \boxtimes No, the project will have No Effect due to the absence of federally listed species and designated critical habitat.
 - → Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide any documents used to make your determination. Documentation

	\square No, the Service(s) did not concur with the finding. \rightarrow <i>Continue to Question 5.</i>
	Formal consultation is required Section 7 of ESA (16 USC 1536) mandates consultation to resolve potential impacts to federally listed endangered and threatened species and critical habitats. If a HUD assisted project may affect any endangered or threatened species or critical habitat, then compliance is required with Section 7. See 50 CFR Part 402 Subpart B Consultation Procedures.
	 → Once consultation is complete, the review is in compliance with this section. Continue to Question 6 and provide the following: (1) A biological assessment, evaluation, or equivalent document (2) Biological opinion(s) issued by FWS and/or NMFS (3) Any other documentation of formal consultation
	For the project to be brought into compliance with this section, all adverse impacts must be mitigated. Explain in detail the proposed measures that will be implemented to mitigate for the impact or effect, including the timeline for implementation.
	□ No mitigation is necessary. Explain why mitigation will not be made here:
<u>Wc</u>	orksheet Summary
	npliance Determination vide a clear description of your determination and a synopsis of the information that it was
	· · · · · · · · · · · · · · · · · · ·
	ed on, such as:
	Map panel numbers and dates
	•
	Map panel numbers and dates
	 Map panel numbers and dates Names of all consulted parties and relevant consultation dates

Are formal compli	ance steps or mitigation required?
☐ Yes	
⊠ No	










NATIONAL SYSTEM MANAGEMENT RESOURCES PUBLICATIONS CONTACT US 50 YEARS SITE INDEX

MICHIGAN

Michigan has approximately 51,438 miles of river, of which 656.4 miles are designated as wild & scenic—just a bit more than 1% of the state's river miles.



Choose A State V Go Choose A River V Go

Nourished by the fertile soils of the region, rivers of the Midwest explode with life, from great avian migrations to ancient fishes.

AuSable River

Bear Creek

Black River

Carp River

Indian River

Manistee River

Ontonagon River

Paint River

Pere Marquette River

Pine River

Presque Isle River

Sturgeon River (Hiawatha National Forest)

Sturgeon River (Ottawa National Forest)

Tahquamenon River (East Branch)


Whitefish River

Yellow Dog River

NATIONAL SYSTEM MANAGEMENT RESOURCES PUBLICATIONS CONTACT US 50 YEARS SITE INDEX

WISCONSIN

Wisconsin has approximately 56,884 miles of river, of which 276 miles are designated as wild & scenic—approximatley 1/2 of 1% of the state's river miles.



St. Croix River Wolf River

Wild and Scenic Rivers (CEST and EA)

General requirements	Legislation	Regulation		
The Wild and Scenic Rivers Act	The Wild and Scenic Rivers	36 CFR Part 297		
provides federal protection for	Act (16 U.S.C. 1271-1287),			
certain free-flowing, wild, scenic	particularly section 7(b) and			
and recreational rivers designated	(c) (16 U.S.C. 1278(b) and (c))			
as components or potential				
components of the National Wild				
and Scenic Rivers System (NWSRS)				
from the effects of construction or				
development.				
References				
https://www.hudexchange.info/environmental-review/wild-and-scenic-rivers				

1. Is your project within proximity of a NWSRS river as defined below?

Wild & Scenic Rivers: These rivers or river segments have been designated by Congress or by states (with the concurrence of the Secretary of the Interior) as wild, scenic, or recreational

<u>Study Rivers:</u> These rivers or river segments are being studied as a potential component of the Wild & Scenic River system.

<u>Nationwide Rivers Inventory (NRI):</u> The National Park Service has compiled and maintains the NRI, a register of river segments that potentially qualify as national wild, scenic, or recreational river areas

X	N	O

→ Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide documentation used to make your determination, such as a map identifying the project site and its surrounding area or a list of rivers in your region in the Screen Summary at the conclusion of this screen.

\square Yes, the project is in proximit	y of a Nationwide Rivers Inventory	/ (NRI) River
---	------------------------------------	---------------

2. Could the project do any of the following?

- Have a direct and adverse effect within Wild and Scenic River Boundaries,
- Invade the area or unreasonably diminish the river outside Wild and Scenic River Boundaries, or
- Have an adverse effect on the natural, cultural, and/or recreational values of a NRI segment.

[→] Continue to Question 2.


Worksheet Summary

Compliance Determination

Provide a clear description of your determination and a synopsis of the information that it was based on, such as:

- Map panel numbers and dates
- Names of all consulted parties and relevant consultation dates
- Names of plans or reports and relevant page numbers
- Any additional requirements specific to your region

See attached ma	ps.		
Are formal comp	oliance steps or mitigation require	ed?	
☐ Yes			
⊠ No			



Business Licenses & Regulations

Recreation Env

Contact

Join DNR

Search or Keywords

Q

Interactive map


Click on a county below for a summary of the applicable permitting requirements based on nonattainment area designations as of August 3, 2018.

. Air quality

* Air pollutants and standards

• Ozone

Please note: Graphical representations of attainment/nonattainment areas are approximate. Contact DNR staff with questions on the current status of specific locations.



Air Quality (CEST and EA)

General Requirements	Legislation	Regulation
The Clean Air Act is administered by the	Clean Air Act (42 USC	40 CFR Parts 6, 51
U.S. Environmental Protection Agency	7401 et seq.) as	and 93
(EPA), which sets national standards on	amended particularly	
ambient pollutants. In addition, the Clean	Section 176(c) and (d)	
Air Act is administered by States, which	(42 USC 7506(c) and (d))	
must develop State Implementation Plans		
(SIPs) to regulate their state air quality.		
Projects funded by HUD must		
demonstrate that they conform to the		
appropriate SIP.		
Reference		
https://www.hudexchange.info/environmental-review/air-quality		

Scope of Work

1. Does your project include new construction or conversion of land use facilitating the development of public, commercial, or industrial facilities OR five or more dwelling units?

\boxtimes	Yes → Continue to Question 2.
	No
	Based on the response, the review is in compliance with this section. Continue to the
	Worksheet Summary below. Provide any documents used to make your determination.

Air Quality Attainment Status of Project's County or Air Quality Management District

2. Is your project's air quality management district or county in non-attainment or maintenance status for any criteria pollutants?

Follow the link below to determine compliance status of project county or air quality management district:

http://www.epa.gov/oaqps001/greenbk/

- No, project's county or air quality management district is in attainment status for all criteria pollutants
 - → Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide any documents used to make your determination.

Worksheet Summary

Compliance Determination

Provide a clear description of your determination and a synopsis of the information that it was based on, such as:

- Map panel numbers and dates
- Names of all consulted parties and relevant consultation dates
- Names of plans or reports and relevant page numbers
- Any additional requirements specific to your region

See attached maps.
Are formal compliance steps or mitigation required?
☐ Yes
⊠ No

Farmlands Protection (CEST and EA)

General requirements	Legislation	Regulation
The Farmland Protection Policy Act (FPPA) discourages federal activities that would convert farmland to nonagricultural purposes.	Farmland Protection Policy Act of 1981 (7 U.S.C. 4201 et seq.)	7 CFR Part 658
Reference		
https://www.hudexchange.info/environmental-review/farmlands-protection		

htt	tps://www.hudexchange.info/environmental-review/farmlands-protection
1.	Does your project include any activities, including new construction, acquisition of undeveloped land or conversion, that could convert agricultural land to a non-agricultural use?
	☐ Yes → Continue to Question 2.☑ No
	Explain how you determined that agricultural land would not be converted:
	All project land is already in urban development and thus is exempted from FPPA by 7 CFR 658.2(a).
	→ Based on the response, the review is in compliance with this section. Continue to th Worksheet Summary below. Provide any documentation supporting you determination.
۷.	Does "important farmland," including prime farmland, unique farmland, or farmland of statewide or local importance regulated under the Farmland Protection Policy Act, occur on the project site? You may use the links below to determine important farmland occurs on the project site:
	 Utilize USDA Natural Resources Conservation Service's (NRCS) Web Soil Surve http://websoilsurvey.nrcs.usda.gov/app/HomePage.htm
	 Check with your city or county's planning department and ask them to document the project is on land regulated by the FPPA (zoning important farmland as non agricultural does not exempt it from FPPA requirements)
	 Contact NRCS at the local USDA service center http://offices.sc.egov.usda.gov/locator/app?agency=nrcs or your NRCS state soil scientist http://soils.usda.gov/contact/state offices/ for assistance
	\square No \Rightarrow Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide any documents used to make your determination.
	□Yes → Continue to Question 3.

Worksheet Summary

Compliance Determination

Provide a clear description of your determination and a synopsis of the information that it was based on, such as:

- Map panel numbers and dates
- Names of all consulted parties and relevant consultation dates
- Names of plans or reports and relevant page numbers
- Any additional requirements specific to your region

See attached map.		
Are formal compliance steps or mitigatio	n required?	
☐ Yes		
⊠ No		



Imagery @2019 Maxar Technologies, USDA Farm Service Agency, Map data @2019

Explosive and Flammable Hazards (CEST and EA)

General requirements	Legislation	Regulation
HUD-assisted projects must meet	N/A	24 CFR Part 51
Acceptable Separation Distance (ASD)		Subpart C
requirements to protect them from		
explosive and flammable hazards.		
Reference		
https://www.hudexchange.info/environmental-review/explosive-and-flammable-facilities		

requirements to protect them nom	
explosive and flammable hazards.	
Re	eference
https://www.hudexchange.info/environme	ntal-review/explosive-and-flammable-facilities
	oject include a hazardous facility (a facility that flammable or combustible chemicals such as bulk
☐ Yes	
Explain:	
\rightarrow Continue to Question 5.	
rehabilitation that will increase reside ⊠ No	eview is in compliance with this section. Continue to
☐ Yes→ Continue to Question 3.	
aboveground storage containers:Of more than 100 gallon capacit	, are there any current or planned stationary (), containing common liquid industrial fuels OR ardous liquids or gases that are not common liquid

	unacceptable separation distance, provide approval from a licensed professional engineer.
	heet Summary
Compli	ance Determination
	e a clear description of your determination and a synopsis of the information that it was
based	on, such as:
•	Map panel numbers and dates
•	Names of all consulted parties and relevant consultation dates
•	Names of plans or reports and relevant page numbers
•	Any additional requirements specific to your region
Are for	mal compliance steps or mitigation required?
	□ Yes
	⊠ No

Noise (EA Level Reviews)

General requirements Legislation		Regulation		
HUD's noise regulations protect	Noise Control Act of 1972	Title 24 CFR 51		
residential properties from		Subpart B		
excessive noise exposure. HUD	General Services Administration			
encourages mitigation as	Federal Management Circular 75-			
appropriate.	2: "Compatible Land Uses at			
	Federal Airfields"			
References				

https://www.hudexchange.info/programs/environmental-review/noise-abatement-andcontrol

1.	What activities does	our proj	ject involve?	Check all	that apply:
----	----------------------	----------	---------------	-----------	-------------

ctivities does your project involve? Check all that apply:
☐ New construction for residential use
NOTE: HUD assistance to new construction projects is generally prohibited if
they are located in an Unacceptable zone, and HUD discourages assistance for
new construction projects in Normally Unacceptable zones. See 24 CFR
51.101(a)(3) for further details.
→ Continue to Question 2.
☐ Rehabilitation of an existing residential property
NOTE: For major or substantial rehabilitation in Normally Unacceptable zones,
HUD encourages mitigation to reduce levels to acceptable compliance standards
For major rehabilitation in Unacceptable zones, HUD strongly encourages
mitigation to reduce levels to acceptable compliance standards. See 24 CFR 51
Subpart B for further details.
→ Continue to Question 2.
\square A research demonstration project which does not result in new construction
or reconstruction, interstate, land sales registration, or any timely emergency
assistance under disaster assistance provisions or appropriations which are
provided to save lives, protect property, protect public health and safety,
remove debris and wreckage, or assistance that has the effect of restoring
facilities substantially as they existed prior to the disaster
\rightarrow Based on the response, the review is in compliance with this section. Continue
to the Markshoot Cummary below

- to the Worksheet Summary below.
- None of the above
- → Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below.

\square Mitigation as follows will be implemented:
→ Provide drawings, specifications, and other materials as needed to describe the project's noise mitigation measures. Continue to the Worksheet Summary.
☐ No mitigation is necessary.
Explain why mitigation will not be made here:
→ Continue to the Worksheet Summary.
Worksheet Summary Compliance Determination
Provide a clear description of your determination and a synopsis of the information that it wa
based on, such as:
Map panel numbers and dates Names of all consulted parties and relevant consultation dates.
 Names of all consulted parties and relevant consultation dates Names of plans or reports and relevant page numbers
Any additional requirements specific to your region
Are formal compliance steps or mitigation required?
☐ Yes
⊠ No

Airport Hazards (CEST and EA)


General policy	Legislation	Regulation	
It is HUD's policy to apply standards to		24 CFR Part 51 Subpart D	
prevent incompatible development			
around civil airports and military			
airfields.			
References			
https://www.hudexchange.info/environmental-review/airport-hazards			
1. To ensure compatible land use development, you must determine your site's proximity to civil and military airports. Is your project within 15,000 feet of a military airport or 2,500 feet of a civilian airport?			

civil and ı	e compatible land use development, you must determine your site's proximity to military airports. Is your project within 15,000 feet of a military airport or 2,500			
feet of a civilian airport?				
⊠No →	Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide a map showing that the site is not within the applicable distances to a military or civilian airport.			
□Yes →	Continue to Question 2.			
	roject located within a Runway Potential Zone/Clear Zone (RPZ/CZ) or Accident			
	oject is in an APZ -> Continue to Question 3.			
□Yes, pro	oject is an RPZ/CZ → Project cannot proceed at this location.			
□No, pro	eject is not within an APZ or RPZ/CZ			
	sed on the response, the review is in compliance with this section. Continue to the orksheet Summary below. Provide a map showing that the site is not within either zone.			
Is the pro	ject in conformance with DOD guidelines for APZ?			
□Yes, pro	oject is consistent with DOD guidelines without further action.			
Explair	how you determined that the project is consistent:			
	feet of a c No → Is your proportion Yes, pro No, pro Ba Wo Is the pro Yes, pro			

→ Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide any documentation supporting this determination.

\square No, the project cannot be brought into conformance with DOD guidelines and has not been approved. \rightarrow <i>Project cannot proceed at this location.</i>
□ Project is not consistent with DOD guidelines, but it has been approved by Certifying Officer or HUD Approving Official. Explain approval process:
If mitigation measures have been or will be taken, explain in detail the proposed
measures that must be implemented to mitigate for the impact or effect, including the timeline for implementation.
→ Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide any documentation supporting this determination.
Worksheet Summary Compliance Determination Provide a clear description of your determination and a synopsis of the information that it was based on, such as: • Map panel numbers and dates • Names of all consulted parties and relevant consultation dates • Names of plans or reports and relevant page numbers • Any additional requirements specific to your region
See attached map.

Are formal compliance	steps or mitigation required?
☐ Yes	
⊠ No	





COLEMAN ENGINEERING COMPANY

CIVIL ENGINEERING • ENVIRONMENTAL ENGINEERING • GEOTECHNICAL ENGINEERING • SURVEYING

200 EAST AYER STREET • IRONWOOD, MI 49938 • PHONE: 906-932-5048

August 28, 2019

Mr. Scott Erickson, City Manager City of Ironwood 213 S. Marquette Street Ironwood, MI 49938



Re: Lahti Property

Phase I Environmental Site Assessment (ESA)

Lots 1, 2, 3, part of Lot 4, 14, 15, 16, 17, and parts of Lots 18 and 19, Block 30

Ironwood, Michigan

Dear Mr. Erickson:

Attached please find a final copy of the Phase I Environmental Site Assessment Report for the Lahti Property located between Lowell Street, Lawrence Street, Aurora Street, and McLeod Avenue.

Thank you again for allowing Coleman Engineering Company to provide professional engineering services for the City of Ironwood. If you have any questions, please do not hesitate to contact me at (906) 932-5048.

Sincerely,

COLEMAN ENGINEERING COMPANY

Michael G. Gotham

Environmental Scientist

MGG/map

Enclosure



PHASE I ENVIRONMENTAL SITE ASSESSMENT

FOR

LAHTI PROPERTY

IRONWOOD, MICHIGAN

AUGUST 2019

COLEMAN ENGINEERING COMPANY

CIVIL ENGINEERING • ENVIRONMENTAL ENGINEERING
GEOTECHNICAL ENGINEERING • SURVEYING

PHASE I ENVIRONMENTAL SITE ASSESSMENT

FOR

LAHTI PROPERTY

IRONWOOD, MICHIGAN

AUGUST 2019

Prepared By:

COLEMAN ENGINEERING COMPANY 200 East Ayer Street Ironwood, Michigan 49938

CEC Project #EC-190668

"I declare that, to the best of my professional knowledge and belief, I meet the definition of environmental professional as defined in §312.10 of 40 CFR 312 and 12.13.2. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312."

Prepared By: Michael G. Gotham, Environmental Scientist

Signature: Date: 8/28/19

Reviewed By: Steven Friberg, P.E., Senior Engineer

Signature: 5tm Date: 8/29/19

TABLE OF CONTENTS

		Page #
	EXECUTIVE SUMMARY	1
1.0	INTRODUCTION	1
1.0	1.1 Background	
	1.2 Purpose	
	1.3 Scope	
	1.4 Limitations and Exceptions	
	1.5 Special Terms and Conditions	
2.0	CITE DESCRIPTION	4
2.0	SITE DESCRIPTION	
	2.1 Location	
	2.2 Legal Description	
	2.3 Site and Vicinity Characteristics	4
	2.4 Current Use of Subject Property	5
	2.5 Past Uses of Subject Property	
	2.6 Description of Site Structures and Improvements	
	2.7 Current Uses of Adjoining Properties	
	2.8 Adjoining Property Observations	6
3.0	CLIENT PROVIDED INFORMATION	6
4.0	RECORDS REVIEW	6
7.0	4.1 Government Database Review	
	4.2 Historical Aerial Photographs	
	4.3 Sanborn Maps	
	4.5 Sanooni Maps	1 /
5.0	SITE RECONNAISSANCE	19
	5.1 Subject Property Site Reconnaissance	19
	5.1.1 Buildings	19
	5.1.2 Vacant Property	19
	5.2 Additional Site Information	19
	5.2.1 Utilities	
	5.2.2 Hazardous Substance/Waste Storage	
	5.2.3 Underground Storage Tanks	
	5.2.4 Aboveground Storage Tanks	
	5.2.5 Solid Waste Disposal	
	5.2.6 Storm Water	
	5.2.7 Water Wells	
	5.2.8 Polychlorinated biphenyls (PCBs)	
	5.2.9 Air Permits	20

		Page #
6.0	INTERVIEWS	21
	6.1 Site Owner/Representative	21
	6.2 State Government	21
	6.3 County and Local Government	
	6.4 Other Knowledgeable Persons	21
7.0	NON-SCOPE ISSUES	21
8.0	FINDINGS	21
9.0	OPINIONS	22
10.0	CONCLUSIONS	22
11.0	DEVIATIONS	23
12.0	REFERENCES	23

APPENDICES

APPENDIX A – FIGURES

Figure 1 – Project Location Map

Figure 2 – Site Aerial Photo

APPENDIX B – ENVIRONMENTAL DATA RESOURCES

APPENDIX C - AERIAL PHOTOGRAPHS

APPENDIX D – SANBORN MAPS

APPENDIX E – SITE PHOTOGRAPHS

APPENDIX F – USER QUESTIONNAIRE

APPENDIX G – PROPERTY DESCRIPTION

APPENDIX H – QUALIFICATIONS

APPENDIX I – LIMITATIONS

EXECUTIVE SUMMARY

Coleman Engineering Company (CEC) has performed a Phase I Environmental Site Assessment (ESA) in conformance with the Scope and Limitations of American Society for Testing and Materials (ASTM) E 1527-13 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process at the Lahti Property, which can be described as Lots 1, 2, 3, the East 19 ½ feet of Lot 4; Lots 14, 15, 16, 17, the West 12 feet of the South 68 feet and the North 72 feet of Lot 18, and the West 12 feet of the North 72 feet of Lot 19, all within Block 30, City of Ironwood, Gogebic County, Michigan, hereinafter referred to as the Subject Property. Any exceptions or deletions from the ASTM E 1527-13 practice are revealed in Section 1.0 of this report.

This assessment has revealed no evidence of recognized environmental conditions (RECs) in association with the Subject Property.

Although ASTM E 1527-13 Standard does not require a demonstration of appropriate inquiry beyond scope considerations, there may be standards or protocols for assessment of potential hazards and conditions associated with beyond scope conditions developed by government entities, professional organizations, or other private entities.

No efforts have been expended to investigate the potential for off-site, third-party impacts. Further investigation of RECs may require site sampling and analysis. These activities are all beyond the defined scope of this investigation. The Client may, however, wish to undertake these activities. Only the Client is capable of determining the relevancy of information presented and the need to pursue items of concern further. Qualifications of Environmental Professionals conducting this assessment are provided as Appendix H. Additional Limitations are provided in Appendix I.

1.0 INTRODUCTION

1.1 Background

CEC has been retained by the City of Ironwood to perform a Phase I ESA of the Lahti Property, in Block 30 which is located between S. Lawrence Street, S. Lowell Street, W. Aurora Street (US-2 Bus), and W. McLeod Avenue in the City of Ironwood, Gogebic County, Michigan (Subject Property).

The Subject Property contains two (2) properties separated by an alley that are approximately 0.753 acres in total. The Subject Property contains a gravel parking lot and an asphalt parking lot. Furthermore, indications of a concrete foundation associated with the former Curry Hotel exist within the asphalt parking lot on the northern-most portion of the Subject Property. Also, a small vegetated area lies within the southwestern-most lot.

1.2 Purpose

The purpose of the Phase I ESA process, as set forth in ASTM E 1527-13, "...is to define good commercial and customary practice in the United States of America for conducting an environmental site assessment of a parcel of commercial real estate with respect to the range of contaminants within the scope of the Comprehensive Environmental Response Compensation and Liability Act (CERCLA) and petroleum products." As such, this practice is intended to permit a buyer of a property to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner or bona fide prospective purchaser defenses, to CERCLA liability: That is, the practices that constitute "all appropriate inquiry into previous ownership and uses of the property consistent with good commercial or customary practices," as defined in 42USC 9601.

"In defining a standard of good commercial and customary practice for conducting an environmental site assessment of a parcel of property, the goal of the processes established by this practice is to identify recognized environmental conditions."

The term REC means the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property. The terms 'hazardous substances' or 'petroleum products' include those even under conditions in compliance with laws. According to ASTM: "The term," (REC), "is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies."

1.3 Scope

Information needed for completion of a Phase I ESA may be provided by a number of parties including third-party vendors, present owners, and operators of the property, regulatory agencies, neighbors, past and present employees, etc. Prior assessments may also contain usable information. A Phase I ESA does not include any testing or sampling of materials.

Limitations of a Phase I ESA are predicated on the scope of services. The Scope of Services for the Phase I ESA focused on the following:

- Regulatory agency file search. The purpose of this review is to help determine the potential for hazardous substances or petroleum products on the Subject Property and within a reasonable "Search Distance" of the Subject Property as a result of either past or present activities; and if such substances are present, to assess if conditions suggest that such materials have the potential to affect the Subject Property.
- Federal, State, local, and Tribal regulatory agency files are reviewed through the use of a specialized environmental database search firm. The information includes, but is not limited to, CERCLA, National Priorities List (NPL), Resource Conservation and Recovery

Act (RCRA), the State List of Environmental Contamination Sites, the State List of Leaking Underground Storage Tank (LUST) Sites, and the State List of Underground Storage Tank (UST) Sites.

- Local records and/or additional state or tribal records shall be checked when in the
 judgment of the environmental professional; such additional documents are sufficiently
 useful.
- Limited interviews with persons having specific knowledge of the Subject Property. The goal of the interviews is to assess if conditions suggest that hazardous substances or petroleum products are present on or have the potential to affect the Subject Property.
- A site reconnaissance of the Subject Property. The goal of the site reconnaissance is to assess if conditions suggest that hazardous substances or petroleum products are present on or have the potential to affect the Subject Property.
- Investigation of adjoining properties limited to a review of the possible existence of regulated substances through information supplied by regulatory agency databases. General observations as to the potential presence of visually evident RECs on adjoining properties are also performed during the site reconnaissance by walking the property lines of the Subject Property.
- The completion of a report describing the investigation methods, findings, and conclusions.

1.4 Limitations and Exceptions

The scope of the ASTM Phase I investigation is limited explicitly from consideration of asbestos-containing materials, radon, lead-based paints, lead in drinking water, potable water well tests, septic tank/drainfield tests, herbicides/pesticides, and wetlands. It is understood that a lead-based paint and asbestos inspection has been completed for the building. The scope of the proposed investigation did not include preparation of a title abstract, nor was one provided by the Client.

There are other limitations inherent to ESAs. When dealing with natural conditions, and especially natural conditions that are hidden from view, even the most accomplished investigator can only deal in probabilities. Environmental conditions are also affected by time due to the mobility of contaminants, change in state, and other characteristics of materials.

No ESA can wholly eliminate uncertainty regarding the environmental condition of the site. A Phase I ESA is intended to reduce, but not eliminate, uncertainty regarding the environmental condition of the Subject Property. A Phase I ESA also does not constitute an exhaustive assessment of a clean property. There is a point at which the cost of information gathered and/or the time required to collect it outweighs the usefulness of the information and, in fact, may be a material detriment to the orderly completion of transactions. The Client must be comfortable that a balance between the competing goals of reasonable and practical ESAs and the reduction in unknown conditions resulting from additional information has been attempted. Additional Limitations are included in Appendix I of this report.

1.5 Special Terms and Conditions

This report is intended solely for the use of the Client. Any reuse without an update and/or written verification of applicability from CEC is at the user's sole risk.

CEC expressly disassociates itself from any use of this document or the information included herein, except as authorized. All information related to or provided by private sources is confidential. The identification of private sources shall not be interpreted as authorization or permission by CEC for contact with such sources.

2.0 SITE DESCRIPTION

2.1 Location

The Subject Property is located in part of Block 30, City of Ironwood, Gogebic County, Michigan. Refer to the figures in Appendix A for the general location and the site layout of the Subject Property.

2.2 Legal Description

Refer to the Parcel Assessment Cards obtained from the Gogebic County Geographic Information System (GIS), within Appendix G, for the abbreviated legal descriptions.

2.3 Site and Vicinity Characteristics

The Subject Property is currently zoned as vacant commercial land. It is situated on the southern portion of downtown Ironwood along W. Aurora Street to the northwest, S. Lowell Street to the northeast, W. McLeod Avenue to the southeast, and S. Lawrence Street to the southwest. There are no existing structures on the Subject Property, but the city block includes the following businesses: Floors N' Mor West, WIMI-WJMS Radio Station, Stems Flower Shop, Fabric Patch, and the Knights Billiards Club.

The Subject Property is greater than 1,500 feet above mean sea level (MSL) and is situated in the Superior Bedrock Uplands physiographic region of Upper Michigan. The Subject Property lies above the Tyler Formation, which is characterized by having bedrock consisting of mainly quartzrich graywacke and argillite of the Early Proterozoic geologic age.

The landscape and soils are a result glacial till, with the area being a bedrock-controlled ground moraine. The glacially derived unconsolidated deposits—which consist of a sequence of interbedded gravel, sand, silt, and boulders with variations over short distances—overlie bedrock at the Subject Property. The soil at the Subject Property is understood to be primarily Gogebic fine sandy loams; however, it is suspected that the soils are actually a result of urbanized fill from commercial developments.

2.4 Current Use of Subject Property

The Subject Property is currently used as a parking lot for Main Street Fitness.

2.5 Past Uses of Subject Property

According to the Sanborn Maps provided by Environmental Database Resources, Inc. (EDR), the Subject Property formerly contained the Curry Hotel and the St. Michaels Catholic Church. It is also understood that a drive-in movie theatre was located in the vicinity of the Subject Property.

2.6 Description of Site Structures and Improvements

The Subject Property is approximately 0.753 acres. The Subject Property is improved with asphalt and gravel parking lots.

2.7 Current Uses of Adjoining Properties

The adjoining properties, defined as any real property or properties, the border of which is contiguous or partially contiguous with that of the Subject Property, or that would be contiguous or partially contiguous with that of the Subject Property but for a street, road, or other public thoroughfare separating them, were observed during the site reconnaissance.

The adjoining properties are summarized by general direction from the Subject Property:

North: North of the Subject Property is the intersection of S. Lowell and W. Aurora Streets. Main Street Fitness, Constantini's Furniture, the Historic Ironwood Theatre, and the Chief Oil Company main office are also situated to the north. Additional businesses and apartment buildings within downtown Ironwood lie further beyond.

South: South of the Subject Property are private residences, W. McLeod Avenue, the WIMI-WJMS Radio Station, and the Ironwood Public Safety Department. A flooded pit associated with the former mining industry lies further beyond.

West: To the west, contiguous with the Subject Property, is Floors N' Mor West, the Knights Billiards Club, and W. Aurora Street. Ben's Place Restaurant, Joe's Pasty Shop, New Beginnings Resale Store, Gene's Auto, Mukavitz Heating, and an abandoned railroad grade turned ATV trail lie further beyond.

East: East of the Subject Property is Stems Flower Shop, the Fabric Patch, and W. McLeod Avenue. Residences, a former dry cleaner, and storage garages lie further beyond.

2.8 Adjoining Property Observations

There are two (2) potential RECs associated with the adjoining properties.

- Adjacent properties, or properties in proximity to the Subject Property within Block 30, were formerly used as automobile repair shops or filling stations during the early 20th Century. The Sanborn Maps attached in Appendix D show evidence of gasoline storage tanks in association with these facilities. Petroleum storage tanks, especially those used during the 20th Century, were notorious for corroding and releasing their contents into the environment. Although former gasoline storage tanks were notorious for causing releases, a review of EGLE databases and an interview with an EGLE LUST Project Manager, exhibited no evidence of contamination in the area. It is presumed that contamination would have been encountered during updates and maintenance of the surrounding infrastructure. Therefore, CEC believes that this REC should be considered historic, and does not present a material threat release to the Subject Property.
- The Ironwood Dye Works property was located at 122 W. Aurora Street separated only by Aurora Street from the Subject Property. Clothing dye chemicals used in the past contained hazardous substances (e.g., chlorinated solvents), which if not stored or disposed of properly, have the potential to cause risk to human health and the environment in the event of a release. Although hazardous substances were used during the operations of dyeing clothing, the Ironwood Dye Works property is listed as a RCRA Conditionally Exempt Small Quantity Generator which signifies that very small amounts of hazardous substances were generated during their small-scale operations. Furthermore, RCRA has no recorded violations for Ironwood Dye Works. Based on this information, CEC believes that this potential REC does not present a material threat of release to the Subject Property.

3.0 CLIENT PROVIDED INFORMATION

An ASTM E 1527-13 Appendix X3 User Questionnaire is provided in Appendix F.

4.0 RECORDS REVIEW

Based on the reviews listed below and the interviews, analysis of further databases or lists was judged to be unnecessary to determine the history of the property.

4.1 Government Database Review

A record review following ASTM standards for Environmental Site Assessments (E 1527-13) was completed using the services of Environmental Data Resources, Inc. (EDR) of Shelton, Connecticut. A summarized list of State and Federal databases searched, along with the applicable ASTM search distances in parentheses, are listed below. The results, including the Radius Map, are presented in Appendix B.

- 1. U.S. Environmental Protection Agency (USEPA) National Priority List (NPL) (1.0 mile)
- 2. USEPA Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) Superfund Enterprise Management System (SEMS) (0.5 miles)
- 3. USEPA Resource Conservation and Recovery Act (RCRA) Corrective Action Report Sites (CORRACTS) (1.0 mile)
- 4. USEPA RCRA non-CORRACTS Treatment, Storage, and Disposal Facilities (RCRA-TSDF) (0.5 miles)
- 5. USEPA RCRA Large Quantity Generators (RCRA-LQG) (0.25 miles), Small Quantity Generators (RCRA-SQG) (0.25 miles), and Conditionally Exempt Small Quantity Generators (RCRA-CESQG) (0.25 miles)
- 6. USEPA Emergency Response Notification System (ERNS) (Target Property Only)
- 7. EGLE Registered Underground Storage Tanks (MI UST) (0.25 miles) and EGLE Aboveground Storage Tanks (MI AST) (0.25 miles)
- 8. EGLE Leaking UST Sites (MI LUST) (0.5 miles)
- 9. EGLE Solid Waste Facilities/Landfills (MI SWF/LF) (0.5 miles)
- 10. EGLE INVENTORY (0.5 miles)
- 11. EGLE Activity Use Limitation (MI AUL) (0.5 miles)

Additional Environmental Records

There are seven (7) additional databases listed within the EDR Report which are not required to be searched by the ASTM Standard but are included within this assessment. These databases include the MI DEL PART 201, RCRA NonGen/NLR, MI DRYCLEANERS, MN MANIFEST, EDR MGP, EDR Hist Auto, and EDR Hist Cleaners.

Findings of Interest

The Subject Property was not listed in any of the databases searched by EDR.

The addresses listed in the databases are normally the administrative or reporting address of the institution or business involved. As a result, the EDR Report may exclude sites for which the official address is outside the search radius.

7

1. The NPL, better known as the list of Superfund sites, are those sites identified by USEPA under CERCLA as requiring immediate action. The sites are ranked according to the potential for harm to the environment and the risk to the population.

There are no NPL sites reported within a 1.0-mile radius.

2. The SEMS database tracks hazardous waste sites, potentially hazardous waste sites, and sites where through the Superfund Program, remedial activities were performed. This database also contains sites which are either proposed to or on the NPL.

There is one (1) SEMS site reported within a 0.5-mile radius:

Ironwood MGP Site NW Corner of Hemlock St and Ayer St Ironwood, MI 49938 Site ID: 0510500

3. The CORRACTS system tracks hazardous waste handlers with RCRA corrective action activity.

There are no CORRACTS sites reported within a 1.0-mile radius.

4. RCRA-TSDF is the Federal Act, which tracks generators of hazardous waste. The database contains information on facilities which generate, transport, treat, store, and/or dispose of hazardous waste.

There are no RCRA-TSDF sites reported within a 0.5-mile radius.

5. USEPA RCRA generators list includes information on sites that generate, transport, store, treat, and/or dispose of hazardous waste. RCRA-LQG generate over 1,000 kilograms (kg) of hazardous waste or over 1 kg of acutely hazardous waste per month. RCRA-SQG generate between 100 kg and 1,000 kg of hazardous waste per month. Lastly, RCRA-CESQG generate less than 100 kg of hazardous waste or less than 1 kg of acutely hazardous waste per month.

There are no RCRA-LQG sites reported within a 0.25-mile radius.

There are no RCRA-SQG sites reported within a 0.25-mile radius.

There are ten (10) RCRA-CESQG sites reported within a 0.25-mile radius:

Globe Publishing 118 E McLeod Ave Ironwood, MI 49938 Quality Collision Center 315 W McLeod Ave Ironwood, MI 49938

Ironwood Dye Works 122 W Aurora St Ironwood, MI 49938

Genes Service and Radiator Inc. 200 W Aurora St Ironwood, MI 49938

Lahti, Inc. 111 S Lowell St Ironwood, MI 49938

GTC Auto Parts (Carquest) 114 W Ayer St Ironwood, MI 49938

Backstreet Cycle & Machine 101 E Vaughn St Ironwood, MI 49938

Downtown Auto Paint & Collision 111 S Lawrence St Ironwood, MI 49938

Michigan Bell Telephone Company 100 W Frederick St Ironwood, MI 49938

Harbor Imports 200 E Frederick St Ironwood, MI 49938

6. ERNS is the USEPA database of sudden and/or accidental releases of hazardous substances or petroleum.

The Subject Property is not listed in the ERNS database.

7. EGLE lists all registered USTs and ASTs. These include all active, non-exempt tanks. Sites with ASTs and/or with USTs, which have not been used since 1988 or are exempt, may not be included. These sites are significant, as they may be a potential REC.

There are ten (10) MI UST sites reported within a 0.25-mile radius:

Steves Standard Service 141 E McLeod Ave Ironwood, MI 49938

Status: Closed - Removed from Ground

Penrose Service 201 E Mcleod Ave Ironwood, MI 49938

Status: Closed - Removed from Ground

Forslund Building Supply 215 E Aurora St Ironwood, MI 49938

Status: Closed - Removed from Ground

Sass Tire & Auto 300 E McLeod Ave Ironwood, MI 49938 Status: Closed in Ground

Genes Service & Radiator Inc 200 W Aurora St Ironwood, MI 49938 Status: Closed – Removed from Ground

Sylvester J. Pawlak 400 S Lowell St Ironwood, MI 49938 Status: Closed – Removed from Ground

Lahti-Chev-Cadillac 111 S Lowell St Ironwood, MI 49938 Status: Closed – Removed from Ground

Gotta Motors, Inc. 237 E Ayer St Ironwood, MI 49938 Status: Closed – Removed from Ground

Ironwood Co (M29445) 100 W Frederick St Ironwood, MI 49938 Status: Currently in Use Reds Auto of Ironwood 200 E Frederick St Ironwood, MI 49938

Status: Closed - Removed from Ground

There is one (1) MI AST site reported within a 0.25-mile radius:

Chums Service 330 W Aurora St Ironwood, MI 49938

Status: Closed – Removed from Premises

8. EGLE maintains a list of the LUST Incident Reports. This list includes only those tanks that, for some reason, have been found to be leaking and have been reported to the EGLE. Most leaking tanks are not easily detected without subsurface exploration.

Leaking tanks can be a source of environmental concern since soil and groundwater could potentially be contaminated by a release of product into the environment. A property could also become impacted by such release due to contaminated groundwater migrating from an off-site LUST site. The probability that the Subject Property was affected includes many variables, including but not limited to the direction of groundwater flow, the location of the release, the type of product released, and the amount of product released. Determination of whether an off-site LUST facility has impacted the Subject Property is beyond the scope of this assessment.

There are two (2) MI LUST sites reported within a 0.5-mile radius:

NSP-Ironwood 101 Alfred Wright Blvd Ironwood, MI 49938 Status: Closed

Leak ID: C-0442-95

Range Can Depository 412 Cedar St Ironwood, MI 49938 Status: Open

Leak ID: C-1157-95

9. MI SWF/LF list contains an inventory of solid waste disposal facilities or landfills that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

There are no MI SWF/LF sites reported within a 0.5-mile radius.

10. EGLE INVENTORY contains facilities from three (3) data sources: 1.) Facilities (contaminated sites) under Part 201, Environmental Remediation, Natural Resources Environmental Protect Act, 1994 PA 451, as amended, (NREPA) identified through response activities; 2.) Facilities under Part 213, Leaking Underground Storage Tanks of the NREPA; or 3.) Facilities identified through the Baseline Environmental Assessment (BEA) submittal process.

There are five (5) MI INVENTORY sites reported within a 0.5-mile radius:

Former Josephson Nursing Home 634 E Ayer St Ironwood, MI 49938 Data Source: BEA

Newman Professional Building – Parcel B (Coleman Engineering Co.) 200 E Ayer St Ironwood, MI 49938 Data Source: BEA

Railroad Corridor #9
Former Chicago & Northwestern Railroad between Lowell and Curry Ironwood, MI 49938
Data Source: Part 201

Ironwood MGP Corner of Hemlock St and Ayer St Ironwood, MI 49938 Data Source: Part 201

Range Can Depository 412 Cedar St Ironwood, MI 49938 Data Source: Part 213

There is one (1) additional Part 201 Facility listed within a 1.0-mile radius:

City of Ironwood Landfill Landfill Road Ironwood, MI 49938

11. EGLE Activity Use Limitations (MI AUL) list includes sites with institutional and/or engineering controls set in place.

There are no MI AUL sites reported within a 0.5-mile radius.

Additional Environmental Records

Michigan Delisted Part 201 (MI DEL PART 201): A deleted site has been removed from the Part 201 List because information known to EGLE at the time of evaluation does not support inclusion on the Part 201 list.

There are two (2) MI DEL PART 201 sites within a 1.0-mile radius:

Fuel Oil Spill 114 E Aurora St Ironwood, MI 49938

Heating Oil Release 143 Rowe St Ironwood, MI 49938

RCRA NonGen/NLR: The database includes selective information from RCRA and the Hazardous and Solid Waste Amendments (HSWA) on sites which do not presently generate, transport, store, and/or dispose of hazardous waste.

There are three (3) RCRA NonGen/NLR sites within a 0.25-mile radius:

Ironwood Cleaners 323 S Lowell St Ironwood, MI 49938

Automotive Parts Headquarters 216 W Aurora St Ironwood, MI 49938

Ironwood MTRS 235 E Ayer St Ironwood, MI 49938

MI DRYCLEANERS: a listing of drycleaners in Michigan.

There is one (1) MI DRYCLEANERS site within a 0.25-mile radius:

Ironwood Cleaners 323 S Lowell St Ironwood, MI 49938

MN MANIFEST: A listing of hazardous waste manifest data from Minnesota.

There are eight (8) MN MANIFEST sites within a 0.25-mile radius:

Globe Publishing 118 E McLeod Ave Ironwood, MI 49938

Quality Collision Center 315 W McLeod Ave Ironwood, MI 49938

Ironwood Dye Works 122 W Aurora St Ironwood, MI 49938

Genes Service & Radiator Shop 200 W Aurora St Ironwood, MI 49938

Lahti Chevrolet Cadillac 111 S Lowell St Ironwood, MI 49938

Backstreet Cycle & Machine 101 E Vaughn St Ironwood, MI 49938

Downtown Auto Paint & Collision 111 S Lawrence St Ironwood, MI 49938

Gotta Motors, Inc. 235 E Ayer St Ironwood, MI 49938

EDR MGP: An EDR Proprietary Manufactured Gas Plant Database which includes records of coal gas plants compiled by EDR researchers.

There is one (1) EDR MGP site reported within a 1.0-mile radius:

Ironwood Gasworks W Ayer and S Hemlock Streets Ironwood, MI 49938 EDR Hist Auto: A listing of gas stations, filling stations, and service stations provided by EDR researchers.

There is four (4) EDR Hist Auto site within a 0.125-mile radius:

Tony & Petes Standard Service McLeod Ave & S Suffolk St Ironwood, MI 49938

Lawrence E Boyer 201 E Mcleod Ave at Suffolk St Ironwood, MI 49938

Genes Service & Radiator Inc 200 W Aurora St Ironwood, MI 49938

Auvinens Service Center 400 S Lowell St Ironwood, MI 49938

EDR Hist Cleaners: A listing of potential dry cleaner sites provided by EDR researchers.

There are four (4) EDR Hist Cleaner sites within a 0.125-mile radius:

Peter Schutte 310 S Suffolk St Ironwood, MI 49938

HJalmer A Setterlund 211 E McLeod Ave Ironwood, MI 49938

Ironwood Dye Works 122 W Aurora St Ironwood, MI 49938

Ironwood Cleaners & Laundromat 323 S Lowell St Ironwood, MI 49938

4.2 Historical Aerial Photographs

The historical aerial photographs from 1938, 1951, 1953, 1966, 1975, 1980, 1992, 1999, 2006, 2010, 2013, and 2016 are presented in Appendix C. A review of the photographs yielded the following:

1938 Aerial Photograph

The 1938 aerial photo shows that downtown Ironwood has been developed. Aurora Street, Lowell Street, McLeod Avenue, and Lawrence Street are all present along with the northeast-southwest oriented alley which bisects the Subject Property. Furthermore, the Curry Hotel and St. Michaels Church are present on the Subject Property. Lastly, the area to the south appears to be largely impacted by the former mining industry.

1951 Aerial Photograph

The 1951 aerial photo, although similar, is of much better quality than the 1938 aerial and clearly shows the existence of many buildings on and around the Subject Property. These buildings include the Curry Hotel, domiciles and their associated garages, and the St. Michaels Catholic Church. In addition to the buildings within the Subject Property, the block includes a filling station, restaurants, stores, a 75-car garage, and a movie theatre.

1953 Aerial Photograph

The 1953 aerial photo appears unchanged from the 1951 aerial photo.

1966 Aerial Photograph

Although the 1966 aerial photo is of very poor quality, it appears that the Curry Hotel no longer exists.

1975 Aerial Photograph

The Subject Property in the 1975 aerial photo proves that the Curry Hotel was demolished. In addition, it looks as if some of the domiciles and additional buildings near the Subject Property have been removed

1980 Aerial Photograph

The 1980 aerial photo appears primarily unchanged from the 1975 aerial.

1992 Aerial Photograph

The 1992 aerial photo shows that additional buildings on and around the Subject Property have been demolished. The aerial also shows that the Ironwood Public Safety Building has been constructed.

1999 Aerial Photograph

The 1999 aerial photo shows the Subject Property in a similar layout as it is today. The Flagstar Bank (p/k/a Wells Fargo) and Pamida are in operation to the southwest of the Subject Property. Furthermore, the building, which was formerly an auto service center, has been demolished. This building was located to the northeast of the Subject Property, on the northern corner of the McLeod Avenue and Lowell Street intersection.

2006 Aerial Photograph

The Subject Property in the 2006 aerial photo appears unchanged from the 1999 aerial photo; however, the building formerly located on the southern corner of the McLeod Avenue and Lowell Street intersection is no longer present.

2010 Aerial Photograph

The 2010 aerial photo appears primarily unchanged from the 2006 aerial photo except that the Floors N' Mor building appears to have an updated roof.

2013 Aerial Photograph

The 2013 aerial photo appears primarily unchanged from the 2010 aerial photo.

2016 Aerial Photograph

The Subject Property in the 2016 aerial photo exists as it does currently.

4.3 Sanborn Maps

The Sanborn Report provided by EDR is attached in Appendix D. This report contains Sanborn (fire insurance) maps from 1888, 1898, 1908, 1921, 1928, and 1946. A review of these maps yielded the following:

1888 Sanborn Map

The 1888 Sanborn Map shows that six (6) structures existed on the Subject Property which were utilized as a furniture store, stable, and warehouse; a garage, shed, and the Rockland House, which is presumably a hotel. The map also shows the existence of the four (4) surrounding streets, except

for what is currently McLeod Avenue was formerly referred to as Ashland Street. In addition to the Subject Property, Block 30 included dwellings, a meat store, and a blacksmith.

1898 Sanborn Map

The 1898 Sanborn Map shows the addition of the Curry Hotel and the Polish Catholic Church on the Subject Property. Other buildings and businesses were constructed which included a blacksmith (changed location), a wagon and paint shop, a carriage warehouse, a kindergarten, the Davis Hotel, a grocery store, a women's hat store, coal and wood sheds, and additional dwelling units.

1908 Sanborn Map

The Subject Property in the 1908 Sanborn Map appears primarily unchanged. Some of the off-site properties within Block 30 seem to have changed operations. The wagon and paint shop and blacksmith are shown as a carpenter shop, the kindergarten building houses a saloon, and the women's hat store appears to be a sample room.

1921 Sanborn Map

The Subject Property in the 1921 Sanborn Map appears similar to the 1908 Sanborn. The map, however, shows the addition of a movie theatre adjacent to the Subject Property. Furthermore, the grocery store and carpenter shop have expanded, and the saloon is labeled as a meat store. Lastly, the building on the north corner of the Lowell Street and McLeod Avenue intersection acts as an automotive repair shop and has one (1) 550-gallon gasoline UST buried in McLeod Avenue.

1928 Sanborn Map

Although the Subject Property appears unchanged, there have been transformations to Block 30 in the 1928 Sanborn Map. The former carpenter shop on the western corner of Block 30 is shown as a filling station with three (3) gasoline tanks. An auto repair shop appears on the southern corner of Lot 7, which also has a gasoline tank. The uses of the remaining large structures are not specified as they all appear to be stores except for the dwelling units.

1946 Sanborn Map

The 1946 Sanborn Map again shows that the Subject Property is primarily unchanged from the 1928 Sanborn. Some of the structures previously shown as stores within Block 30 appear to be restaurants. Additionally, Lots 6 and 7 have undergone changes, as it appears that a 75-car garage exists. Part of this structure is presumably used for auto repair and a saloon on separate floors with a fire escape and an adjacent restaurant.

5.0 SITE RECONNAISSANCE

The site reconnaissance serves several purposes. It allows the investigator to gain first-hand knowledge of the property. Only by a site reconnaissance can the investigator observe the property for signs of environmental concern, such as stained soils/buildings or stressed vegetation. A site walkover also allows the investigator to correlate historical record information with current site conditions and may provide for identification of items requiring further investigation.

Mr. Michael Gotham conducted the reconnaissance of the property on August 27, 2019. The weather was overcast with a temperature of 65° Fahrenheit. The walkover included observations of current use and indications of the prior use of the Subject Property and, to a limited extent, adjoining properties. Please note, however, that because portions of the building are collapsed, the site reconnaissance was limited to areas that were deemed safe.

5.1 Subject Property Site Reconnaissance

The Subject Property is shown in Appendix A as Figure 1 – Project Location Map and Figure 2 – Aerial Photo. Site photographs are included in Appendix E. The Subject Property consists of an approximately 0.753-acre site in the City of Ironwood, Michigan.

The Subject Property is situated within Block 30 of the original plat between Aurora Street, Lowell Street, McLeod Avenue, and Lawrence Street. The northern portion of the Subject Property (Lots 1 through 3 and part of 4) is an asphalt parking lot used by Mainstreet Fitness customers. On the south and east side of the alley, which bisects the Subject Property, is primarily a gravel parking lot (Lots 14 through 17 and parts of 18 and 19) with a small grassy area in the southwestern portion of Lot 14. There are no structures on the Subject Property, but evidence of former Curry Hotel's footprint remains in the asphalt.

There were no observations of grave environmental concern; however, small areas of staining, less than 1 square foot, were observed on the asphalt from minor leaks automobile fluid.

5.1.1 Buildings

There are no buildings on the Subject Property.

5.1.2 Vacant Property

The entirety of the Subject Property is currently vacant as it is used for automobile parking only.

5.2 Additional Site Information

5.2.1 Utilities

- Electric power is supplied by Xcel Energy.
- Natural Gas is supplied by Xcel Energy.

- Sewer is handled by the City of Ironwood.
- Water is supplied by the City of Ironwood.
- Telecommunication service in the area is provided by Charter Communications.

5.2.2 Hazardous Substance/Waste Storage

There were no observations of hazardous substances or petroleum compounds stored on the Subject Property.

5.2.3 Underground Storage Tanks (UST)

There are no USTs at the Subject Property, nor are there any records of former USTs associated with the property.

5.2.4 Aboveground Storage Tanks (ASTs)

There were no indications of ASTs on the Subject Property.

5.2.5 Solid Waste Disposal

No dumpsters or solid waste containers were observed at the Subject Property; however, solid waste disposal is handled by Eagle Waste and Recycling, Inc.

5.2.6 Stormwater

Stormwater on the property migrates overland flow into the City of Ironwood's stormwater system.

5.2.7 Water Wells

There are no private water wells on or near the Subject Property.

5.2.8 Polychlorinated biphenyls (PCBs)

PCBs are a potential carcinogen formerly used in the dielectric fluid in transformers. The USEPA has ruled that in concentrations above 50 parts per million, PCBs are considered hazardous. Electric utility companies have been testing the transformer oil and labeling the transformers accordingly. Utility companies are responsible for releases of hazardous substances from transformers. There is an overhead powerline within the alleyway easement; however, according to its apparent age, it is determined that the electrical components do not contain PCB.

5.2.9 Air Permits

No air permits were issued for the Subject Property.

6.0 INTERVIEWS

6.1 Site Owner/Representative

On August 28, 2019, Mr. Steve Lahti, Property Owner, was contacted regarding the Subject Property. Mr. Lahti stated that he began renting the Subject Property in 1992 until he took ownership in 2005. He mentioned that Lahti's, Inc. formerly used the asphaltic portion of the property as a new car lot until 2006, approximately. Since then, it has been used strictly for general parking. Mr. Lahti said that the asphaltic surface is maintained on a regular basis and that it was last resurfaced two (2) years ago. He asserted that there were no spills or releases of petroleum compounds or hazardous substances during his tenure, and he is unaware of any environmental issues prior to 1992.

6.2 State Government

In addition to State databases reviewed by EDR, the local EGLE field offices were contacted to determine if any problems have arisen in the vicinity of the Subject Property after the development of the databases, or if any are known to exist but not included in the database

The following State regulatory official was contacted concerning known environmental concerns on or near the Subject Property:

On August 28, 2019, Mr. Steve Harrington, EGLE Remediation and Redevelopment Division Project Manager, was contacted regarding the Subject Property. Mr. Harrington searched through EGLE storage tank databases but found nothing associated with the Subject Property. Mr. Harrington found no records of contamination from the existence or removal of the USTs.

6.3 County and Local Government

Attempts were made to contact Mr. Brandon Snyder, Fire Marshall, and Mr. Andrew DiGiorgio, Public Safety Director, but the efforts were unsuccessful.

6.4 Other Knowledgeable Persons

Refer to Appendix F for the User Questionnaire completed by the City of Ironwood.

7.0 NON-SCOPE ISSUES

There are no known non-scope issues associated with the property.

8.0 FINDINGS

CEC has performed a Phase I ESA in conformance with the Scope and Limitations of ASTM E 1527-13 Standard Practice for Environmental Site Assessments: Phase I Environmental

Site Assessment Process at the Subject Property. Any exceptions or deletions from the ASTM E 1527-13 practice are revealed in Section 1.0 of this report.

This assessment has revealed two (2) potential RECs associated with the Subject Property:

- Adjacent properties, or properties in proximity to the Subject Property within Block 30, were formerly used as automobile repair shops or filling stations during the early 20th Century. The Sanborn Maps attached in Appendix D show evidence of gasoline storage tanks in association with these facilities. Petroleum storage tanks, especially those used during the 20th Century, were notorious for corroding and releasing their contents into the environment.
- The Ironwood Dye Works property was located at 122 W. Aurora Street separated only by Aurora Street from the Subject Property. Clothing dye chemicals used in the past contained hazardous substances (e.g., chlorinated solvents), which if not stored or disposed of properly, have the potential to cause risk to human health and the environment in the event of a release.

Although ASTM E 1527-13 Standard does not require a demonstration of appropriate inquiry beyond scope considerations, there may be standards or protocols for assessment of potential hazards and conditions associated with beyond scope conditions developed by government entities, professional organizations, or other private entities.

No efforts have been expended to investigate the potential for off-site, third-party impacts. Further investigation of REC's may require site sampling and analysis. These activities are all beyond the defined scope of this investigation. The Client may, however, wish to undertake these activities. Only the Client is capable of determining the relevancy of information presented and the need to pursue items of concern further. Qualifications of Environmental Professionals conducting this assessment are provided as Appendix H. Additional Limitations are provided in Appendix I.

9.0 OPINIONS

It is the opinion of CEC that there are no RECs associated with the Subject Property, as defined in ASTM E 1527-13.

10.0 CONCLUSIONS

CEC has performed a Phase I ESA in conformance with the Scope and Limitations of ASTM E 1527-13 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process at the Lahti Property, which can be described as Lots 1, 2, 3, the East 19 ½ feet of Lot 4; Lots 14, 15, 16, 17, the West 12 feet of the South 68 feet and the North 72 feet of Lot 18, and the West 12 feet of the North 72 feet of Lot 19, all within Block 30, City of Ironwood,

Gogebic County, Michigan. Any exceptions or deletions from this practice are revealed in Section 11.0 of this report. Throughout the process of this Phase I ESA, no RECs were confirmed.

Although ASTM E 1527-13 Standard does not require a demonstration of appropriate inquiry beyond scope considerations, there may be standards or protocols for assessment of potential hazards and conditions associated with beyond scope conditions developed by government entities, professional organizations, or other private entities.

No efforts have been expended to investigate the potential for off-site, third-party impacts. Further investigation of REC's may require site sampling and analysis. These activities are all beyond the defined scope of this investigation. The Client may, however, wish to undertake these activities. Only the Client is capable of determining the relevancy of information presented and the need to pursue items of concern further. Qualifications of Environmental Professionals conducting this assessment are provided as Appendix H. Additional Limitations are provided in Appendix I.

11.0 **DEVIATIONS**

CEC has performed this Phase I ESA in substantial conformance with the scope and limitations of ASTM Standard E 1527-13. During completion of this Phase I ESA, CEC conducted a site reconnaissance, interviews with those familiar with the Subject Property, a historical records review, and an environmental database review. There were no deviations, exceptions to or deletions from the referenced ASTM E 1527-13. Refer to Appendix I for additional limitations.

12.0 REFERENCES

EDR, August 1, 2019. The Environmental EDR Report for the Lahti Property, City of Ironwood, Michigan.

Aerial Photography from EDR, June 19, 2018.

Sanborn Maps from EDR, June 19, 2018.

Interviews/Contacts

Mr. Steve Lahti, Owner, Lahti's, Inc.


Mr. Scott Erickson, City Manager, City of Ironwood

Mr. Steve Harrington, Remediation and Redevelopment Division, EGLE

APPENDIX A

FIGURES

Figure 1 – Project Location Map Figure 2 – Site Aerial Photo






FIGURE 1 - PROJECT LOCATION MAP

CITY OF IRONWOOD

LAHTI PROPERTY - PHASE I ENVIRONMENTAL SITE ASSESSMENT

IRONWOOD, MI



DATE 8/29/2019 JOB NO 190668 CADD FILE 190668-WIW-WIQ.DWG

PDF FILE 190668-WIW-WIQ.PDF




FIGURE 2 - AERIAL PHOTO

CITY OF IRONWOOD

LAHTI PROPERTY - PHASE I ENVIRONMENTAL SITE ASSESSMENT IRONWOOD, MI



DATE 8/29/2019 JOB NO 190668

CADD FILE 190668-AERIAL.DWG PDF FILE 190668-AERIAL.PDF

APPENDIX B ENVIRONMENTAL DATA RESOURCES REPORT

Lahti Property

Mcleod Ave, Lowell St, and Aurora St Ironwood, MI 49938

Inquiry Number: 5737107.2s

August 01, 2019

EDR Summary Radius Map Report



6 Armstrong Road, 4th floor Shelton, CT 06484 Toll Free: 800.352.0050 www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map.	2
Detail Map.	3
Map Findings Summary.	4
Map Findings.	8
Orphan Summary	
Government Records Searched/Data Currency Tracking	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings.	A-8
Physical Setting Source Records Searched	PSGR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2019 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-13), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E 2247-16), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E 1528-14) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

MCLEOD AVE, LOWELL ST, AND AURORA ST IRONWOOD, MI 49938

COORDINATES

Latitude (North): 46.4532560 - 46° 27' 11.72" Longitude (West): 90.1697440 - 90° 10' 11.07"

Universal Tranverse Mercator: Zone 15 UTM X (Meters): 717359.2 UTM Y (Meters): 5148084.0

Elevation: 1511 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property: TF

Source: U.S. Geological Survey

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from: 20150709 Source: USDA

MAPPED SITES SUMMARY

Target Property Address: MCLEOD AVE, LOWELL ST, AND AURORA ST IRONWOOD, MI 49938

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
A1	IRONWOOD DYE WORKS	122 W AURORA ST	RCRA-CESQG, FINDS, ECHO	Lower	67, 0.013, NW
A2	IRONWOOD DYE WORKS	122 W AURORA ST	EDR Hist Cleaner	Lower	67, 0.013, NW
A3	IRONWOOD DYE WORKS	122 W AURORA ST	MN MANIFEST	Lower	67, 0.013, NW
A4	114 E. ARORA ST, FUE	114 E. ARORA STREET	MI DEL PART 201	Higher	139, 0.026, North
B5	IRONWOOD CLEANERS	323 S LOWELL ST	MI DRYCLEANERS, MI WDS	Lower	172, 0.033, ESE
B6	IRONWOOD CLEANERS	323 S LOWELL ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	172, 0.033, ESE
B7	IRONWOOD CLEANERS &	323 S LOWELL ST	EDR Hist Cleaner	Lower	172, 0.033, ESE
B8	GLOBE PUBLISHING	118 E MCLEOD AVE	RCRA-CESQG, FINDS, ECHO	Higher	202, 0.038, East
B9	GLOBE PUBLISHING	118 E MCLEOD AVE	MN MANIFEST	Higher	202, 0.038, East
C10	GENES SERVICE & RADI	200 W AURORA ST	MN MANIFEST	Lower	277, 0.052, WSW
C11	GENES SERVICE AND RA	200 W AURORA ST	RCRA-CESQG, FINDS, ECHO	Lower	277, 0.052, WSW
C12	GENES SERVICE & RADI	200 W AURORA STREET	EDR Hist Auto	Lower	277, 0.052, WSW
B13	STEVES STNADARD SERV	141 E MCLEOD AVE	MIUST	Higher	302, 0.057, East
C14	AUTOMOTIVE PARTS HEA	216 W AURORA ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	309, 0.059, WSW
C15	GENES SERVICE & RADI	200 WAURORA ST	MI UST	Lower	338, 0.064, West
D16	LAHTI CHEVROLET CADI	111 S LOWELL ST	MN MANIFEST	Lower	362, 0.069, NNW
D17	LAHTI INC	111 S LOWELL ST	RCRA-CESQG	Lower	362, 0.069, NNW
D18	GTC AUTO PARTS (CARQ	114 W AYER ST	RCRA-CESQG, FINDS, ECHO	Lower	423, 0.080, NW
E19	SYLVESTER J. PAWLAK	400 S LOWELL ST	MI UST	Lower	431, 0.082, SE
E20	AUVINEN TOM SERVICE	400 S LOWELL ST	EDR Hist Auto	Lower	431, 0.082, SE
E21	BACKSTREET CYCLE & M	101 E VAUGHN ST	RCRA-CESQG, FINDS, ECHO	Lower	434, 0.082, SE
E22	BACK STREET CYCLE &	101 E VAUGHN ST	MN MANIFEST	Lower	434, 0.082, SE
F23	DOWNTOWN AUTO PAINT	111 S LAWRENCE ST	RCRA-CESQG, FINDS, ECHO	Lower	471, 0.089, WNW
F24	DOWNTOWN AUTO PAINT	111 S LAWRENCE ST	MN MANIFEST	Lower	471, 0.089, WNW
G25	TONY & PETES STANDAR	MC LEOD & S SUFFOLK	EDR Hist Auto	Higher	535, 0.101, ENE
G26	PENROSE SERVICE	201 E MCLEOD AVE	MIUST	Higher	554, 0.105, ENE
G27	BOYER LAWRENCE E	201 E MC LEOD AT SUF	EDR Hist Auto	Higher	554, 0.105, ENE
D28	LAHTI-CHEV-CADILLAC	NO ADDRESS	MIUST	Lower	565, 0.107, NNW
G29	SCHUTTE PETER	310 SO SUFFOLK ST	EDR Hist Cleaner	Higher	569, 0.108, ENE
30	FORSLUND BUILDING SU	215 E AURORA ST	MIUST	Higher	580, 0.110, NE
G31	SETTERLUND HJALMER A	211 E MC LEOD AVE	EDR Hist Cleaner	Higher	596, 0.113, ENE
H32	NEWMAN PROFESSIONAL	200 EAST AYER STREET	MI INVENTORY, MI BEA	Lower	648, 0.123, North
H33	IRONWOOD MTRS	235 E AYER ST	RCRA NonGen / NLR, FINDS, ECHO	Lower	770, 0.146, NNE
H34	GOTTA MOTORS	235 E AYER ST	MN MANIFEST	Lower	770, 0.146, NNE
H35	GOTTA MOTORS INC	237 E AYER ST	MIUST	Lower	778, 0.147, NNE
36	CHUMS SERVICE	330 W AURORA	MI AST	Higher	789, 0.149, WSW
137	MICHIGAN BELL TELEPH	100 W FREDERICK ST	RCRA-CESQG, FINDS, ECHO	Lower	830, 0.157, NW
138	IRONWOOD CO (M29445)	100 W FREDERICK ST	MIUST	Lower	830, 0.157, NW
J39	REDS AUTO OF IRONWOO	200 E FREDERICK ST	MI UST	Lower	942, 0.178, North

MAPPED SITES SUMMARY

Target Property Address: MCLEOD AVE, LOWELL ST, AND AURORA ST IRONWOOD, MI 49938

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
J40	HARBOR IMPORTS	200 E FREDERICK ST	RCRA-CESQG	Lower	942, 0.178, North
K41	QUALITY COLLISION CE	315 W MCLEOD AVE	RCRA-CESQG, FINDS, ECHO	Higher	975, 0.185, SW
K42	QUALITY COLLISION CE	315 W MCLEOD AVE	MN MANIFEST	Higher	975, 0.185, SW
43	SASS TIRE & AUTO	300 E MCLEOD AVE	MI UST	Higher	979, 0.185, ENE
44	RAILROAD CORRIDOR #9	FORMER CHICAGO & NOR	MI INVENTORY, MI PART 201	Lower	1523, 0.288, NNE
45	NSP-IRONWOOD	101 ALFRED WRIGHT BL	MI LUST, MI UST, MI WDS	Lower	1738, 0.329, SSE
L46	IRONWOOD GAS WORKS	W. AYER AND S. HEMLO	EDR MGP	Lower	1825, 0.346, WSW
L47	IRONWOOD MGP SITE	NW CORNER OF HEMLOCK	SEMS, PRP	Lower	1825, 0.346, WSW
L48	IRONWOOD MGP	ON MONRTREAL RIVER,	MI INVENTORY	Lower	1957, 0.371, WSW
49	RANGE CAN DEPOSITORY	412 CEDAR ST	MI LUST, MI UST, MI INVENTORY	Lower	2208, 0.418, WSW
50	FORMER JOSEPHSON NUR	634 EAST AYER STREET	MI INVENTORY, MI BEA	Higher	2583, 0.489, NE
51	IRONWOOD LF CITY OF	LANDFILL RD	MI INVENTORY, MI PART 201	Higher	3399, 0.644, East
52	143 ROWE ST, HEATING	143 ROWE STREET	MI DEL PART 201	Higher	4129, 0.782, ENE

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in **bold italics** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal CERCLIS list

SEMS: A review of the SEMS list, as provided by EDR, and dated 04/11/2019 has revealed that there is 1 SEMS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
IRONWOOD MGP SITE Site ID: 0510500 EPA Id: MIN000510500	NW CORNER OF HEMLOCK	WSW 1/4 - 1/2 (0.346 mi.)	L47	18

Federal RCRA generators list

RCRA-CESQG: A review of the RCRA-CESQG list, as provided by EDR, and dated 03/25/2019 has revealed that there are 10 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
GLOBE PUBLISHING EPA ID:: MID985610286	118 E MCLEOD AVE	E 0 - 1/8 (0.038 mi.)	B8	9
QUALITY COLLISION CE EPA ID:: MIR000020545	315 W MCLEOD AVE	SW 1/8 - 1/4 (0.185 mi.)	K41	17
Lower Elevation	Address	Direction / Distance	Map ID	Page
IRONWOOD DYE WORKS EPA ID:: MID985622109	122 W AURORA ST	NW 0 - 1/8 (0.013 mi.)	A1	8
GENES SERVICE AND RA	200 W AURORA ST	WSW 0 - 1/8 (0.052 mi.)	C11	10

EPA ID:: MID017152968				
LAHTI INC EPA ID:: MID017153313	111 S LOWELL ST	NNW 0 - 1/8 (0.069 mi.)	D17	11
GTC AUTO PARTS (CARQ EPA ID:: MIR000028217	114 W AYER ST	NW 0 - 1/8 (0.080 mi.)	D18	12
BACKSTREET CYCLE & M EPA ID:: MIR000046888	101 E VAUGHN ST	SE 0 - 1/8 (0.082 mi.)	E21	12
DOWNTOWN AUTO PAINT EPA ID:: MID038759874	111 S LAWRENCE ST	WNW 0 - 1/8 (0.089 mi.)	F23	13
MICHIGAN BELL TELEPH EPA ID:: MID982633141	100 W FREDERICK ST	NW 1/8 - 1/4 (0.157 mi.)	137	16
HARBOR IMPORTS EPA ID:: MIK452579691	200 E FREDERICK ST	N 1/8 - 1/4 (0.178 mi.)	J40	17

State and tribal leaking storage tank lists

MI LUST: A review of the MI LUST list, as provided by EDR, and dated 05/03/2019 has revealed that there are 2 MI LUST sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
NSP-IRONWOOD Release Status: Closed Substance Release: Gasoline,Unknown Facility Id: 00016234	101 ALFRED WRIGHT BL	SSE 1/4 - 1/2 (0.329 mi.)	45	18
RANGE CAN DEPOSITORY Release Status: Open Substance Release: Gasoline Facility Id: 00038008	412 CEDAR ST	WSW 1/4 - 1/2 (0.418 mi.)	49	19

State and tribal registered storage tank lists

MI UST: A review of the MI UST list, as provided by EDR, has revealed that there are 10 MI UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
STEVES STNADARD SERV Database: UST, Date of Government Tank Status: Removed from Ground Facility Type: CLOSED Facility Id: 00003652		E 0 - 1/8 (0.057 mi.)	B13	10
PENROSE SERVICE Database: UST, Date of Government Tank Status: Removed from Ground Facility Type: CLOSED		ENE 0 - 1/8 (0.105 mi.)	G26	13

Facility Id: 00007508 FORSLUND BUILDING SU 215 E AURORA ST NE 0 - 1/8 (0.110 mi.) 30 14 Database: UST, Date of Government Version: 02/06/2019 Tank Status: Removed from Ground Facility Type: CLOSED Facility Id: 00014033 SASS TIRE & AUTO 300 E MCLEOD AVE ENE 1/8 - 1/4 (0.185 mi.) 17 43 Database: UST, Date of Government Version: 02/06/2019 Tank Status: Closed in Ground Facility Type: CLOSED Facility Id: 00007664 **Lower Elevation Address Direction / Distance** Map ID Page **GENES SERVICE & RADI** 200 WAURORA ST W 0 - 1/8 (0.064 mi.) C15 11 Database: UST, Date of Government Version: 02/06/2019 Tank Status: Removed from Ground Facility Type: CLOSED Facility Id: 00018110 SYLVESTER J. PAWLAK 400 S LOWELL ST SE 0 - 1/8 (0.082 mi.) E19 12 Database: UST, Date of Government Version: 02/06/2019 Tank Status: Removed from Ground Facility Type: CLOSED Facility Id: 00001830 LAHTI-CHEV-CADILLAC **NO ADDRESS** NNW 0 - 1/8 (0.107 mi.) D28 14 Database: UST, Date of Government Version: 02/06/2019 Tank Status: Removed from Ground Facility Type: CLOSED Facility Id: 00002903 **GOTTA MOTORS INC** 237 E AYER ST NNE 1/8 - 1/4 (0.147 mi.) H35 15 Database: UST, Date of Government Version: 02/06/2019 Tank Status: Removed from Ground Facility Type: CLOSED Facility Id: 00013536 IRONWOOD CO (M29445) 100 W FREDERICK ST NW 1/8 - 1/4 (0.157 mi.) 138 16 Database: UST, Date of Government Version: 02/06/2019 Tank Status: Removed from Ground Tank Status: Currently In Use Facility Type: ACTIVE Facility Id: 00011739 **REDS AUTO OF IRONWOO** N 1/8 - 1/4 (0.178 mi.) 200 E FREDERICK ST J39 16 Database: UST, Date of Government Version: 02/06/2019 Tank Status: Removed from Ground

Facility Type: CLOSED Facility Id: 00001504

MI AST: A review of the MI AST list, as provided by EDR, and dated 01/15/2019 has revealed that there is 1 MI AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
CHUMS SERVICE Facility Id: 92027205 Removed/Closed Date: 01/01/1994 Tank Status: Removed from Premises	330 W AURORA	WSW 1/8 - 1/4 (0.149 mi.)	36	16

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

MI INVENTORY: A review of the MI INVENTORY list, as provided by EDR, and dated 04/23/2019 has revealed that there are 5 MI INVENTORY sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FORMER JOSEPHSON NUR	634 EAST AYER STREET	NE 1/4 - 1/2 (0.489 mi.)	50	19
Lower Elevation	Address	Direction / Distance	Map ID	Page
NEWMAN PROFESSIONAL RAILROAD CORRIDOR #9 Facility ID: 27000031	200 EAST AYER STREET FORMER CHICAGO & NOR	N 0 - 1/8 (0.123 mi.) NNE 1/4 - 1/2 (0.288 mi.)	H32 44	15 18
IRONWOOD MGP Facility ID: 27000066	ON MONRTREAL RIVER,	WSW 1/4 - 1/2 (0.371 mi.)	L48	19
RANGE CAN DEPOSITORY Facility ID: 00038008	412 CEDAR ST	WSW 1/4 - 1/2 (0.418 mi.)	49	19

MI PART 201: A review of the MI PART 201 list, as provided by EDR, and dated 10/01/2013 has revealed that there are 2 MI PART 201 sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
IRONWOOD LF CITY OF Facility Status: Inactive - no actions take Facility ID: 27000004	LANDFILL RD en to address contamination	E 1/2 - 1 (0.644 mi.)	51	19
Lower Elevation	Address	Direction / Distance	Map ID	Page
RAILROAD CORRIDOR #9 Facility Status: Evaluation conducted Facility ID: 27000031	FORMER CHICAGO & NOR	NNE 1/4 - 1/2 (0.288 mi.)	44	18

MI DEL PART 201: A review of the MI DEL PART 201 list, as provided by EDR, and dated 08/01/2013 has revealed that there are 2 MI DEL PART 201 sites within approximately 1 mile of the target property. developed

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
114 E. ARORA ST, FUE Facility Id: 27000037	114 E. ARORA STREET	N 0 - 1/8 (0.026 mi.)	A4	8
143 ROWE ST, HEATING Facility Id: 27000053	143 ROWE STREET	ENE 1/2 - 1 (0.782 mi.)	52	20

Other Ascertainable Records

RCRA NonGen / NLR: A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 03/25/2019 has revealed that there are 3 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page	
IRONWOOD CLEANERS EPA ID:: MID985581156	323 S LOWELL ST	ESE 0 - 1/8 (0.033 mi.)	В6	9	
AUTOMOTIVE PARTS HEA EPA ID:: MID985617380	216 W AURORA ST	WSW 0 - 1/8 (0.059 mi.)	C14	11	
IRONWOOD MTRS EPA ID:: MID017153743	235 E AYER ST	NNE 1/8 - 1/4 (0.146 mi.)	H33	15	

MI BEA: A review of the MI BEA list, as provided by EDR, and dated 08/21/2013 has revealed that there are 2 MI BEA sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page	
FORMER JOSEPHSON NUR	634 EAST AYER STREET	NE 1/4 - 1/2 (0.489 mi.)	50	19	
Lower Elevation	Address	Direction / Distance	Map ID	Page	
NEWMAN PROFESSIONAL	200 EAST AYER STREET	N 0 - 1/8 (0.123 mi.)	H32	15	

MI DRYCLEANERS: A review of the MI DRYCLEANERS list, as provided by EDR, and dated 01/15/2019 has revealed that there is 1 MI DRYCLEANERS site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page	
IRONWOOD CLEANERS	323 S LOWELL ST	ESE 0 - 1/8 (0.033 mi.)	B5	8	
Establishment#: 2700002					
Establishment#: 2700001					

MN MANIFEST: A review of the MN MANIFEST list, as provided by EDR, and dated 06/30/2016 has revealed that there are 8 MN MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	qual/Higher Elevation Address		Map ID	Page	
GLOBE PUBLISHING	118 E MCLEOD AVE	E 0 - 1/8 (0.038 mi.)	B9	10	
QUALITY COLLISION CE	315 W MCLEOD AVE	SW 1/8 - 1/4 (0.185 mi.)	K42	17	
Lower Elevation	Address	Direction / Distance	Map ID	Page	
IRONWOOD DYE WORKS	122 W AURORA ST	NW 0 - 1/8 (0.013 mi.)	А3	8	
GENES SERVICE & RADI	200 W AURORA ST	WSW 0 - 1/8 (0.052 mi.)	C10	10	
LAHTI CHEVROLET CADI	111 S LOWELL ST	NNW 0 - 1/8 (0.069 mi.)	D16	11	
BACK STREET CYCLE &	101 E VAUGHN ST	SE 0 - 1/8 (0.082 mi.)	E22	13	
DOWNTOWN AUTO PAINT	111 S LAWRENCE ST	WNW 0 - 1/8 (0.089 mi.)	F24	13	
GOTTA MOTORS	235 E AYER ST	NNE 1/8 - 1/4 (0.146 mi.)	H34	15	

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
IRONWOOD GAS WORKS	W. AYER AND S. HEMLO	WSW 1/4 - 1/2 (0.346 mi.)	L46	18

EDR Hist Auto: A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 4 EDR Hist Auto sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page	
TONY & PETES STANDAR	MC LEOD & S SUFFOLK	ENE 0 - 1/8 (0.101 mi.)	G25	13	
BOYER LAWRENCE E	201 E MC LEOD AT SUF	ENE 0 - 1/8 (0.105 mi.)	G27	14	
Lower Elevation	Address	Direction / Distance	Map ID	Page	
Lower Elevation GENES SERVICE & RADI	Address 200 W AURORA STREET	Direction / Distance WSW 0 - 1/8 (0.052 mi.)	Map ID	Page 10	

EDR Hist Cleaner: A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 4 EDR Hist Cleaner sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page	
SCHUTTE PETER	310 SO SUFFOLK ST	ENE 0 - 1/8 (0.108 mi.)	G29	14	
SETTERLUND HJALMER A	211 E MC LEOD AVE	ENE 0 - 1/8 (0.113 mi.)	G31	14	
Lower Elevation	Address	Direction / Distance	Map ID	Page	
IRONWOOD DYE WORKS	122 W AURORA ST	NW 0 - 1/8 (0.013 mi.)	A2	8	

Lower Elevation	Address	Direction / Distance	Map ID	Page
IRONWOOD CLEANERS &	323 S LOWELL ST	ESE 0 - 1/8 (0.033 mi.)	B7	9


Database(s)	
Zip	
Site Address	
Site Name	
EDR ID	
City	

ORPHAN SUMMARY

Count: 0 records.

NO SITES FOUND

OVERVIEW MAP - 5737107.2S



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.


SITE NAME: Lahti Property
ADDRESS: Mcleod Ave, Lowell St, and Aurora St
Ironwood MI 49938

LAT/LONG: 46.453256 / 90.169744 CLIENT: Coleman Engi CONTACT: Mike Gotham Coleman Engineering Company

INQUIRY#: 5737107.2s

August 01, 2019 12:30 pm DATE:

DETAIL MAP - 5737107.2S



CLIENT: Coleman Engineering Company

default map view.

CONTACT: Mike Gotham INQUIRY#: 5737107.2s

DATE: August 01, 2019 12:33 pm

SITE NAME: Lahti Property

Mcleod Ave, Lowell St, and Aurora St Ironwood MI 49938 ADDRESS:

LAT/LONG: 46.453256 / 90.169744

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	Total Plotted
STANDARD ENVIRONMEN	TAL RECORDS							
Federal NPL site list								
NPL Proposed NPL NPL LIENS	1.000 1.000 1.000		0 0 0	0 0 0	0 0 0	0 0 0	NR NR NR	0 0 0
Federal Delisted NPL sit	te list							
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
FEDERAL FACILITY SEMS	0.500 0.500		0 0	0 0	0 1	NR NR	NR NR	0 1
Federal CERCLIS NFRA	P site list							
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
Federal RCRA CORRAC	TS facilities li	st						
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-COR	RACTS TSD fa	acilities list						
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generator	rs list							
RCRA-LQG RCRA-SQG RCRA-CESQG	0.250 0.250 0.250		0 0 7	0 0 3	NR NR NR	NR NR NR	NR NR NR	0 0 10
Federal institutional cor engineering controls re								
LUCIS US ENG CONTROLS US INST CONTROL	0.500 0.500 0.500		0 0 0	0 0 0	0 0 0	NR NR NR	NR NR NR	0 0 0
Federal ERNS list								
ERNS	0.001		0	NR	NR	NR	NR	0
State- and tribal - equiva	alent CERCLIS	;						
MI SHWS WI SHWS	1.000 1.000		0 0	0 0	0 0	0 0	NR NR	0 0
State and tribal landfill a solid waste disposal site								
MI SWF/LF WI SWF/LF	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
State and tribal leaking	storage tank li	sts						
MI LUST WI LUST	0.500 0.500		0 0	0 0	2 0	NR NR	NR NR	2 0

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
INDIAN LUST	0.500		0	0	0	NR	NR	0
State and tribal registere	d storage tar	nk lists						
FEMA UST MI UST WI UST MI AST WI AST INDIAN UST	0.250 0.250 0.250 0.250 0.250 0.250		0 6 0 0 0	0 4 0 1 0	NR NR NR NR NR	NR NR NR NR NR	NR NR NR NR NR NR	0 10 0 1 0
State and tribal institution control / engineering con		s						
MI AUL WI AUL	0.500 0.500		0	0 0	0 0	NR NR	NR NR	0 0
State and tribal voluntary	=	es						
INDIAN VCP	0.500		0	0	0	NR	NR	0
State and tribal Brownfie								
MI BROWNFIELDS WI BROWNFIELDS	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
ADDITIONAL ENVIRONMEN	TAL RECORDS	<u>s</u>						
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / S Waste Disposal Sites	olid							
MI SWRCY MI HIST LF WI SWRCY INDIAN ODI DEBRIS REGION 9 ODI IHS OPEN DUMPS	0.500 0.500 0.500 0.500 0.500 0.500 0.500		0 0 0 0 0 0	0 0 0 0 0 0	0 0 0 0 0 0	NR NR NR NR NR NR	NR NR NR NR NR NR	0 0 0 0 0 0
Local Lists of Hazardous Contaminated Sites	waste /							
US HIST CDL MI INVENTORY MI PART 201 MI CDL WI CDL MI DEL PART 201 US CDL	0.001 0.500 1.000 0.001 0.001 1.000 0.001		0 1 0 0 0 1	NR 0 0 NR NR 0 NR	NR 4 1 NR NR 0 NR	NR NR 1 NR NR 1 NR	NR NR NR NR NR NR	0 5 2 0 0 2
Local Land Records								
MI LIENS WI LIENS	0.001 0.001		0 0	NR NR	NR NR	NR NR	NR NR	0 0

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	<u>1/2 - 1</u>	<u>> 1</u>	Total Plotted
LIENS 2	0.001		0	NR	NR	NR	NR	0
Records of Emergency R	Release Repo	rts						
HMIRS MI SPILLS WI SPILLS	0.001 0.001 0.001		0 0 0	NR NR NR	NR NR NR	NR NR NR	NR NR NR	0 0 0
Other Ascertainable Rec	ords							
RCRA NonGen / NLR FUDS DOD SCRD DRYCLEANERS US FIN ASSUR EPA WATCH LIST 2020 COR ACTION TSCA TRIS SSTS ROD RMP RAATS PRP PADS ICIS FTTS MLTS COAL ASH DOE COAL ASH EPA PCB TRANSFORMER RADINFO HIST FTTS DOT OPS CONSENT INDIAN RESERV FUSRAP UMTRA LEAD SMELTERS US MINES ABANDONED MINES FINDS DOCKET HWC UXO	0.250 1.000 1.000 0.500 0.001 0.001 0.001 0.001 1.000 0.001		200000000000000000000000000000000000000	1 0 0 0 RR ORR ORR SKRRRRRR ORR SKR O O O ORR OORR O	NOOORRRRRORRRRRRRRORRROOOORRRRRRRO	N O O R R R R R O R R R R R R R R R R R	RRCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC	3 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
ECHO FUELS PROGRAM MI AIRS WI AIRS MI ASBESTOS WI ASBESTOS MI BEA MI COAL ASH	0.001 0.250 0.001 0.001 0.001 0.001 0.500 0.500		0 0 0 0 0 0 1	NR 0 NR NR NR NR 0	NR NR NR NR NR NR 1	NR NR NR NR NR NR NR	NR NR NR NR NR NR NR	0 0 0 0 0 0 2

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted		
WI COAL ASH	0.500		0	0	0	NR	NR	0		
MI DRYCLEANERS	0.250		1	0	NR	NR	NR	1		
WI DRYCLEANERS	0.250		0	0	NR	NR	NR	0		
MI Financial Assurance WI Financial Assurance	0.001 0.001		0 0	NR NR	NR NR	NR NR	NR NR	0 0		
WI LEAD	0.001		0	NR	NR	NR	NR	0		
MI LEAD	0.001		0	NR	NR	NR	NR	0		
WI MANIFEST	0.250		0	0	NR	NR	NR	0		
MN MANIFEST	0.250		6	2	NR	NR	NR	8		
MI NPDES	0.001		0	NR	NR	NR	NR	Ö		
WINPDES	0.001		Ō	NR	NR	NR	NR	Ō		
MI UIC	0.001		0	NR	NR	NR	NR	0		
MI WDS	0.001		0	NR	NR	NR	NR	0		
EDR HIGH RISK HISTORICAL RECORDS EDR Exclusive Records										
EDR MGP	1.000		0	0	1	0	NR	1		
EDR Hist Auto	0.125		4	NR	NR	NR	NR	4		
EDR Hist Cleaner	0.125		4	NR	NR	NR	NR	4		
EDR RECOVERED GOVERNMENT ARCHIVES										
Exclusive Recovered Govt. Archives										
MI RGA PART 201 MI RGA LF WI RGA LF MI RGA LUST	0.001 0.001 0.001 0.001		0 0 0 0	NR NR NR NR	NR NR NR NR	NR NR NR NR	NR NR NR NR	0 0 0 0		
WI RGA LUST	0.001		0	NR	NR	NR	NR	0		
- Totals		0	33	11	10	2	0	56		

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

A1 IRONWOOD DYE WORKS RCRA-CESQG 1004723505
NW 122 W AURORA ST FINDS MID985622109

< 1/8 0.013 mi. 67 ft.

Click here for full text details

IRONWOOD, MI 49938

Relative: Lower

RCRA-CESQG

EPA Id: MID985622109

FINDS

Registry ID:: 110003662867

ECHO

Registry ID: 110003662867

A2 IRONWOOD DYE WORKS EDR Hist Cleaner 1020010012
NW 122 W AURORA ST N/A

NW 122 W AURORA ST < 1/8 IRONWOOD, MI 49938 0.013 mi.

0.013 m 67 ft.

Click here for full text details

Relative: Lower

A3 IRONWOOD DYE WORKS MN MANIFEST S110203706
NW 122 W AURORA ST N/A

< 1/8 IRONWOOD, MI 49938 0.013 mi.

0.013 mi 67 ft.

Click here for full text details

Relative:

Lower

A4 114 E. ARORA ST, FUEL OIL SPILL MI DEL PART 201 S108633117

North 114 E. ARORA STREET < 1/8 IRONWOOD, MI 49938

0.026 mi. 139 ft.

Click here for full text details

Relative: Higher

MI DEL PART 201
Facility Id: 27000037

B5 IRONWOOD CLEANERS MI DRYCLEANERS \$111938478
ESE 323 S LOWELL ST MI WDS N/A

ESE 323 S LOWELL ST < 1/8 IRONWOOD, MI 49938 0.033 mi.

0.033 m 172 ft.

Click here for full text details

Relative: Lower

MI DRYCLEANERS

Establishment#: 2700002 Establishment#: 2700001 N/A

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

IRONWOOD CLEANERS (Continued)

S111938478

MID985581156

N/A

1004723354

MID985610286

FINDS

ECHO

FINDS

ECHO

MI WDS

WMD Id: 402973 Site Id: MID985581156

IRONWOOD CLEANERS RCRA NonGen / NLR 1000323494

ESE 323 S LOWELL ST < 1/8 IRONWOOD, MI 49938 0.033 mi.

172 ft.

В6

Click here for full text details

Relative: Lower

RCRA NonGen / NLR

EPA Id: MID985581156

FINDS

Registry ID:: 110003641364

Registry ID: 110003641364

IRONWOOD CLEANERS & LAUNDROMAT B7 EDR Hist Cleaner 1018738020

ESE 323 S LOWELL ST IRONWOOD, MI 49938 < 1/8

0.033 mi. 172 ft.

Click here for full text details

Relative: Lower

В8 **GLOBE PUBLISHING** RCRA-CESQG

East 118 E MCLEOD AVE IRONWOOD, MI 49938 < 1/8

0.038 mi. 202 ft.

Click here for full text details

Relative: Higher

RCRA-CESQG

EPA Id: MID985610286

FINDS

Registry ID:: 110003655553

ECHO

Registry ID: 110003655553

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

B9 GLOBE PUBLISHING MN MANIFEST S119127059
East 118 E MCLEOD AVE N/A

East 118 E MCLEOD AVE < 1/8 IRONWOOD, MI 49938 0.038 mi.

202 ft.

Click here for full text details

Relative: Higher

C10 GENES SERVICE & RADIATOR SHOP MN MANIFEST S119126796
WSW 200 W AURORA ST N/A

WSW 200 W AURORA ST < 1/8 IRONWOOD, MI 49938

0.052 mi. 277 ft.

Relative:

Click here for full text details

Lower

 C11
 GENES SERVICE AND RADIATOR INC
 RCRA-CESQG
 1000221604

 WSW
 200 W AURORA ST
 FINDS
 MID017152968

WSW 200 W AURORA ST < 1/8 IRONWOOD, MI 49938 0.052 mi.

277 ft.

Click here for full text details

Relative: Lower

RCRA-CESQG

EPA Id: MID017152968

FINDS

Registry ID:: 110003588608

ECHO

Registry ID: 110003588608

C12 GENES SERVICE & RADIATOR INC EDR Hist Auto 1021048327

WSW 200 W AURORA STREET < 1/8 IRONWOOD, MI 49938 0.052 mi.

277 ft. Relative:

Click here for full text details

Lower

B13 STEVES STNADARD SERVICE MI UST U003320080
East 141 E MCLEOD AVE N/A

East 141 E MCLEOD AVE < 1/8 IRONWOOD, MI 49938 0.057 mi.

302 ft.

Click here for full text details

Relative: Higher

MI UST

Tank Status: Removed from Ground

Facility Type: CLOSED Facility Id: 00003652

N/A

Direction Distance

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

C14 AUTOMOTIVE PARTS HEADQUARTERS RCRA NonGen / NLR 1000529300 WSW 216 W AURORA ST FINDS MID985617380

< 1/8 IRONWOOD, MI 49938 0.059 mi.

0.059 m 309 ft.

Click here for full text details

Relative: Lower

RCRA NonGen / NLR EPA ld: MID985617380

FINDS

Registry ID:: 110003660100

ECHO

Registry ID: 110003660100

C15 GENES SERVICE & RADIATOR INC MI UST U003324016
West 200 WAURORA ST N/A

West 200 WAURORA ST < 1/8 IRONWOOD, MI 49938

0.064 mi. 338 ft.

Click here for full text details

Relative: Lower

MI UST

Tank Status: Removed from Ground

Facility Type: CLOSED Facility Id: 00018110

D16 LAHTI CHEVROLET CADILLAC MN MANIFEST S119126798

NNW 111 S LOWELL ST < 1/8 IRONWOOD, MI 49938

0.069 mi. 362 ft.

Click here for full text details

Relative: Lower

D17 LAHTI INC RCRA-CESQG 1000411246
NNW 111 S LOWELL ST RCRA-CESQG MID017153313

111 S LOWELL S11/8 IRONWOOD, MI 499380.069 mi.

362 ft.

Relative: Click here for full text details

Lower

RCRA-CESQG

EPA Id: MID017153313

N/A

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

D18 GTC AUTO PARTS (CARQUEST) OF IRONWOOD

RCRA-CESQG 1004725106 FINDS MIR000028217

NW 114 W AYER ST < 1/8 IRONWOOD, MI 49938

ECHO

0.080 mi. 423 ft.

Click here for full text details

Relative: Lower

RCRA-CESQG

EPA Id: MIR000028217

FINDS

Registry ID:: 110003703635

ECHO

Registry ID: 110003703635

E19 SYLVESTER J. PAWLAK MI UST U003319614
SE 400 S LOWELL ST N/A

SE 400 S LOWELL ST
< 1/8 IRONWOOD, MI 49938</p>
0.082 mi.

431 ft.

Click here for full text details

Relative: Lower

MI UST

Tank Status: Removed from Ground

Facility Type: CLOSED Facility Id: 00001830

E20 AUVINEN TOM SERVICE CENTER EDR Hist Auto 1020465308

SE 400 S LOWELL ST < 1/8 IRONWOOD, MI 49938

< 1/8 IRONW 0.082 mi.

431 ft.

Click here for full text details

Relative: Lower

E21 BACKSTREET CYCLE & MACHINE RCRA-CESQG 1004725551
SE 101 E VAUGHN ST FINDS MIR000046888

< 1/8 IRONWOOD, MI 49938 0.082 mi.

434 ft.

Click here for full text details

Relative: Lower

RCRA-CESQG

EPA Id: MIR000046888

FINDS

Registry ID:: 110003714945

ECHO

Registry ID: 110003714945

N/A

Map ID Direction Elevation Distance Site MAP FINDINGS Database(s)

EDR ID Number EPA ID Number

E22 SE BACK STREET CYCLE & MACHINE 101 E VAUGHN ST IRONWOOD, MI 49938 MN MANIFEST S119127222

< 1/8 0.082 mi.

Relative: Lower Click here for full text details

434 ft.

< 1/8 F23 WNW 0.089 mi. DOWNTOWN AUTO PAINT & COLLISION 111 S LAWRENCE ST IRONWOOD, MI 49938 RCRA-CESQG FINDS ECHO 1004722645 MID038759874

471 ft. Click here for full text details

Relative: Lower RCRA-CESQG EPA Id: MID038759874

FINDS

Registry ID:: 110003592586

ECHORegistry ID: 110003592586

F24 WNW < 1/8 DOWNTOWN AUTO PAINT & COLLISION 111 S LAWRENCE ST IRONWOOD, MI 49938 MN MANIFEST S119126814

Relative: Lower 471 ft. Click here for full text details

0.089 mi.

G25 ENE TONY & PETES STANDARD SERVICE MC LEOD & S SUFFOLK IRONWOOD, MI 49938 **EDR Hist Auto** 1021019175

< 1/8 0.101 mi. 535 ft. Click here for full text details

Relative: Higher

MI UST U003321110

< 1/8 0.105 mi. G26 ENE PENROSE SERVICE 201 E MCLEOD AVE IRONWOOD, MI 49938 N N

Relative: Higher Click here for full text details

MI UST Tank Status: Removed from Ground Facility Type: CLOSED Facility Id: 00007508

		Click nere for full text details	Relative: Higher
1020084295 N/A	EDR Hist Cleaner	SETTERLUND HJALMER A 211 E MC LEOD AVE IRONWOOD, MI 49938	G31 ENE < 1/8 0.113 mi. 596 ft.
		2	Relative: Higher
U003322946 N/A	MIUST	FORSLUND BUILDING SUPPLY 215 E AURORA ST IRONWOOD, MI 49938 Click here for full text details	30 NE < 1/8 0.110 mi. 580 ft.
1020082271 N/A	EDR Hist Cleaner	SCHUTTE PETER 310 SO SUFFOLK ST IRONWOOD, MI 49938 Click here for full text details	G29 ENE < 1/8 0.108 mi. 569 ft. Relative: Higher
		MI UST Tank Status: Removed from Ground Facility Type: CLOSED Facility Id: 00002903	Relative: Lower
U003319890 N/A	MI UST	≂ ∠⊏	D28 NNW < 1/8 0.107 mi. 565 ft.
1020184143 N/A	EDR Hist Auto	BOYER LAWRENCE E 201 E MC LEOD AT SUFFOLK IRONWOOD, MI 49938 Click here for full text details	G27 ENE < 1/8 0.105 mi. 554 ft. Relative:
EDR ID Number	Database(s)	Site MAP FINDINGS	Map ID Direction Distance Elevation

MAP FINDINGS

Map ID Direction Elevation Distance Site

Database(s) EDR ID Number EPA ID Number

H32 North NEWMAN PROFESSIONAL BUILDING - PARCEL B 200 EAST AYER STREET TEMPTOWNSHIP, MI 49338 MI INVENTORY
MI BEA

S105541682 N/A

^ 1/8

648 ft. 0.123 mi.

Click here for full text details

Relative: Lower

H33 NNE IRONWOOD MTRS 235 E AYER ST IRONWOOD, MI 49938

RCRA NonGen / NLR FINDS ECHO

1000395223 MID017153743

1/8-1/4 0.146 mi.

770 ft. Click here for full text details

Relative: Lower

RCRA NonGen / NLR EPA Id: MID017153743

FINDS

Registry ID:: 110003588635

ECHORegistry ID: 110003588635

NNE GOTTA MOTORS 235 E AYER ST IRONWOOD, MI 49938 MN MANIFEST S119126799

1/8-1/4 0.146 mi.

Click here for full text details

770 ft.

Relative: Lower

NNE

MI UST U003322821

1/8-1/4 GOTTA MOTORS INC 237 E AYER ST IRONWOOD, MI 49938

0.147 mi.

Relative: Lower Click here for full text details

MI UST

778 ft.

Tank Status: Removed from Ground Facility Type: CLOSED Facility Id: 00013536

MAP FINDINGS

Map ID Direction Elevation Distance

Site

EDR ID Number EPA ID Number

Database(s)

MI AST

A100206692

36 WSW CHUMS SERVICE 330 W AURORA

1/8-1/4 IRONWOOD, MI 49938

789 ft. 0.149 mi.

Relative: Higher Click here for full text details

MI AST

Facility Id: 92027205

Removed/Closed Date: 01/01/1994
Tank Status: Removed from Premises

1/8-1/4 0.157 mi.

۲

MICHIGAN BELL TELEPHONE COMPANY 100 W FREDERICK ST IRONWOOD, MI 49938

RCRA-CESQG FINDS ECHO

MID982633141 1000237639

830 ft.

Click here for full text details

Relative: Lower

RCRA-CESQG EPA Id: MID982633141

FINDS

Registry ID:: 110003632490

ECHO

Registry ID: 110003632490

1/8-1/4 0.157 mi. 830 ft.

۲

IRONWOOD CO (M29445) 100 W FREDERICK ST IRONWOOD, MI 49938

MI UST

U003322296

Click here for full text details

Relative: Lower MI UST

Tank Status: Removed from Ground Tank Status: Currently In Use Facility Type: ACTIVE Facility Id: 00011739

North J39

REDS AUTO OF IRONWOOD INC

MI UST

U003319539

IRONWOOD, MI 49938 200 E FREDERICK ST

1/8-1/4 0.178 mi. 942 ft.

Click here for full text details

Relative: Lower MI UST

Tank Status: Removed from Ground Facility Type: CLOSED Facility Id: 00001504

MAP FINDINGS Map ID

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

J40 HARBOR IMPORTS RCRA-CESQG 1007880160 North 200 E FREDERICK ST MIK452579691

1/8-1/4 IRONWOOD, MI 49938 0.178 mi.

942 ft.

Click here for full text details

Relative: Lower

RCRA-CESQG

EPA Id: MIK452579691

K41 **QUALITY COLLISION CENTER** RCRA-CESQG 1004724952 SW 315 W MCLEOD AVE **FINDS** MIR000020545

1/8-1/4 0.185 mi. 975 ft.

Click here for full text details

Relative: Higher

RCRA-CESQG

IRONWOOD, MI 49938

EPA Id: MIR000020545

FINDS

Registry ID:: 110003699105

ECHO

Registry ID: 110003699105

K42 **QUALITY COLLISION CENTER** MN MANIFEST \$119127201

SW 315 W MCLEOD AVE 1/8-1/4 IRONWOOD, MI 49938

0.185 mi. 975 ft.

Click here for full text details

Relative: Higher

43 **SASS TIRE & AUTO** MI UST U003321149 **ENE** 300 E MCLEOD AVE N/A

1/8-1/4 0.185 mi. 979 ft.

Click here for full text details

IRONWOOD, MI 49938

Relative: Higher

MI UST

Tank Status: Closed in Ground Facility Type: CLOSED Facility Id: 00007664

N/A

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

44 **RAILROAD CORRIDOR #94-19 SA, IRONWOOD** NNE

MI INVENTORY S110300602

FORMER CHICAGO & NORTHWESTERN RAILROAD BETWEEN LOWELL & CURR

1/4-1/2 IRONWOOD, MI 0.288 mi.

1523 ft.

Click here for full text details

Relative: Lower

MI INVENTORY

Facility ID: 27000031

45

Click here for full text details

Relative: Lower

MI LUST

Facility Id: 00016234

Substance Release: Gasoline, Unknown

MI UST

Tank Status: Removed from Ground

WMD Id: 411319

IRONWOOD GAS WORKS

1/4-1/2 IRONWOOD, MI 49938

Relative: Lower

IRONWOOD MGP SITE L47

wsw **NW CORNER OF HEMLOCK ST & AYER ST**

1/4-1/2

0.346 mi.

Relative:

Click here for full text details

Lower

SEMS

Site ID: 0510500 EPA Id: MIN000510500

TC5737107.2s Page 18

MI LUST

MI UST

MI WDS

EDR MGP

SEMS

PRP

MI PART 201

N/A

U000253628

1008408121

1014202191

MIN000510500

N/A

N/A

MI PART 201

Facility Status: Evaluation conducted

Facility ID: 27000031

NSP-IRONWOOD SSE **101 ALFRED WRIGHT BLVD** IRONWOOD, MI 49938 1/4-1/2

0.329 mi. 1738 ft.

Release Status: Closed

Facility Type: CLOSED Facility Id: 00016234

MI WDS

Site Id: MIR000021436

L46 wsw W. AYER AND S. HEMLOCK

0.346 mi. 1825 ft.

Click here for full text details

1825 ft.

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

L48 **IRONWOOD MGP** MI INVENTORY S120851893 ON MONRTREAL RIVER, AT WEST AYER STREET AND HEMLOCK STREET **WSW** N/A

1/4-1/2 IRONWOOD, MI 49938

0.371 mi. 1957 ft.

Click here for full text details Relative:

Lower

MI INVENTORY

Facility ID: 27000066

49 **RANGE CAN DEPOSITORY** MI LUST U002301249 wsw **412 CEDAR ST** MI UST N/A

1/4-1/2 0.418 mi. 2208 ft.

Click here for full text details

IRONWOOD, MI 49938

Relative: Lower

MI LUST

Release Status: Open Facility Id: 00038008 Substance Release: Gasoline

MI UST

Tank Status: Removed from Ground

Facility Type: CLOSED Facility Id: 00038008

MI INVENTORY

Facility ID: 00038008

MI INVENTORY \$105966373 50 FORMER JOSEPHSON NURSING HOME

ΝE **634 EAST AYER STREET** 1/4-1/2 **IRONWOOD CITY, MI 49938**

0.489 mi. 2583 ft.

Click here for full text details

Relative: Higher

51 **IRONWOOD LF CITY OF** MI INVENTORY

LANDFILL RD East

IRONWOOD, MI 49938 1/2-1 0.644 mi.

3399 ft.

Click here for full text details

Relative: Higher

Facility ID: 27000004

MI PART 201

MI INVENTORY

Facility Status: Inactive - no actions taken to address contamination

Facility ID: 27000004

N/A

S103594916

N/A

MI BEA

MI PART 201

MI INVENTORY

Map ID MAP FINDINGS Direction

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

52 143 ROWE ST, HEATING OIL RELEASE MI DEL PART 201 S105965847 ENE 143 ROWE STREET N/A

ENE 143 ROWE STREET 1/2-1 IRONWOOD, MI 49938

0.782 mi. 4129 ft.

Click here for full text details

Relative: Higher

MI DEL PART 201 Facility Id: 27000053

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
MI	AIRS	Permit and Emissions Inventory Data	Department of Environment, Great Lakes, and E	04/03/2019	04/05/2019	06/04/2019
MI	ASBESTOS	Asbestos Notification Listing	Department of Licensing & Regulatory Affairs	04/30/2019	05/07/2019	06/04/2019
MI	AST	Aboveground Tanks	Department of Licensing & Regulatory Affairs	01/15/2019	01/24/2019	03/25/2019
MI	AUL	Engineering and Institutional Controls	Department of Environment, Great Lakes, and E	03/19/2019	03/20/2019	05/07/2019
MI	BEA	Baseline Environmental Assessment Database	Department of Environment, Great Lakes, and E	08/21/2013	08/23/2013	09/12/2013
MI	BROWNFIELDS	Brownfields and USTfield Site Database	Department of Environment, Great Lakes, and E	01/15/2016	02/02/2016	04/04/2016
MI	BROWNFIELDS 2	Brownfields Building and Land Site Locations	Economic Development Corporation	04/23/2019	04/24/2019	06/04/2019
MI	CDL	Clandestine Drug Lab Listing	Department of Community Health	11/14/2018	02/04/2019	03/21/2019
MI	COAL ASH	Coal Ash Disposal Sites	Department of Environment, Great Lakes, and E	10/20/2016	02/02/2017	04/20/2017
MI	DEL PART 201	Delisted List of Contaminated Sites	Department of Environment, Great Lakes, and E	08/01/2013	08/01/2013	09/11/2013
MI	DRYCLEANERS	Drycleaning Establishments	Department of Environment, Great Lakes, and E	01/15/2019	01/17/2019	04/01/2019
MI	FINANCIAL ASSURANCE 3	Financial Assurance Information Listing	Department of Licensing & Regulatory Affairs	04/08/2019	04/24/2019	06/14/2019
MI	Financial Assurance 1	Financial Assurance Information Listing	Department of Environment, Great Lakes, and E	04/10/2019	04/11/2019	05/07/2019
MI	Financial Assurance 2	Financial Assurance Information Listing	Department of Environment, Great Lakes, and E	02/19/2019	02/22/2019	03/22/2019
MI	HIST LF	Inactive Solid Waste Facilities	Department of Environment, Great Lakes, and E	03/01/1997	02/28/2003	03/06/2003
MI	INVENTORY	Inventory of Facilities	Department of Environment, Great Lakes, and E	04/23/2019	04/24/2019	06/05/2019
MI	LEAD CERT	Lead Safe Housing Registry	Department of Community Health	09/15/2015	09/16/2015	09/30/2015
MI	LIENS	Lien List	Department of Environment, Great Lakes, and E	11/02/2018	01/17/2019	03/21/2019
MI	LUST	Leaking Underground Storage Tank Sites	Department of Environment, Great Lakes, and E	05/03/2019	05/14/2019	06/05/2019
MI	NPDES	List of Active NPDES Permits	Department of Environment, Great Lakes, and E	03/27/2019	04/03/2019	05/07/2019
MI	PART 201	Part 201 Site List	Department of Environment, Great Lakes, and E	10/01/2013	10/03/2014	10/03/2014
MI	PEAS	Pollution Emergency Alerting System	Department of Environment, Great Lakes, and E	12/31/2018	01/25/2019	03/21/2019
MI	PFAS	PFAS Contaminated Sites Listing	Department of Environment, Great Lakes & Ener	04/04/2019	05/15/2019	07/12/2019
MI	RGA LF	Recovered Government Archive Solid Waste Facilities List	Department of Environment, Great Lakes, and E		07/01/2013	01/13/2014
MI	RGA LUST	Recovered Government Archive Leaking Underground Storage Tan	Department of Environment, Great Lakes, and E		07/01/2013	12/24/2013
MI	RGA PART 201	Recovered Government Archive State Hazardous Waste Facilitie	Department of Environment, Great Lakes, and E		07/01/2013	12/24/2013
MI	SHWS	This state does not maintain a SHWS list. See the Federal CE	Department of Environment, Great Lakes, and E		10/31/2013	11/20/2013
MI	SWF/LF	Solid Waste Facilities Database	Department of Environment, Great Lakes, and E	03/26/2019	03/27/2019	05/07/2019
MI	SWRCY	Recycling Facilities	Department of Environment, Great Lakes, and E	03/20/2019	03/21/2019	05/14/2019
MI	UIC	Underground Injection Wells Database	Department of Environment, Great Lakes, and E	01/29/2019	01/30/2019	04/01/2019
MI	UST	Underground Storage Tank Facility List	Department of Licensing & Regulatory Affairs	02/06/2019	02/13/2019	03/25/2019
MI	UST 2	Underground Storage Tank Listing	Department of Licensing & Regulatory Affairs	04/23/2018	04/25/2018	06/27/2018
MI	WDS	Waste Data System	Department of Environment, Great Lakes, and E	05/17/2019	05/17/2019	06/05/2019
US	2020 COR ACTION	2020 Corrective Action Program List	Environmental Protection Agency	09/30/2017	05/08/2018	07/20/2018
US	ABANDONED MINES	Abandoned Mines	Department of Interior	03/27/2019	03/28/2019	05/01/2019
WI	AIRS	Air Permit Program Listing	Department of Natural Resources	04/22/2019	04/23/2019	06/25/2019
WI	ASBESTOS	Asbestos Notification Listing	Department of Natural Resources	05/31/2019	05/31/2019	06/13/2019
WI	AST	Tanks Database	Department of Agriculture, Trade & Consumer P	06/11/2019	06/12/2019	06/13/2019
WI	AUL	Deed Restriction at Closeout Sites	Department of Natural Resources	05/03/2019	06/14/2019	06/17/2019
WI	BROWNFIELDS	Brownfields Site Locations Listing	Department of Natural Resources	05/03/2019	06/14/2019	06/17/2019
US	BRS	Biennial Reporting System	EPA/NTIS	12/31/2015	02/22/2017	09/28/2017
WI	CDL	Clandestine Drug Lab Listing	Department of Justice	12/31/2016	03/19/2019	06/17/2019
WI	COAL ASH	Coal Ash Disposal Site Listing	Deaprement of Natural Resources	06/20/2018	06/26/2018	08/16/2018
US	COAL ASH DOE	Steam-Electric Plant Operation Data	Department of Energy	12/31/2005	08/07/2009	10/22/2009
US	COAL ASH EPA	Coal Combustion Residues Surface Impoundments List	Environmental Protection Agency	07/01/2014	09/10/2014	10/20/2014
US	CONSENT	Superfund (CERCLA) Consent Decrees	Department of Justice, Consent Decree Library	03/31/2019	04/23/2019	05/23/2019
US	CORRACTS	Corrective Action Report	EPA	03/25/2019	03/27/2019	04/17/2019

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	DEBRIS REGION 9	Torres Martinez Reservation Illegal Dump Site Locations	EPA, Region 9	01/12/2009	05/07/2009	09/21/2009
US	DOCKET HWC	Hazardous Waste Compliance Docket Listing	Environmental Protection Agency	05/31/2018	07/26/2018	10/05/2018
US	DOD	Department of Defense Sites	USGS	12/31/2005	11/10/2006	01/11/2007
US	DOT OPS	Incident and Accident Data	Department of Transporation, Office of Pipeli	12/03/2018	01/29/2019	03/21/2019
WI	DRYCLEANERS	Five Star Recognition Program Sites	Department of Natural Resources	06/11/2019	06/13/2019	06/13/2019
US	Delisted NPL	National Priority List Deletions	EPA	04/11/2019	04/18/2019	05/14/2019
US	ECHO	Enforcement & Compliance History Information	Environmental Protection Agency	04/07/2019	04/09/2019	05/23/2019
US	EDR Hist Auto	EDR Exclusive Historical Auto Stations	EDR, Inc.			
US	EDR Hist Cleaner	EDR Exclusive Historical Cleaners	EDR, Inc.			
US	EDR MGP	EDR Proprietary Manufactured Gas Plants	EDR, Inc.			
US	EPA WATCH LIST	EPA WATCH LIST	Environmental Protection Agency	08/30/2013	03/21/2014	06/17/2014
US	ERNS	Emergency Response Notification System	National Response Center, United States Coast	03/25/2019	03/26/2019	05/01/2019
US	FEDERAL FACILITY	Federal Facility Site Information listing	Environmental Protection Agency	04/03/2019	04/05/2019	05/14/2019
US	FEDLAND	Federal and Indian Lands	U.S. Geological Survey	12/31/2005	02/06/2006	01/11/2007
US	FEMA UST	Underground Storage Tank Listing	FEMA	05/15/2017	05/30/2017	10/13/2017
US	FINDS	Facility Index System/Facility Registry System	EPA	02/15/2019	03/05/2019	03/15/2019
US	FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA/Office of Prevention, Pesticides and Toxi	04/09/2009	04/16/2009	05/11/2009
US	FTTS INSP	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fu	EPA	04/09/2009	04/16/2009	05/11/2009
US	FUDS	Formerly Used Defense Sites	U.S. Army Corps of Engineers	03/07/2019	04/03/2019	05/23/2019
US	FUELS PROGRAM	EPA Fuels Program Registered Listing	EPA	02/19/2019	02/21/2019	04/01/2019
US	FUSRAP	Formerly Utilized Sites Remedial Action Program	Department of Energy	08/08/2017	09/11/2018	09/14/2018
WI	Financial Assurance 1	Financial Assurance Information Listing	Department of Natural Resources	06/03/2019	06/04/2019	06/17/2019
WI	Financial Assurance 2	Financial Assurance Information Listing	Department of Agriculture, Trade & Consumer P	03/21/2019	04/02/2019	06/17/2019
WI	Financial Assurance 3	Financial Assurance Information Listing	Department of Natural Resources	06/03/2019	06/04/2019	06/17/2019
US	HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	HIST FTTS INSP	FIFRA/TSCA Tracking System Inspection & Enforcement Case Lis	Environmental Protection Agency	10/19/2006	03/01/2007	04/10/2007
US	HMIRS	Hazardous Materials Information Reporting System	U.S. Department of Transportation	03/25/2019	03/26/2019	05/14/2019
US	ICIS	Integrated Compliance Information System	Environmental Protection Agency	11/18/2016	11/23/2016	02/10/2017
US	IHS OPEN DUMPS	Open Dumps on Indian Land	Department of Health & Human Serivces, Indian	04/01/2014	08/06/2014	01/29/2015
US	INDIAN LUST R1	Leaking Underground Storage Tanks on Indian Land	EPA Region 1	10/13/2018	03/07/2019	05/01/2019
US	INDIAN LUST R10	Leaking Underground Storage Tanks on Indian Land	EPA Region 10	10/17/2018	03/07/2019	05/01/2019
US	INDIAN LUST R4	Leaking Underground Storage Tanks on Indian Land	EPA Region 4	09/24/2018	03/12/2019	05/01/2019
US	INDIAN LUST R5	Leaking Underground Storage Tanks on Indian Land	EPA, Region 5	10/12/2018	03/07/2019	05/01/2019
US	INDIAN LUST R6	Leaking Underground Storage Tanks on Indian Land	EPA Region 6	11/01/2018	03/07/2019	05/01/2019
US	INDIAN LUST R7	Leaking Underground Storage Tanks on Indian Land	EPA Region 7	02/19/2019	03/07/2019	05/01/2019
US	INDIAN LUST R8	Leaking Underground Storage Tanks on Indian Land	EPA Region 8	10/16/2018	03/07/2019	05/01/2019
US	INDIAN LUST R9	Leaking Underground Storage Tanks on Indian Land	Environmental Protection Agency	10/10/2018	03/08/2019	05/01/2019
US	INDIAN ODI	Report on the Status of Open Dumps on Indian Lands	Environmental Protection Agency	12/31/1998	12/03/2007	01/24/2008
US	INDIAN RESERV	Indian Reservations	USGS	12/31/1998	07/14/2015	01/10/2017
US	INDIAN UST R1	Underground Storage Tanks on Indian Land	EPA, Region 1	10/03/2018	03/07/2019	05/01/2019
US	INDIAN UST R10	Underground Storage Tanks on Indian Land	EPA Region 10	10/17/2018	03/07/2019	05/01/2019
US	INDIAN UST R4	Underground Storage Tanks on Indian Land	EPA Region 4	09/24/2018	03/07/2019	05/01/2019
US	INDIAN UST R4	Underground Storage Tanks on Indian Land	EPA Region 5	10/12/2018	03/12/2019	05/01/2019
US	INDIAN UST R5	Underground Storage Tanks on Indian Land	EPA Region 6	11/01/2018	03/07/2019	05/01/2019
US	INDIAN UST RO	Underground Storage Tanks on Indian Land	EPA Region 7	11/07/2018	03/07/2019	05/01/2019
US	INDIAN UST R7 INDIAN UST R8	Underground Storage Tanks on Indian Land Underground Storage Tanks on Indian Land	EPA Region 7 EPA Region 8	10/16/2018	03/07/2019	05/01/2019
US	INDIAN UST RO INDIAN UST R9	Underground Storage Tanks on Indian Land	EPA Region 9	10/10/2018	03/07/2019	05/01/2019
US	INDIAN UST NA	onderground Storage Tanks on Mulan Land	LI A Negion 9	10/10/2018	03/00/2019	00/01/2019

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	INDIAN VCP R1	Voluntary Cleanup Priority Listing	EPA, Region 1	07/27/2015	09/29/2015	02/18/2016
US	INDIAN VCP R7	Voluntary Cleanup Priority Lisitng	EPA, Region 7	03/20/2008	04/22/2008	05/19/2008
WI	LEAD	Lead Inspection Data	Department of Health & Family Services	10/02/2018	10/18/2018	11/27/2018
WI	LEAD CERT	Lead Safe Housing Registry	Department of Environmental & Occupation	02/25/2019	02/26/2019	06/13/2019
US	LEAD SMELTER 1	Lead Smelter Sites	Environmental Protection Agency	04/11/2019	04/18/2019	05/14/2019
US	LEAD SMELTER 2	Lead Smelter Sites	American Journal of Public Health	04/05/2001	10/27/2010	12/02/2010
WI	LIENS	Environmental Liens Listing	Department of Natural Resources	04/15/2019	04/18/2019	06/24/2019
US	LIENS 2	CERCLA Lien Information	Environmental Protection Agency	04/11/2019	04/18/2019	05/23/2019
US	LUCIS	Land Use Control Information System	Department of the Navy	02/22/2019	03/07/2019	04/17/2019
WI	LUST	Leaking Underground Storage Tank Database	Department of Natural Resources	05/03/2019	06/14/2019	06/17/2019
US	MLTS	Material Licensing Tracking System	Nuclear Regulatory Commission	08/30/2016	09/08/2016	10/21/2016
WI	NPDES	NPDES Permit Listing	Department of Natural Resources	05/21/2019	05/23/2019	06/18/2019
US	NPL	National Priority List	EPA	04/11/2019	04/18/2019	05/14/2019
US	NPL LIENS	Federal Superfund Liens	EPA	10/15/1991	02/02/1994	03/30/1994
US	ODI	Open Dump Inventory	Environmental Protection Agency	06/30/1985	08/09/2004	09/17/2004
US	PADS	PCB Activity Database System	EPA	03/20/2019	04/10/2019	05/14/2019
US	PCB TRANSFORMER	PCB Transformer Registration Database	Environmental Protection Agency	05/24/2017	11/30/2017	12/15/2017
WI	PFAS	PFAS Contamination Site Location Listing	Department of Natural Resources	04/02/2019	04/04/2019	05/08/2019
US	PRP	Potentially Responsible Parties	EPA	04/11/2019	04/18/2019	05/23/2019
US	Proposed NPL	Proposed National Priority List Sites	EPA	04/11/2019	04/18/2019	05/14/2019
US	RAATS	RCRA Administrative Action Tracking System	EPA	04/17/1995	07/03/1995	08/07/1995
US	RADINFO	Radiation Information Database	Environmental Protection Agency	04/02/2019	04/02/2019	05/14/2019
US	RCRA NonGen / NLR	RCRA - Non Generators / No Longer Regulated	Environmental Protection Agency	03/25/2019	03/27/2019	04/17/2019
US	RCRA-CESQG	RCRA - Conditionally Exempt Small Quantity Generators	Environmental Protection Agency	03/25/2019	03/27/2019	04/17/2019
US	RCRA-LQG	RCRA - Large Quantity Generators	Environmental Protection Agency	03/25/2019	03/27/2019	04/17/2019
US	RCRA-SQG	RCRA - Small Quantity Generators	Environmental Protection Agency	03/25/2019	03/27/2019	04/17/2019
US	RCRA-TSDF	RCRA - Treatment, Storage and Disposal	Environmental Protection Agency	03/25/2019	03/27/2019	04/17/2019
WI	RGA LF	Recovered Government Archive Solid Waste Facilities List	Department of Natural Resources	03/23/2019	07/01/2013	01/13/2014
WI	RGA LUST	Recovered Government Archive Leaking Underground Storage Tan	Department of Natural Resources		07/01/2013	12/27/2013
US	RMP	Risk Management Plans	Environmental Protection Agency	04/25/2019	05/02/2019	05/23/2019
US	ROD	Records Of Decision	EPA	04/23/2019	04/18/2019	05/23/2019
US	SCRD DRYCLEANERS	State Coalition for Remediation of Drycleaners Listing	Environmental Protection Agency	01/01/2017	02/03/2017	04/07/2017
US	SEMS	Superfund Enterprise Management System	EPA	04/11/2019	04/18/2019	05/23/2019
US	SEMS-ARCHIVE	Superfund Enterprise Management System Archive	EPA	04/11/2019	04/18/2019	05/23/2019
WI	SHWS	Hazard Ranking List	Department of Natural Resources	11/30/1994	02/10/1995	03/23/2019
WI	SPILLS	Spills Database	Department of Natural Resources	05/03/2019	06/14/2019	06/17/2019
US	SSTS	Section 7 Tracking Systems	EPA	12/31/2009	12/10/2019	02/25/2011
WI	SWF/LF	List of Licensed Landfills	Department of Natural Resources	12/31/2009	01/03/2019	02/25/2011
WI	SWRCY		Solid & Hazardous Waste Education center	03/26/2019	03/28/2019	06/18/2019
US	TRIS	Recycling Center Listing	EPA	12/31/2016	03/26/2019	01/12/2018
US	TSCA	Toxic Chemical Release Inventory System	EPA			
		Toxic Substances Control Act		12/31/2016	06/21/2017	
US	UMTRA	Uranium Mill Tailings Sites	Department of Energy	06/23/2017	10/11/2017	
US	US AIRS (AFS)	Aerometric Information Retrieval System Facility Subsystem (EPA	10/12/2016	10/26/2016	02/03/2017
US	US AIRS MINOR	Air Facility System Data	EPA	10/12/2016	10/26/2016	02/03/2017
US	US BROWNFIELDS	A Listing of Brownfields Sites	Environmental Protection Agency	12/17/2018	12/18/2018	01/11/2019
US	US CDL	Clandestine Drug Labs	Drug Enforcement Administration	02/24/2019	02/26/2019	04/17/2019
US	US ENG CONTROLS	Engineering Controls Sites List	Environmental Protection Agency	01/31/2019	02/04/2019	03/08/2019

St	Acronym	Full Name	Government Agency	Gov Date	Arvl. Date	Active Date
US	US FIN ASSUR	Financial Assurance Information	Environmental Protection Agency	03/25/2019	03/26/2019	05/07/2019
US	US HIST CDL	National Clandestine Laboratory Register	Drug Enforcement Administration	02/24/2019	02/26/2019	04/17/2019
US	US INST CONTROL	Sites with Institutional Controls	Environmental Protection Agency	01/31/2019	02/04/2019	03/08/2019
US	US MINES	Mines Master Index File	Department of Labor, Mine Safety and Health A	11/27/2018	02/27/2019	04/01/2019
US	US MINES 2	Ferrous and Nonferrous Metal Mines Database Listing	USGS	12/05/2005	02/29/2008	04/18/2008
US	US MINES 3	Active Mines & Mineral Plants Database Listing	USGS	04/14/2011	06/08/2011	09/13/2011
WI	UST	Registered Underground Storage Tanks	Department of Agriculture, Trade & Consumer P	06/11/2019	06/12/2019	06/13/2019
US	UXO	Unexploded Ordnance Sites	Department of Defense	12/31/2017	01/17/2019	04/01/2019
WI	WI MANIFEST	Manifest Information	Department of Natural Resources	12/31/2017	06/15/2018	07/09/2018
СТ	CT MANIFEST	Hazardous Waste Manifest Data	Department of Factory 9 Environmental Protecti	02/11/2019	02/12/2019	03/04/2019
NJ	NJ MANIFEST	Manifest Information	Department of Energy & Environmental Protecti Department of Environmental Protection	12/31/2018	04/10/2019	05/16/2019
NY	NY MANIFEST	Facility and Manifest Data	Department of Environmental Conservation	01/01/2019	05/01/2019	06/21/2019
PA	PA MANIFEST	Manifest Information	Department of Environmental Protection	12/31/2017	10/23/2018	11/27/2018
RI	RI MANIFEST	Manifest information	Department of Environmental Management	12/31/2017	02/23/2018	04/09/2018
WI	WI MANIFEST	Manifest Information	Department of Natural Resources	12/31/2017	06/15/2018	07/09/2018
V V I	WI WANI EST	Manifest information	Department of Natural Nesources	12/31/2017	00/13/2010	07/03/2010
US	AHA Hospitals	Sensitive Receptor: AHA Hospitals	American Hospital Association, Inc.			
US	Medical Centers	Sensitive Receptor: Medical Centers	Centers for Medicare & Medicaid Services			
US	Nursing Homes	Sensitive Receptor: Nursing Homes	National Institutes of Health			
US	Public Schools	Sensitive Receptor: Public Schools	National Center for Education Statistics			
US	Private Schools	Sensitive Receptor: Private Schools	National Center for Education Statistics			
MI	Daycare Centers	Sensitive Receptor: Day Care Centers, Group & Family Homes	Bureau of REgulatory Services			
US	Flood Zones	100-year and 500-year flood zones	Emergency Management Agency (FEMA)			
US	NWI	National Wetlands Inventory	U.S. Fish and Wildlife Service			
MI	State Wetlands	Wetlands Inventory	Department of Natural Resources			
US	Topographic Map		U.S. Geological Survey			
US	Oil/Gas Pipelines		PennWell Corporation			
US	Electric Power Transmission Line D	Pata	PennWell Corporation			

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK®-PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

LAHTI PROPERTY MCLEOD AVE, LOWELL ST, AND AURORA ST IRONWOOD, MI 49938

TARGET PROPERTY COORDINATES

Latitude (North): 46.453256 - 46° 27' 11.72" Longitude (West): 90.169744 - 90° 10' 11.08"

Universal Tranverse Mercator: Zone 15 UTM X (Meters): 717359.2 UTM Y (Meters): 5148084.0

Elevation: 1511 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map: 6070115 IRONWOOD, MI

Version Date: 2014

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

- 1. Groundwater flow direction, and
- 2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION


Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General West

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES





Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property FEMA Source Type

Not Reported

Additional Panels in search area: FEMA Source Type

Not Reported

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property Data Coverage

IRONWOOD YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius: 1.25 miles Status: Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

LOCATION GENERAL DIRECTION

MAP ID FROM TP GROUNDWATER FLOW

Not Reported

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

GEOLOGIC AGE IDENTIFICATION

Era: Precambrian Category: Plutonic and Intrusive Rocks

System: Precambrian
Series: W granitic rocks

Code: Wg (decoded above as Era, System & Series)

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: ROCK OUTCROP

Soil Surface Texture: unweathered bedrock

Hydrologic Group: Not reported

Soil Drainage Class: Not reported

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: Not Reported

Depth to Bedrock Min: > 0 inches

Depth to Bedrock Max: > 4 inches

Soil Layer Information							
	Boui	ndary		Classif	ication		
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	60 inches	unweathered bedrock	Not reported	Not reported	Max: 0.06 Min: 0.01	Max: 0.00 Min: 0.00

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: cobbly - sandy loam

sandy loam fine sandy loam

muck

Surficial Soil Types: cobbly - sandy loam

sandy loam fine sandy loam

muck

Shallow Soil Types: cobbly - sandy loam

silt loam cobbly - loam

Deeper Soil Types: cobbly - sandy loam

sandy loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

WELL SEARCH DISTANCE INFORMATION

DATABASE SEARCH DISTANCE (miles)

Federal USGS 1.000

Federal FRDS PWS Nearest PWS within 1 mile

State Database 1.000

FEDERAL USGS WELL INFORMATION

LOCATION FROM TP

MAP ID WELL ID

FEDERAL USGS WELL INFORMATION

MAP ID WELL ID LOCATION FROM TP

No Wells Found

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

 MAP ID
 WELL ID
 FROM TP


 1
 MI3620056
 0 - 1/8 Mile NNW

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

LOCATION FROM TP
 1/2 - 1 Mile South
1/2 - 1 Mile WNW 1/2 - 1 Mile North

PHYSICAL SETTING SOURCE MAP - 5737107.2s



SITE NAME: Lahti Property
ADDRESS: Mcleod Ave, Lowell St, and Aurora St
Ironwood MI 49938

LAT/LONG: 46.453256 / 90.169744 CLIENT: Coleman Engi CONTACT: Mike Gotham Coleman Engineering Company

INQUIRY#: 5737107.2s August 01, 2019 12:34 pm DATE:

Copyright © 2019 EDR, Inc. © 2015 TomTom Rel. 2015.

Map ID Direction Distance Elevation		Database	EDR ID Number
1 NNW 0 - 1/8 Mile Lower	Click here for full text details	FRDS PWS	MI3620056
2 South 1/2 - 1 Mile Lower	Click here for full text details	MI WELLS	MI4000000475034
3 WNW 1/2 - 1 Mile Lower	Click here for full text details	MI WELLS	MI4000000474896
4 North 1/2 - 1 Mile Lower	Click here for full text details	MI WELLS	MI4000000474874

AREA RADON INFORMATION

State Database: MI Radon

Radon Test Results

Zipcode	Test Date	LT Sign	Result
49938	2/10/1997		1.5
49938	3/8/1997		1.5
49938	10/25/1999		1.6
49938	10/21/1999		1.6
49938	2/16/2000		1.6
49938	10/21/1999		1.6
49938	10/21/1999		1.6
49938	3/24/2000		1.5
49938	2/5/2002		1.5
49938	2/26/2003		1.5
49938	2/12/2004		1.5
49938	2/3/2004		1.5
49938	2/11/2005		1.5
49938	3/7/2003		1.4
49938	4/28/2001		1.5
49938	5/27/1997		1.4
49938	2/12/1997		1.4
49938	2/5/1998		1.4
49938	2/17/1998		1.4
49938	2/17/1998		1.4
49938	9/29/2000		1.4
49938	10/29/1999		1.4
49938	10/29/1999		1.4
	10/21/1999		1.4
49938 49938	11/21/1999		1.4
49938 49938	2/27/1998		1.4
49938	3/3/1998		1.3
49938	3/3/1996 2/22/1997		1.3
49938	2/22/1997		1.3
49938	2/14/1998		1.3
			1.3
49938 49938	2/8/1997 11/9/1998		1.3
49938	3/24/2003		1.3
49938	2/9/2002		1.3
49938	1/31/2002		1.3
49938	3/4/1995		1.3
49938	2/12/1997		1.2
49938	8/27/1997		1.2
49938	2/5/1998		1.2
49938	4/10/2000		1.2
			1.3
49938 49938	10/21/1999 4/30/2001		1.3
49938 49938	3/6/2000		1.3
49938 49938	3/6/2000 10/29/1999		1.3
49938 49938	1/26/2008		1.3
49938 49938	10/25/1999		1.2
49900			

	E/40/0004	4.0
40000	5/10/2001	1.2
49938	3/2/2002	1.2
49938	2/5/1998	1.1
49938	2/24/1995	1.1
49938	3/20/1998	1.1
49938	4/14/1997	1.1
49938	2/5/2002	1.1
49938	3/8/1995	1.2
49938	2/10/2000	1.1
49938	2/14/2000	1.1
49938	10/5/2000	1.1
49938	5/1/2001	1.1
	4/23/2001	
49938		1.1
49938	10/21/1999	1.1
49938	10/23/1999	1.1
49938	10/21/1999	1.1
49938	5/3/2001	1.1
49938	5/24/2001	1.1
49938	5/3/2001	1.1
49938	2/7/1995	1.0
49938	2/15/1997	1.0
49938	2/15/1997	1.0
49938	2/10/2003	1.0
49938	6/26/2002	1.0
49938	12/8/2003	1.0
49938	9/30/2002	1.0
49938	3/3/2005	1.0
	5, 5, 2, 2, 5	
49938	2/11/2005	1.0
49938	10/31/1995	1.0
49938	2/9/1998	1.0
49938	2/5/1997	1.0
49938	2/3/1997	1.0
49938	11/28/1998	1.0
49938	3/10/1998	1.0
49938	4/27/2000	1.0
49938	3/7/2000	1.0
49938	2/10/2000	1.0
49938	10/29/1999	1.0
49938	4/28/2001	1.0
49938	10/25/1999	1.0
49938	10/27/1999	1.0
49938	1/28/2005	1.0
49938	7/22/2005	1.9
49938	2/14/2005	1.9
49938	2/21/1997	1.9
49938	3/6/2003	1.9
49938	5/14/2003	1.9
49938	2/5/1997	1.8
49938	3/18/1996	1.8
49938	9/13/2001	1.8
49938	2/1/2005	1.8
49938	8/24/2009	1.9
49938	2/25/1998	1.8
49938	10/22/1999	1.8
49938	2/11/2000	1.8
49938	12/24/1994	1.8
49938		

	10/8/2009		1.8
49938	2/7/2005		1.8
49938	4/20/2001		1.7
49938	4/20/2001		1.7
49938	4/26/2001		1.7
49938	10/21/1999		1.7
49938	2/5/1998		1.7
49938	2/21/2003		1.7
49938	2/13/2004		1.7
49938	3/15/2004		1.7
49938	2/7/1997		1.6
49938	1/29/2002		1.6
49938	1/25/2005		1.6
49938	2/21/2005		1.6
49938	2/21/1997		1.6
49938	2/9/1998		1.6
49938	2/7/1997	<	0.3
49938	2/10/1997	<	0.3
49938	2/13/1997	<	0.3
49938	2/17/1997	<	0.3
49938	2/13/1997	<	0.3
49938	2/15/1997	<	0.3
49938	2/21/1997	<	0.3
49938	2/10/1997 3/29/1997	<	0.3
49938		<	0.3
49938	3/6/1997	<	0.3
49938	2/18/2002		0.5
49938 49938	3/13/1998	<	0.3
	7/25/2005	<	0.3
49938	2/27/2007	<	0.3
49938 49938	3/2/2005 6/7/2004		0.5 0.5
49938	2/11/2005		0.5
49938	2/11/2005		0.5
49938	4/20/1996		0.3
49938	2/23/2004	<	0.3
49938	2/7/2004	<	0.3
49938	2/21/2005	<	0.3
49938	2/16/2005	<	0.3
49938	2/11/2005	<	0.3
49938	1/17/2006	<	0.3
49938	4/7/2003	<	0.3
49938	1/3/2005	<	0.3
49938	4/26/2001		0.5
49938	5/25/2001		0.5
49938	4/20/2001		0.5
49938	10/25/1999		0.5
49938	12/12/1994		0.5
49938	3/8/2000		0.5
49938	2/18/2000		0.5
49938	2/18/2000		0.5
49938	1/31/1995		0.5
49938	1/23/1995		0.5
49938	4/3/2000		0.5
49938	2/18/2003	<	0.3
49938	2/8/2003	<	0.3
49938	_, _,	•	0.0

	2/28/2003		0.3
49938	3/21/2005	<	0.3
49938	11/8/2003	<	0.3
49938	4/11/2005	<	0.3
49938	4/18/2005	<	0.3
49938	3/22/2004	<	0.3
49938	2/21/1995		0.3
49938	2/27/2002	<	0.3
49938	2/25/2002	<	0.3
49938	2/4/2002	<	0.3
49938	2/9/2002	<	0.3
49938	3/1/2004	<	0.3
49938	4/19/1995	<	0.3
49938	2/13/1995	<	0.3
49938	4/25/1995	<	0.3
49938	4/6/1995	<	0.3
49938	2/27/1998	<	0.3
49938	2/13/1997	<	0.3
49938	2/13/1997	<	0.3
49938	2/3/1997	<	0.3
49938	2/3/1997	<	0.3
49938	2/15/1997	<	0.3
49938	4/5/2002	<	0.3
49938	2/3/1997	<	0.3
49938	2/17/1998	<	0.3
49938	2/23/1998	<	0.3
49938	5/9/2003	<	0.3
49938	2/23/2004	<	0.3
49938	7/9/1997	<	0.3
49938	11/9/1998		0.8
49938	5/9/1996		8.0
49938	2/17/1997		8.0
49938	4/23/2002		0.5
49938	3/11/2003		0.5
49938	2/9/2002		0.5
49938	2/5/2002		0.7
49938	2/9/1998		0.9
49938	2/3/1997		8.0
49938	2/13/2003		8.0
49938	2/9/1998		0.9
49938	2/23/1998		0.9
49938	3/7/2005		0.6
49938	7/15/2002		8.0
49938	3/9/1998		0.9
49938	2/12/1997		0.9
49938	3/15/2005		0.6
49938	3/1/2004		0.8
49938	2/15/2005		0.8 0.8
49938	2/7/2005 3/8/2004		0.8
49938	3/30/1998		0.7
49938 49938	2/6/2002		0.9
49938	2/13/2002		
49938	2/13/2002 2/23/2004		0.9
49938	8/11/2001		0.8
49938	1/30/2002		0.9
49938	1700/2002		5.5
TU000			

	E/27/2006	0.6
40000	5/27/2006	0.6
49938	2/26/2004	0.9
49938	3/28/2005	0.9
49938	9/27/2004	0.9
49938	10/21/1999	0.7
49938	5/3/2001	0.7
49938	2/15/2005	0.9
49938	10/21/1999	0.6
49938	3/1/2000	0.7
49938	4/15/1995	0.7
49938	12/5/1994	0.7
49938	12/9/1994	0.7
49938	2/18/1995	0.6
49938	3/11/1995	0.6
49938	5/10/2001	0.8
49938	10/21/1999	0.8
49938	10/21/1999	0.8
49938	2/10/2000	0.8
49938	2/18/2000	0.8
49938	6/4/2001	0.7
49938	4/26/2001	0.7
		0.7
49938	4/23/2001	-
49938	12/5/1994	0.8
49938	5/26/1998	0.6
49938	4/20/2001	0.9
49938	2/17/2009	0.6
49938	11/6/1998	0.6
49938	11/4/1998	0.6
49938	3/6/1997	0.6
49938	2/21/1998	0.6
49938	2/20/1997	0.5
49938	2/12/1997	0.7
49938	2/21/1997	0.7
49938	4/7/1997	0.7
49938	4/15/1996	0.6
49938	2/3/1997	0.6
49938	2/4/1997	0.6
49938	2/22/1997	0.6
49938	2/7/1997	0.6
49938	2/7/1998	0.6
49938	5/6/1997	0.5
49938	2/19/1997	0.5
49938	11/6/1998	0.5
49938	3/5/1996	0.5
49938	10/30/1998	0.5
49938	2/4/1997	0.5
49938	2/10/1997	0.5
49938	2/10/1997	0.7
49938	3/1/1997	0.7
49938	2/12/1997	0.7
49938	2/28/2003	0.6
49938	1/30/2002	0.6
	1/30/2002	
49938		0.6
49938	2/3/1997	0.5
49938	2/4/2002	0.7
49938	4/25/2002	0.6
49938		

	3/17/2003		0.6
49938	3/15/1997		0.8
49938	4/28/1998		0.8
49938	2/7/1995		8.0
49938	5/21/2001		2.8
49938	2/27/1998		2.6
49938	5/1/1995		2.6
49938	4/24/2009		2.6
49938	2/14/1998		2.7
49938	4/21/2001		2.5
49938	2/10/1997		2.4
49938	12/5/1997		2.4
49938	3/12/2007		2.3
49938	5/13/2000		2.3
49938	2/15/1997		2.2
49938	2/5/1997		2.2
49938	2/8/2005		2.2
49938	3/16/1996		2.1
49938	2/14/2003		2.1
49938	10/21/1999		3.0
49938	2/22/2000		3.0
49938	2/23/2004		2.6
49938	4/7/2005		2.8
49938	10/31/1998		2.9
49938	10/21/1999		2.8
49938	3/1/2004		3.6
49938	3/8/2000		3.6
49938	2/27/1995		3.6
49938	4/14/2001		3.6
49938 49938	3/14/1998 2/21/1998		3.5 3.5
49938	10/21/1999		0.3
49938	11/19/1994	<	0.3
49938	4/23/2001	<	0.3
49938	4/26/2001	<	0.3
49938	4/26/2001	<	0.3
49938	4/12/2001	<	0.3
49938	4/20/2001	<	0.3
49938	4/23/2001	<	0.3
49938	4/23/2001	<	0.3
49938	4/16/2001	<	0.3
49938	11/3/1994	<	0.3
49938	4/21/1999	<	0.3
49938	11/4/1999	<	0.3
49938	5/9/1998		3.4
49938	5/18/2009		3.4
49938	3/23/2000	<	0.3
49938	3/8/2000	<	0.3
49938	2/18/2000	<	0.3
49938	2/16/1998		3.2
49938	2/2/2007		3.1
49938	2/14/2000	<	0.3
49938	2/14/2000	<	0.3
49938	4/1/2000	<	0.3
49938	5/9/2001	<	0.3
49938	5/3/2001	<	0.3
49938			

	10/30/1998		3.3
40038	10/30/1998	_	3.3 0.3
49938		<	
49938	10/21/1999	<	0.3
49938	10/25/1999	<	0.3
49938	10/25/1999	<	0.3
49938	10/21/1999	<	0.3
49938	2/11/2000		3.1
49938	11/17/1999		3.1
49938	10/21/1999		3.1
49938	5/1/2001		3.2
49938	10/27/2009		3.1
49938	2/7/1997		3.0
49938	3/10/1998		3.7
49938	2/5/1997		3.1
49938	3/28/2009	<	0.3
49938	3/23/2009	<	0.3
49938	4/17/2006		3.7
49938	10/28/1999		3.3
49938	4/20/2001		3.9
49938	7/30/2009		3.9
49938	3/17/1995		3.6
49938	10/30/1998		3.2
49938	2/12/2000		6.9
49938	5/28/2001		6.6
49938	2/10/2003		7.5
49938	4/4/1998		6.5
49938	7/15/2005		6.4
49938	5/8/1995		6.3
49938	3/3/1998		6.0
49938	5/3/2001		6.0
49938	2/17/2009		4.8
49938	5/3/2001		5.1
49938	2/3/1995		5.1
49938	2/23/2004		4.7
49938	2/11/1997		5.0
49938	2/15/1997		5.3
49938	2/8/2005		5.0
49938	2/14/2009		5.7
49938	2/6/2002		4.9
49938	8/1/2005		5.6
49938	4/3/1998		7.0
49938	2/10/2003		7.7
49938	3/23/1998		2.0
49938	5/1/1997		2.0
49938	2/7/2005		114.9
49938			
	3/15/2005		63.5
49938	2/24/2005		23.6
49938	2/3/1997		18.2
49938	3/11/1995		49.7
49938	2/18/1995		48.9
49938	4/26/2001		47.7
49938	3/11/1995		45.5
49938	3/15/2005		42.2
49938	2/1/2006		22.4
49938	4/21/2001		13.5
49938	2/22/1997		12.5
49938			-

AREA RADON INFORMATION

	5/28/2001	12.5
49938	5/11/2001	11.1
49938	2/14/1998	10.1
49938	1/22/1996	8.0
49938	10/23/1999	10.7
49938	4/23/2001	10.4
49938	11/10/1999	10.4
49938	3/7/2003	8.7
49938	2/7/2005	2.1
49938	3/1/2004	2.0
49938	2/15/2003	9.3
49938	8/9/2004	2.0
49938	3/24/2003	9.0
49938	11/13/2000	2.1
49938	9/28/2009	2.0
49938	11/10/2009	2.1
49938	2/25/1997	4.4
49938	11/22/1994	4.2
49938	5/11/2001	4.2
49938	2/23/2004	4.0
49938	5/18/2009	4.0
49938	4/30/2001	4.0
49938	5/7/1994	4.0
49938	12/11/2009	4.0
49938	3/7/1995	4.6
49938	2/19/2004	4.1
49938	10/25/1999	4.4
49938	9/19/2006	4.2
49938	10/28/1999	4.2

Federal EPA Radon Zone for GOGEBIC County: 2

Note: Zone 1 indoor average level > 4 pCi/L.

: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.

: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 49938

Number of sites tested: 5

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.800 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	1.120 pCi/L	100%	0%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.

Source: FEMA

Telephone: 877-336-2627

Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Wetlands Inventory Source: Department of Natural Resources

Telephone: 517-241-2254

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)

Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Water Well Data

Source: Department of Environmental Quality

Telephone: 517-335-9218

The data in this file was obtained from Wellogic, the Michigan Department of Environmental Quality Statewide Groundwater Database (SGWD). Wellogic contains approximately 425,000 water well records found within the State of Michigan, and although it represents the best available data, it cannot be considered a complete database of all the wells or well records in existence. Locations of verified municipal and private water well sites compiled from Michigan Department of Public Health, Water Well and Pump Records. Available in the following MI counties: Calhoun, Eaton, Genesee, Ingham, Jackson, Kalamazoo, Kent, Midland, Muskegon, Oakland, Ottawaw, Saginaw, St. Clair, Washtenaw.

OTHER STATE DATABASE INFORMATION

Michigan Oil and Gas Wells

Source: Department of Environmental Quality

Telephone: 517-241-1528

Locations of oil and gas wells are compiled from permit records on file at the Geological Survey Division (GSD),

Michigan Department of Natural Resources.

RADON

State Database: MI Radon

Source: Department of Environmental Quality

Telephone: 517-335-9551 Radon Test Results

Michigan Radon Test Results

Source: Department of Environmental Quality

Telephone: 517-335-8037

These results are from test kits distributed by the local health departments and used by

Michigan residents. There is no way of knowing whether the devices were used properly, whether there are duplicates (or repeat verification) test (i.e., more than one sample per home), etc.

Area Radon Information

Source: USGS

Telephone: 703-356-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency

(USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey.

The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at

private sources such as universities and research institutions.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

EPA Radon Zones Source: EPA

Telephone: 703-356-4020

Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor

radon levels.

OTHER

Airport Landing Facilities: Private and public use landing facilities

Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater

Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared

in 1975 by the United State Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX C AERIAL PHOTOGRAPHS

Proposed City of Ironwood Park

Not Reported Ironwood, MI 49938

Inquiry Number: 5337284.5

June 19, 2018

The EDR Aerial Photo Decade Package



EDR Aerial Photo Decade Package

06/19/18

Site Name: Client Name:

Proposed City of Ironwood Par Coleman Engineering Company

Not Reported 635 Circle Drive

Ironwood, MI 49938 Iron Mountain, MI 49801 EDR Inquiry # 5337284.5 Contact: Mike Gotham



Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

Search Results:

<u>Year</u>	<u>Scale</u>	<u>Details</u>	Source
2016	1"=500'	Flight Year: 2016	USDA/NAIP
2013	1"=500'	Flight Year: 2013	USDA/NAIP
2010	1"=500'	Flight Year: 2010	USDA/NAIP
2006	1"=500'	Flight Year: 2006	USDA/NAIP
1999	1"=500'	Acquisition Date: April 26, 1999	USGS/DOQQ
1992	1"=500'	Flight Date: May 05, 1992	NAPP
1980	1"=500'	Flight Date: June 16, 1980	ASCS
1975	1"=500'	Flight Date: May 05, 1975	USGS
1966	1"=500'	Flight Date: October 12, 1966	SHC
1953	1"=500'	Flight Date: July 27, 1953	USGS
1951	1"=500'	Flight Date: May 13, 1951	USGS
1938	1"=500'	Flight Date: September 04, 1938	USDA


When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.


Disclaimer - Copyright and Trademark Notice


This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.


EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.



















INQUIRY #: 5337284.5

YEAR: 1975











APPENDIX D SANBORN MAPS

Proposed City of Ironwood Park Not Reported Ironwood, MI 49938

Inquiry Number: 5337284.3

June 19, 2018

Certified Sanborn® Map Report



Certified Sanborn® Map Report

06/19/18

Site Name: Client Name:

Proposed City of Ironwood Parl Coleman Engineering Company

Not Reported

Ironwood, MI 49938 EDR Inquiry # 5337284.3

635 Circle Drive

Iron Mountain, MI 49801 Contact: Mike Gotham

The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Coleman Engineering Company were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 1F69-4CBE-9208 PO# **PrpsedParkIWD**

City of Ironwood - Lahti s **Project**

Maps Provided:

1946

1928

1921

1908

1898 1888



Sanborn® Library search results

Certification #: 1F69-4CBE-9208

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

Library of Congress



University Publications of America



▼ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Coleman Engineering Company (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2018 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

page 2

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.



1946 Source Sheets



Volume 1, Sheet 2 1946



Volume 1, Sheet 5 1946

1928 Source Sheets



Volume 1, Sheet 2 1928



Volume 1, Sheet 5 1928

1921 Source Sheets



Volume 1, Sheet 4 1921



Volume 1, Sheet 5 1921

1908 Source Sheets



Volume 1, Sheet 4 1908



Volume 1, Sheet 5 1908

Sanborn Sheet Key

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.



1898 Source Sheets



Volume 1, Sheet 4 1898



Volume 1, Sheet 5 1898

1888 Source Sheets




Volume 1, Sheet 4 1888





Volume 1, Sheet 2 1888













5337284 - 3


page 5
















5337284 - 3


page 6

























































5337284 - 3 page 9

APPENDIX E SITE PHOTOGRAPHS

LAHTI PROPERTY PHASE I ESA PHOTOS WERE TAKEN BY MICHAEL G. GOTHAM



Photo 1 – Northwesterly view of Lowell Street with the Subject Property on the left.



Photo 2 – Southeasterly view of Lowell Street from the northeastern corner of the Subject Property.



Photo 3 – Southwesterly view of the Subject Property and Floors N' Mor.



Photo 4 – Northwesterly view of the Subject Property with Lahti's in the background.



Photo 5 – Southeasterly view of the Subject Property and the adjacent parcel with McLeod Avenue and the Police Department in the background.



Photo 6 – Northerly view of the Subject Property facing the Lahti's, Constantini's Furniture, and the Historic Ironwood Theatre.






Photo 7 – Southeasterly view of the vegetated area of the Subject Property and the Police Department in the background.



Photo 8 – Northeasterly view of the McLeod Avenue with the Subject Property on the left and the Fabric Patch in the background.






Photo 9 – Northerly view of the Subject Property from the southern-most property corner.



Photo 10 – Northeasterly view of the northwestern-most property boundary.



Photo 11 – View of the footprint of the former Curry Hotel within the asphalt.




Photo 12 – Southwesterly view of Aurora Street with the Subject Property on the left.



Photo 13 – Northeasterly view of Lowell Street facing away from the Subject Property.



Photo 14 – Northerly view of Aurora Street facing away from the Subject Property.



APPENDIX F USER QUESTIONNAIRE

COLEMAN ENGINEERING COMPANY



200 E Ayer Street Ironwood, MI 49938

Phone: 906-932-5048 Fax: 906-932-3213

Phase I Environmental Site Assessment X3. User Questionnaire – Lahti Parcels ASTM Standard E 1527-13

Project Name: City Park Phase I ESA

Project Number: EC-190668

User: Scott Erickson, City Manager

Relation to Site: Prospective Purchaser

Part of Block 30, McLeod Ave, Lowell St., and Aurora St., City of

Site Address: Ironwood, Michigan

Phone Number: (906) 932-5050

Interview Completed

By: Michael G. Gotham, Environmental Scientist

Date and Time: August 21, 2019 @ 15:25 CST

QUESTIONNAIRE

1) Environmental cleanup liens that are filed or recorded against the site (40 CFR 312.25).

Are you aware of any environmental cleanup liens against the property that are filed or recorded under federal, tribal, state or local law?

2) Activity and land use limitations that are in place on the site or that have been filed or recorded in the registry (40 CFR 312.26).

Are you aware of any activity and use limitations (AULs) such as engineering controls, land use restrictions or institutional controls that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state or local law?

3) Specialized knowledge or experience of the person seeking to qualify for the LLP (40 CFR 312.28).

As the user of this ESA do you have any specialized knowledge or experience related to the property or nearby properties? For example, are you involved in the same line of business as the current or former occupants of the subject property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business?

No

4) Relationship of the purchase price to the fair market value of the property if it were not contaminated (40 CRF 312.29).

Does the purchase price being paid for this property reasonably reflect the fair market value of the property? If you conclude that there is a difference, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property?

Purchase price is based on the appraisal. There is no known contamination.

5) Commonly known or reasonable ascertainable information about the property (40 CFR 312.30).

Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example, as user,

- a. Do you know the past uses of the property?
 Yes, The Curry Motel and a Catholic Church
- b. Do you know of specific chemicals that are present or once were present at the property?
 No
- c. Do you know of spills or other chemical releases that have taken place at the property?
- d. Do you know of any environmental cleanups that have taken place at the property? No
- 6) The degree of obviousness of the presence of likely presence of contamination at the subject property, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31).

As the user of this ESA, based on your knowledge and experience related to the property, are there any obvious indicators that point to the presence or likely presence of contamination at the property?

No

APPENDIX G PROPERTY DESCRIPTION

GOGEBIC COUNTY, MICHIGAN GIS

Parcel Report: 52-22-332-120

Parcel Owner and Mailing Address

LAHTI, STEVE & FRANK 1321 N. LAWRENCE ST IRONWOOD, MI 49938

Property Address:

, MI 49938

Abreviated Legal Description

LOTS 1, 2, 3, & E 19 1/2 FT OF LOT 4 BLOCK 30 ORIGINAL PLAT

2019 Land Valuation	2019 Assessed Valuation
Land Value: \$22400	Property Class: 202
Land Assessed Value: \$13597	Principal Residence %: 0%
Acres: 0.45	Assessed Value: \$13597
Parcel Frontage: 140'	Taxable Value: \$11709

Parcel Frontage: 140' Taxable Value
Parcel Depth: 140' SEV: \$13597

2019 Structure Valuation

House Floor Area: 0 Sft Year Built: 0

Number of Bedrooms: 0 Bsmt Fin Living Area: Sft Number of Bath: 0 Building Class: 0

Number of Half Bath: 0 Garage Square Feet: 0 Sft

2018 Assessed Valuation Sale History

Property Class: 202 Principal Residence %: 0% Assessed Value: \$13987 Taxable Value: \$11435

2016 Sale History

2017 Sale History

2018 Sale History

Sale Date:
Sale Price:
Sale Price:
Sale Price:
Sale Price:

Sale Price:Sale Price:Sale Price:Sale Grantor:Sale Grantor:Sale Grantor:Sale Grantee:Sale Grantee:Sale Grantee:Sale Liber-Page:Sale Liber-Page:Sale Liber-Page:

DATA CURRENT AS OF MAY 29, 2019

GOGEBIC COUNTY, MICHIGAN GIS

Parcel Report: 52-22-332-070

Parcel Owner and Mailing Address

LAHTI, STEVE AND FRANK 1321 N. LAWRENCE ST IRONWOOD, MI 49938

Property Address:

W MCLEOD AVE , MI 49938

Abreviated Legal Description

LOTS 14, 15, 16, 17, AND THE WEST 12 FEET OF THE SOUTH 68 FT, AND THE NORTH 72 FT OF LOT 18, AND THE WESTERLY 12 FT OF THE NORTH 72 FT OF LOT 19, BLOCK 30. ORIGINAL PLAT

2019 Land Valuation		2019 Assessed Valuation		
Land Value: \$17019 Land Assessed Value: \$6861 Acres: 0.303 Parcel Frontage: 120' Parcel Depth: 110'		Property Class: 202 Principal Residence %: 0% Assessed Value: \$6861 Taxable Value: \$4526 SEV: \$6861		
2019 Structure Valuation				
House Floor Area: 0 Sft Number of Bedrooms: 0 Number of Bath: 0 Number of Half Bath: 0		Year Built: 0 Bsmt Fin Living Area: Sft Building Class: 0 Garage Square Feet: 0 Sft		
2018 Assessed Valuation		Sale History		
Property Class: 202 Principal Residence %: 0% Assessed Value: \$5000 Taxable Value: \$4420				
2016 Sale History	2017 Sale History	2018 Sale History		
Sale Date: Sale Price: Sale Grantor: Sale Grantee: Sale Liber-Page:	Sale Date: Sale Price: Sale Grantor: Sale Grantee: Sale Liber-Page:	Sale Date: Sale Price: Sale Grantor: Sale Grantee: Sale Liber-Page:		

DATA CURRENT AS OF MAY 29, 2019

APPENDIX H QUALIFICATIONS



MICHAEL G. GOTHAM, Environmental Scientist

Education: U.W. Stevens Point – B.S. Soil and Waste Resource Management, 2015

Experience: 2015 – Present Coleman Engineering Company

Certifications: 40-hour Hazwoper & 8-hour Annual Refreshers

2017 Enbridge Environmental Orientation US MLP

Liquid Pipelines Safety, US MLP Ground Disturbance Awareness

Confined Space Training 2017 OQ Pipeline Training Lead Sampling Technician

Asbestos Containing Materials Inspector

2017 MSHA 24 Hour New Miner Training (Surface Mining)

Mr. Gotham's experience with Coleman Engineering Company includes road construction projects as well as geotechnical drilling, soil investigation, and environmental projects. His roles have included Road Construction Inspector, Driller's Assistant, Environmental Scientist, and Project Manager. As a Construction Inspector, he was responsible for recording all pay items as well inspecting all erosion control items, earthwork, and traffic control items for the Wisconsin Department of Transportation projects. As a Driller's Assistant, Mr. Gotham assisted in geotechnical investigation borings, environmental borings, sediment borings, and boring ratio tests. As an Environmental Scientist, Mr. Gotham's roles included soil, groundwater, soil gas, and sediment sampling, providing soil descriptions, hazardous building material inspections – including but not limited to lead and asbestos, laboratory data analysis, and reporting. As a Project Manager, Mr. Gotham's responsibilities have included investigating the cause and magnitude of releases, oversight of Trade Contractors for site construction activities, and site safety. He has also conducted subsurface investigations which are included, but not limited to, stratigraphic descriptions, aquifer analysis through hydraulic conductivity testing (slug and pump tests), and well logging. Additionally, Mr. Gotham is skilled in operating ground penetrating radar and data Mr. Gotham has managed all phases of Environmental Site Assessments and Michigan Brownfield Redevelopment projects. He has been responsible for providing consultation and controlling budgets for private, state, and federal clients. Mr. Gotham's responsibilities involve client relations, planning, analysis, cost tracking, and project oversight.

viivii, ii ve. - consuming Engineers

Certifications: Licensed Professional Engineer – 1999, Wisconsin, #33833

Licensed Professional Engineer – 2015, Michigan, #63032 Certified Storm Water Management Operator, MI #C-15892 40-Hour Health and Safety Training for Hazardous Waste Sites

Annual 8-Hour Health and Safety Training Natural Gas PE Pipe Fusion Certification

State of Wisconsin – DSPS, Registered PECFA Consultant

Mr. Friberg provides a wide degree of technical guidance, design and management for a variety of projects. Areas of expertise and experience include: initial site investigations, feasibility reports, facility plan preparation, grant application preparation, contract administration, municipal water well exploration, water treatment, well building design, distribution system design, gravity sewer design, road design, site design, marina design, natural gas planning, surveying, construction inspection and documentation, AutoCAD drafting, soil and groundwater contamination investigations, limnological studies, wetland delineations, and solid waste site construction.

APPENDIX I LIMITATIONS

LIMITATIONS FOR PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORTS

- 1. In preparation of this report, Coleman Engineering Company (CEC) has relied on certain information provided by the parties referenced herein. Although there may have been some degree of overlap in the information provided by these various sources, we did not attempt to independently verify the accuracy or completeness of all information reviewed or received during the course of this site review.
- 2. Our conclusions regarding the site are based on observations of existing site conditions, our interpretation of available site history and site usage information. The findings are relevant to the dates of our site visit and should not be relied upon to represent conditions or information available at other dates. The findings and conclusions must be considered probabilities based on professional judgment concerning the significance of the limited data gathered during the course of the site review. Conclusions regarding the condition of the site do not represent a warranty that all areas within the site are of the same quality as may be inferred from observable site conditions and readily available site history and limited exploration program carried out as part of this review. Should additional information on environmental conditions at the site which is not contained in this report be obtained, such information should be brought to CEC's attention. We will evaluate such information and, on the basis of our evaluation, may modify the conclusions stated in the report.
- 3. Observations were made of the site and of structures on the site as indicated within the report. Where access to portions of the site or to structures on the site was unavailable or limited, CEC renders no opinion as to the presence of hazardous material or to the presence of indirect evidence relating to hazardous material in that portion of the site or structure. In addition, CEC renders no opinion as to the presence of hazardous material or to the presence of indirect evidence relating to hazardous material where direct observation of interior walls, floor, or ceiling of a structure on the site was obstructed by objects or coverings on or over these surfaces.
- 4. CEC did not perform testing or analyses to determine the presence or concentration of asbestos, lead-based paints, or radon or other naturally occurring materials, nor did it include an evaluation of latent conditions at the site or in the environment at the site.
- 5. No specific attempt was made to check the compliance of present or past owners or operators of the site with federal, state, or local laws and regulations, environmental or otherwise.
- 6. This report has been prepared for and is intended for the exclusive use of the City of Ironwood. The contents of this report should not be relied upon by any other party without the express written consent of CEC. However, CEC acknowledges that the report may be conveyed to the owner and lending institution associated with the prospective sale and/or lease of the site.

Environmental Justice (CEST and EA)

General requirements	Legislation	Regulation				
Determine if the project creates	Executive Order 12898					
adverse environmental impacts						
upon a low-income or minority						
community. If it does, engage						
the community in meaningful						
participation about mitigating						
the impacts or move the						
project.						
References						
https://www.hudexchange.info/environmental-review/environmental-justice						

HUD strongly encourages starting the Environmental Justice analysis only after all other laws and authorities, including Environmental Assessment factors if necessary, have been completed.

1. Were any adverse environmental impacts identified in any other compliance review portion of this project's total environmental review?

Yes \rightarrow Continue to Question 2.

No → Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below.

2. Were these adverse environmental impacts disproportionately high for low-income and/or minority communities?

Ye	S
E	Explain:
	→ Continue to Question 3. Provide any supporting documentation.
Ν	
1	Explain:

→ Continue to the Worksheet Summary and provide any supporting documentation.

3.	All adverse impacts should be mitigated. Explain in detail the proposed measures that must be implemented to mitigate for the impact or effect, including the timeline for implementation.
	Mitigation as follows will be implemented:
	→ Continue to Question 4.
	No mitigation is necessary.
	Explain why mitigation will not be made here:
	→ Continue to Question 4.
4.	Describe how the affected low-income or minority community was engaged or meaningfully involved in the decision on what mitigation actions, if any, will be taken.

ightarrow Continue to the Worksheet Summary and provide any supporting documentation.

Worksheet Summary

Compliance Determination

Provide a clear description of your determination and a synopsis of the information that it was based on, such as:

- Map panel numbers and dates
- Names of all consulted parties and relevant consultation dates
- Names of plans or reports and relevant page numbers
- Any additional requirements specific to your region

Phase I ESA completed and discovered no recognized environmental conditions associated with
project site; thus, no environmental impacts were identified that would impact population
subgroups.

Are formal compliance steps or mitigation required?

Yes

No

Flood Insurance (CEST and EA)

General requirements	Legislation	Regulation					
Certain types of federal financial assistance may	Flood Disaster	24 CFR 50.4(b)(1)					
not be used in floodplains unless the community	Protection Act of	and 24 CFR					
participates in National Flood Insurance Program	1973 as amended	58.6(a) and (b);					
and flood insurance is both obtained and	(42 USC 4001-4128)	24 CFR 55.1(b).					
maintained.							
Reference							
https://www.hudexchange.info/environmental-review/flood-insurance							

1.	Does	this	project	involve	financial	assistance	for	construction,	rehabilitation,	or
	acquisition of a mobile home, building, or insurable personal property?									
	\square No.	This	project d	oes not re	equire floo	d insurance	or is	excepted from	flood insurance.	\rightarrow

 \boxtimes Yes \rightarrow Continue to Question 2.

2. Provide a FEMA/FIRM map showing the site.

Continue to the Worksheet Summary.

The Federal Emergency Management Agency (FEMA) designates floodplains. The <u>FEMA Map Service Center</u> provides this information in the form of FEMA Flood Insurance Rate Maps (FIRMs). For projects in areas not mapped by FEMA, use the best available information to determine floodplain information. Include documentation, including a discussion of why this is the best available information for the site. Provide FEMA/FIRM floodplain zone designation, panel number, and date within your documentation.

Is the structure, part of the structure, or insurable property located in a FEMA-designated Special Flood Hazard Area?

3. Is the community participating in the National Flood Insurance Program *or* has less than one year passed since FEMA notification of Special Flood Hazards?

We the community is portional in the National Flood Incommunity


Ш	res, the community is participating in the National Flood insurance Program.
	For loans, loan insurance or loan guarantees, flood insurance coverage must be
	continued for the term of the loan. For grants and other non-loan forms of financia
	assistance, flood insurance coverage must be continued for the life of the building
	irrespective of the transfer of ownership. The amount of coverage must equal the tota
	project cost or the maximum coverage limit of the National Flood Insurance Program
	whichever is less

Provide a copy of the flood insurance policy declaration or a paid receipt for the current annual flood insurance premium and a copy of the application for flood insurance. → Continue to the Worksheet Summary.
 ☐Yes, less than one year has passed since FEMA notification of Special Flood Hazards. If less than one year has passed since notification of Special Flood Hazards, no flood Insurance is required. → Continue to the Worksheet Summary.
☐ No. The community is not participating, or its participation has been suspended. Federal assistance may not be used at this location. Cancel the project at this location.
Worksheet Summary Compliance Determination Provide a clear description of your determination and a synopsis of the information that it was based on, such as: • Map panel numbers and dates • Names of all consulted parties and relevant consultation dates • Names of plans or reports and relevant page numbers • Any additional requirements specific to your region
See attached map.
Are formal compliance steps or mitigation required? ☐ Yes
⊠ No



U.S. Fish and Wildlife Service Coastal Barrier Resources System

Ironwood CBRS Mapper



August 19, 2019

CBRS Units

Otherwise Protected Area

System Unit

This map is for general reference only. The Coastal Barrier Resources System (CBRS) boundaries depicted on this map are representations of the controlling CBRS boundaries, which are shown on the official maps, accessible at https://www.fws.gov/cbra/maps/index.html. All CBRS related data should be used in accordance with the layer metadata found on the CBRS Mapper website.

The CBRS Buffer Zone represents the area immediately adjacent to the CBRS boundary where users are advised to contact the Service for an official determination (http://www.fws.gov/cbra/Determinations.html) as to whether the property or project site is located "in" or "out" of the CBRS.

CBRS Units normally extend seaward out to the 20- or 30-foot bathymetric contour (depending on the location of the unit). The true seaward extent of the units is not shown in the CBRS mapper.

Coastal Barrier Resources (CEST and EA)

General requirements	Legislation	Regulation				
HUD financial assistance may not be	Coastal Barrier Resources Act					
used for most activities in units of	(CBRA) of 1982, as amended					
the Coastal Barrier Resources	by the Coastal Barrier					
System (CBRS). See 16 USC 3504 for	Improvement Act of 1990 (16					
limitations on federal expenditures	USC 3501)					
affecting the CBRS.						
References						
https://www.hudexchange.info/envir	https://www.hudexchange.info/environmental-review/coastal-barrier-resources					

Projects located in the following states must complete this form.

Alabama	Georgia	Massachusetts	New Jersey	Puerto Rico	Virgin Islands
Connecticut	Louisiana	Michigan	New York	Rhode Island	Virginia
Delaware	Maine	Minnesota	North Carolina	South Carolina	Wisconsin
Florida	Maryland	Mississippi	Ohio	Texas	

1. Is the project located in a CBRS Unit?

- Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide a map showing that the site is not within a CBRS Unit.
- \square Yes \rightarrow Continue to Question 2.

<u>Federal assistance for most activities may not be used at this location. You must either choose an alternate site or cancel the project.</u> In very rare cases, federal monies can be spent within CBRS units for certain exempted activities (e.g., a nature trail), after consultation with the Fish and Wildlife Service (FWS) (see <u>16 USC 3505</u> for exceptions to limitations on expenditures).

2. Indicate your selected course of action.

- After consultation with the FWS the project was given approval to continue
 - → Based on the response, the review is in compliance with this section. Continue to the Worksheet Summary below. Provide a map and documentation of a FWS approval.
- ☐ Project was not given approval

Project cannot proceed at this location.

Worksheet Summary

Compliance Determination

Provide a clear description of your determination and a synopsis of the information that it was based on, such as:

- Map panel numbers and dates
- Names of all consulted parties and relevant consultation dates
- Names of plans or reports and relevant page numbers
- Any additional requirements specific to your region

See attached map	0.			
Are formal compli	iance steps or miti	gation required?		
☐ Yes	•			
⊠ No				